

Accessibility Audit of the Record of Monuments and Places for County Longford

RMP Ref: LF-	002-002	Monument	Ritual Site - Holy Well				
Location/ Townland	Ballyduffy		National Grid Ref:	223543	E	296706	N
			RPS Ref				
			National Monument Ref				
Description	St. Patrick's Well / Tober Patrick. Modern concrete construction with field drain on one side & natural spring on the other.						
Ownership	Public	Date of Inspection	23/09/09	Inspected By	SMcG	Accessibility Rating	B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign for 'St. Patrick's Well' at the side of the road. (Ballinamuck to Legga road)
Visibility	Visible at end of grassy path
Intervisibility	
Road Access	Accessed from local road. (Lane leading to Lough Nabelwy from the Ballinamuck to Legga road)
Parking	No designated parking. Some space for parking along roadside.
Public Transport	
Approach Topography	Moderate slope downwards from road to well.

Approach Surface	Well-maintained grass path with grassed-over hardcore path along one side.	
Approach Safety	No noticeable hazards.	
Approach Width	>1.8m	Approach Gate width >800mm
Gate type	Field gate, easily opened.	
Site Topography	At end of path the degree of slope increases with modern concrete steps providing access to well.	
Site Paths	No paths at well - concrete steps lead to modern concrete platform at well.	
Paths Surfacing		
Paths Width	Steps c.1m width.	
Hazards	No railings at steps. A white powder (possibly lime?) was conspicuous on the ground in the vicinity of the well. No lighting at site.	
Maintenance	Well water appears clear and area of site is generally clean	
Condition of Monument		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>
	On-site Seating <input type="checkbox"/>	On-site Toilets <input type="checkbox"/>
On-site facilities	None	
Notes		

RMP Ref: LF-	002-006001	Monument	Ritual Site - Holy Well
Location/ Townland	Cornacullew	National Grid Ref:	220042 E 293128 N
		RPS Ref	
		National Monument Ref	
Description	Tober Patrick. Stone-lined well, c.2m in diameter, adjacent to holy tree LF-002-006004. Well and tree are separated from the graveyard (LF-002-006003) by a small stream. Three low steps lead to break in wall of well for access, while a further stone has been added to the interior as a step down when the water is at a low level. The newly laid path suggests that traditions associated with the well are still going strong.		
Ownership	Public	Date of Inspection	23/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Sign for 'Toberpatrick Cemetery' at junction of main road of Ballinamuck to Legga road.
Site Signs	Faded sign in cemetery providing information about stations for associated pilgrimage, but is currently illegible.
Visibility	Visible along side of road
Intervisibility	
Road Access	Local road runs alongside cemetery. (Lane leading to Lough Nabelwy from the Ballinamuck to Legga r
Parking	Parking space provided for c.5 cars
Public Transport	
Approach Topography	Slope in car-parking area
Approach Surface	Hardcore and gravel surface on parking area
Approach Safety	Free of hazards. Off-road parking is located at access points to graveyard and well
Approach Width	>1.8m
Approach Gate width	c.1m

<i>Gate type</i>	Gate leading to well from parking area.
<i>Site Topography</i>	Level ground at well and holy tree.
<i>Site Paths</i>	A level path leads from gate to well and holy tree.
<i>Paths Surfacing</i>	Pathway at well and holy tree is gravel-covered.
<i>Paths Width</i>	Pathway at well and holy tree is c.1.2 - 1.8m in width.
<i>Hazards</i>	No on-site lighting. Open well and adjacent stream may be considered a mild hazard.
<i>Maintenance</i>	Entire area is very well maintained.
<i>Condition of Monument</i>	Good. Holy well and holy tree are easily accessed by all.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	Holy well and holy tree are easily accessed by all.

RMP Ref: LF-	002-006002	Monument	Mound
Location/ Townland	Cornacullew	National Grid Ref:	220048 E 293125 N
		RPS Ref	
		National Monument Ref	
Description	Probably the raised ground on which the graveyard is situated.		
Ownership	Public	Date of Inspection	23/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Sign for 'Toberpatrick Cemetery' at junction of main road between Ballinamuck and Legga.
Site Signs	Faded sign in graveyard may have once provided information on site or associated pilgrimage, but is currently illegible.
Visibility	Visible along side of road
Intervisibility	
Road Access	Local road runs alongside cemetery. (Lane leading to Lough Nabelwy from the Ballinamuck to Legga r
Parking	Parking space provided for c.5 cars
Public Transport	
Approach Topography	Slope in car-parking area
Approach Surface	Hardcore and gravel surface on parking area
Approach Safety	Free of hazards. Off-road parking is located at access points to graveyard and well
Approach Width	>1.8m
Approach Gate width	gate to graveyard, c.1.5m; gate to w

Gate type	Gates leading to graveyard and well from parking area; another gate, coupled with a stile, gives direct access from road to graveyard, with step on the cemetery-side of the gate.
Site Topography	Level routes at well and holy tree. Steep slope up to graveyard from main gate and step up to graveyard from gate at roadside. The graveyard is located on a raised mound, so the ground slopes on all sides.
Site Paths	A level path leads from gate to well and holy tree. No paths exist between graves in graveyard and density of graves means some are only accessed by crossing other graves.
Paths Surfacing	Pathway at well and holy tree is gravel-covered; graveyard is generally grass covered.
Paths Width	Pathway at well and holy tree is c.1.2 - 1.8m in width.
Hazards	Uneven slope and low grave surrounds in graveyard may present slight hazards for children or those with unsure footing. No on-site lighting. Open well and adjacent stream may also be considered a mild hazard.
Maintenance	Entire area is very well maintained.
Condition of Monument	
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/> On-site Staff <input type="checkbox"/> On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	None.
Notes	The raised nature of the graveyard, and lack of paths therein do not allow for access by wheelchairs or buggies.

RMP Ref: LF-	002-006003	Monument	Graveyard				
Location/ Townland	Cornacullew		National Grid Ref:	220067	E	293157	N
			RPS Ref				
			National Monument Ref				
Description	Toberpatrick Cemetery. The graveyard is sub-oval in plan, located on a raised area of ground, with a sharp drop to the road on one side and the stream on the other. The graveyard is still in use, as evidenced by the presence of modern headstones interspersed among older graveslabs. Earliest burial marker consists of a small cross, dated 1688 (LF-002-006004). Separated by a small stream from Holy Well (LF-002-006001) and Holy Tree (LF-002-006005).						
Ownership	Public	Date of Inspection	23/09/09	Inspected By	SMcG	Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#48 Tubberpatrick Graveyard, Dromard. Limited wheelchair access. Limited parking spaces - not designated. No pathways. Public access (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Sign for 'Toberpatrick Cemetery' at junction of main road from Ballinamuck to Legga.
Site Signs	Faded sign at roadside gate may have once provided information on site or associated pilgrimage, but is currently illegible.
Visibility	Visible along side of road
Intervisibility	
Road Access	Local road runs alongside cemetery. (Lane leading to Lough Nabelwy from the Ballinamuck to Legga r
Parking	Parking space provided for c.5 cars
Public Transport	
Approach Topography	Slope in car-parking area
Approach Surface	Hardcore and gravel surface on parking area

Approach Safety	Free of hazards. Off-road parking is located at access points to graveyard and well	
Approach Width	>1.8m	Approach Gate width c.1.5m
Gate type	Gates leading to graveyard from parking area; another gate, coupled with a stile, gives direct access from road to graveyard, with steps on the cemetery-side of the gate.	
Site Topography	Steep slope up to graveyard from main gate and steps up to graveyard from gate at roadside. The graveyard is located on a raised mound, so the ground slopes on all sides.	
Site Paths	No paths exist between graves in graveyard and density of graves means some are only accessed by crossing other graves.	
Paths Surfacing	Graveyard is generally grass covered.	
Paths Width		
Hazards	Uneven slope and low grave surrounds in graveyard may present slight hazards for children or those with unsure footing. No on-site lighting.	
Maintenance	Entire area is very well maintained.	
Condition of Monument		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>
	On-site Seating <input type="checkbox"/>	On-site Toilets <input type="checkbox"/>
On-site facilities	None.	
Notes	The raised nature of the graveyard, and lack of paths therein do not allow for access by wheelchairs or buggies.	

RMP Ref: LF-	002-006004	Monument	Cross
Location/ Townland	Cornacullew	National Grid Ref:	220048 E 293125 N
		RPS Ref	
		National Monument Ref	
Description	Small cross, dated 1688, ex-situ in graveyard. May not be the correct cross as www.archaeology.ie website & NGR suggest it is adjacent to well & tree.		
Ownership	Public	Date of Inspection	23/09/09
		Inspected By	SMcG
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Sign for 'Toberpatrick Cemetery' at junction of main road from Ballinamuck to Legga.
Site Signs	Faded sign at roadside gate may have once provided information on site or associated pilgrimage, but is currently illegible.
Visibility	Visible along side of road. (Lane leading to Lough Nabelwy from the Ballinamuck to Legga road)
Intervisibility	
Road Access	Local road runs alongside cemetery
Parking	Parking space provided for c.5 cars
Public Transport	
Approach Topography	Slope in car-parking area
Approach Surface	Hardcore and gravel surface on parking area
Approach Safety	Free of hazards. Off-road parking is located at access points to graveyard and well
Approach Width	>1.8m
Approach Gate width	gate to graveyard, c.1.5m; gate to w

Gate type	Gates leading to graveyard and well from parking area; another gate, coupled with a stile, gives direct access from road to graveyard, with steps on the cemetery-side of the gate.
Site Topography	Level routes at well and holy tree. Steep slope up to graveyard from main gate and steps up to graveyard from gate at roadside. The graveyard is located on a raised mound, so the ground slopes on all sides.
Site Paths	A level path leads from gate to well and holy tree. No paths exist between graves in graveyard and density of graves means some are only accessed by crossing other graves.
Paths Surfacing	Pathway at well and holy tree is gravel-covered; graveyard is generally grass covered.
Paths Width	Pathway at well and holy tree is c.1.2 - 1.8m in width.
Hazards	Uneven slope and low grave surrounds in graveyard may present slight hazards for children or those with unsure footing. No on-site lighting. Open well and adjacent stream may also be considered a mild hazard.
Maintenance	Entire area is very well maintained.
Condition of Monument	
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/> On-site Staff <input type="checkbox"/> On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	None.
Notes	

RMP Ref: LF-	002-006005	Monument	Ritual Site - Holy Tree/Bush
Location/ Townland	Cornacullew	National Grid Ref:	220046 E 293128 N
		RPS Ref	
		National Monument Ref	
Description	Hawthorn tree adjacent to holy well (LF-002-006001), with rags, socks, handkerchiefs and scraps of plastic tied to branches. Separated from graveyard (LF-002-006003) by small stream.		
Ownership	Public	Date of Inspection	23/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Sign for 'Toberpatrick Cemetery' at junction of main road from Ballinamuck to Legga.
Site Signs	Faded sign in graveyard may have once provided information on site or associated pilgrimage, but is currently illegible.
Visibility	Visible along side of road. (Lane leading to Lough Nabelwy from the Ballinamuck to Legga road)
Intervisibility	
Road Access	Local road runs alongside cemetery
Parking	Parking space provided for c.5 cars
Public Transport	
Approach Topography	Slope in car-parking area
Approach Surface	Hardcore and gravel surface on parking area
Approach Safety	Free of hazards. Off-road parking is located at access points to graveyard and well
Approach Width	>1.8m
Approach Gate width	c.1m

<i>Gate type</i>	Gate leading tree and well from parking area
<i>Site Topography</i>	Level route at well and holy tree.
<i>Site Paths</i>	A level path leads from gate to well and holy tree.
<i>Paths Surfacing</i>	Pathway at well and holy tree is gravel-covered.
<i>Paths Width</i>	Pathway at well and holy tree is c.1.2 - 1.8m in width.
<i>Hazards</i>	No on-site lighting. Open well and adjacent stream may also be considered a mild hazard.
<i>Maintenance</i>	Entire area is very well maintained.
<i>Condition of Monument</i>	Holy well and holy tree are easily accessed by all.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	Holy well and holy tree are easily accessed by all.

RMP Ref: LF-	002-011001	Monument	Battlefield
Location/ Townland	Shanmullagh, Ballinamuck		National Grid Ref: 219139 <i>E</i> 290670 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Site of the Battle of Ballinamuck, 1798. Not counted as an RMP on the official www.archaeology.ie website.		
Ownership	Private	Date of Inspection	23/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Information sign in Ballinamuck village relating to sites associated with the Battle of Ballinamuck. Included in 'Woodland & Bog Walks in County Longford' (Longford Community Resources Ltd. Rural Social Scheme, 2008). J.P. Farrell, "History of County Longford". Dollard Printing House, Dublin, 1891 - pp. 161, 163, 164, 167, 262 & 263.
Local Sources Directions	Marked on map in 'Woodland & Bog Walks in County Longford' (Longford Community Resources Ltd. Rural Social Scheme, 2008).
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Ballinamuck heritage centre is included in historical places 'Around Longford Town' at http://www.goireland.com/longford/attractions-activities.htm . A short, descriptive paragraph is provided, but it does not provide information regarding accessibility. Ballinamuck heritage centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Signpost in Ballinamuck village to sites related to the battle.
Site Signs	Location of battlefield not signposted, but numerous commemorative plaques on funerary monument for the burials.
Visibility	
Intervisibility	
Road Access	Access via small country lane and across fields
Parking	Parking in Ballinamuck village and walking routes suggested from there, although none of these allow for access to the battlefield itself.
Public Transport	Public transport to Ballinamuck village only.
Approach Topography	

<i>Approach Surface</i>		
<i>Approach Safety</i>		
<i>Approach Width</i>		<i>Approach Gate width</i>
<i>Gate type</i>		
<i>Site Topography</i>		
<i>Site Paths</i>		
<i>Paths Surfacing</i>		
<i>Paths Width</i>		
<i>Hazards</i>		
<i>Maintenance</i>		
<i>Condition of Monument</i>		
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>		
<i>Notes</i>		

RMP Ref: LF-	002-011002	Monument	Burial
Location/ Townland	Shanmullagh		National Grid Ref: 219048 E 290677 N
		RPS Ref	
		National Monument Ref	
Description	Not RMP. SMR no only on website. Monument to 'Croppies Graves 1798' at site, consisting of a masonry and concrete rectangular structure with a metal cross and 2 plaques.		
Ownership	Private	Date of Inspection	23/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Included in 'Woodland & Bog Walks in County Longford' (Longford Community Resources Ltd. Rural Social Scheme, 2008). J.P. Farrell, "History of County Longford". Dollard Printing House, Dublin, 1891 - pp. 161, 163, 164, 167, 262 & 263.
Local Sources Directions	Marked on map in 'Woodland & Bog Walks in County Longford' (Longford Community Resources Ltd. Rural Social Scheme, 2008).
Graveyard Survey	Not wheelchair accessible. No designated parking. Privately owned (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Ballinamuck heritage centre is included in historical places 'Around Longford Town' at http://www.goireland.com/longford/attractions-activities.htm . A short, descriptive paragraph is provided, but it does not provide information regarding accessibility. Ballinamuck heritage centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	

<i>Approach Width</i>	<input type="text"/>	<i>Approach Gate width</i>	<input type="text"/>
<i>Gate type</i>	<input type="text"/>		
<i>Site Topography</i>	<input type="text"/>		
<i>Site Paths</i>	<input type="text"/>		
<i>Paths Surfacing</i>	<input type="text"/>		
<i>Paths Width</i>	<input type="text"/>		
<i>Hazards</i>	<input type="text"/>		
<i>Maintenance</i>	<input type="text"/>		
<i>Condition of Monument</i>	<input type="text"/>		
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>	<i>On-site Staff</i> <input type="checkbox"/>	<i>On-site Seating</i> <input type="checkbox"/>
<i>On-site facilities</i>	<input type="text"/>		
<i>Notes</i>	<input type="text"/>		

RMP Ref: LF-	002-011003	Monument	Burial
Location/ Townland	Shanmullagh		National Grid Ref: 219063 E 290628 N
		RPS Ref	
		National Monument Ref	
Description	Not RMP. SMR no. only. Exact location uncertain.		
Ownership		Date of Inspection	
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	Not wheelchair accessible. No designated parking. Privately owned (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Ballinamuck heritage centre is included in historical places 'Around Longford Town' at http://www.goireland.com/longford/attractions-activities.htm . A short, descriptive paragraph is provided, but it does not provide information regarding accessibility. Ballinamuck heritage centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	002-011004	Monument	Burial
Location/ Townland	Shanmullagh		National Grid Ref: 219624 <i>E</i> 290565 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	SMR no. on-line but not in RMP Exact location uncertain.		
Ownership		Date of Inspection	
		Inspected By	
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	Not wheelchair accessible. No designated parking. Privately owned (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Ballinamuck heritage centre is included in historical places 'Around Longford Town' at http://www.goireland.com/longford/attractions-activities.htm . A short, descriptive paragraph is provided, but it does not provide information regarding accessibility. Ballinamuck heritage centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	002-011005	Monument	Burial
Location/ Townland	Shanmullagh		National Grid Ref: 219212 <i>E</i> 290537 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Location not visible on ground. Listed in website as SMR no only - not RMP.		
Ownership	Private	Date of Inspection	23/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	Not wheelchair accessible. No designated parking. Privately owned (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Ballinamuck heritage centre is included in historical places 'Around Longford Town' at http://www.goireland.com/longford/attractions-activities.htm . A short, descriptive paragraph is provided, but it does not provide information regarding accessibility. Ballinamuck heritage centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	005-007	Monument	Megalithic Tomb - Portal Tomb
Location/ Townland	Melkagh	National Grid Ref:	216140 E 287932 N
		RPS Ref	
		National Monument Ref	
Description	'Dermot & Grania's Bed'. No longer extant. Site consists of a sub-circular are of slightly raised ground with bushes, trees and overgrowth. Some smaller stones were apparent, as well as a linear earthen mound. Some large stone slabs were noted along the field boundary with the road.		
Ownership	Private	Date of Inspection	23/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Adjacent to main road from Drumlish.
Parking	
Public Transport	
Approach Topography	Even ground but open field.
Approach Surface	Rough pasture
Approach Safety	Field under pasture, so may contain cattle
Approach Width	
	Approach Gate width
Gate type	Rusted farm gate, not easily opened.

<i>Site Topography</i>	Some undulations and uneven surface at site of monument
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	uneven footing, overgrowth in area of site. Not enclosed from field which may contain farm animals.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Non-extant
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	No monument evident on ground.

RMP Ref: LF-	005-010001	Monument	Church possible
Location/ Townland	Kilmahon	National Grid Ref:	219073 E 286395 N
		RPS Ref	
		National Monument Ref	
Description	No upstanding remains evident. No upstanding remains of church within graveyard, although circular shape of graveyard suggests it was originally an early medieval foundation.		
Ownership	Public	Date of Inspection	23/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Sign for 'Kilmahon Cemetery' on main road (R198)
Site Signs	Sign for 'Kilmahon Cemetery' at entrance to graveyard
Visibility	
Intervisibility	
Road Access	Adjacent to local road.
Parking	New carpark established within boundary of graveyard
Public Transport	
Approach Topography	Access from carpark, level ground.
Approach Surface	Tarmacadam surface on carpark
Approach Safety	Free from hazards
Approach Width	>1.8m
	Approach Gate width Gate leading from main road to grav
Gate type	Double gate leading from carpark to graveyard; additional gate from main road with a stile at one side.

<i>Site Topography</i>	Generally level ground in graveyard, with a slight rise in centre
<i>Site Paths</i>	Two pathways maintained through grass, with open area in front of newly installed altar.
<i>Paths Surfacing</i>	Small area of hardcore leading from carpark into graveyard and area of concrete at roadside gate. Otherwise site is grass-covered.
<i>Paths Width</i>	>1.8m
<i>Hazards</i>	No apparent hazards. No lighting on-site.
<i>Maintenance</i>	Neat and tidy; paths well-maintained. Grass elsewhere in graveyard may require more frequent cutting.
<i>Condition of Monument</i>	Non-extant
<i>Child friendly</i> <input checked="" type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input checked="" type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	2 benches installed, at either side of altar.
<i>Notes</i>	No upstanding remains of church within graveyard, although circular shape of graveyard suggests it was originally an early medieval foundation.

RMP Ref: LF-	005-010002	Monument	Graveyard
Location/ Townland	Kilmahon	National Grid Ref:	219073 E 286395 N
		RPS Ref	
		National Monument Ref	
Description	<p>Although originally circular, recent works have straightened off one side to create a car park and new entrance. Identifiable graves are mainly 19th & 20th century, although occasional low stones and unengraved markers may be earlier. The graveyard is surrounded by stone walls with coniferous trees along the inside of the wall on two sides.</p> <p>The circular shape of graveyard suggests it was originally an early medieval foundation.</p>		
Ownership	Public	Date of Inspection	23/09/09
		Inspected By	SMcG
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	<p>#53 Kilmahon Graveyard, Drumlish & Ballinamuck. Wheelchair accessible to entrance area only. No designated parking space. Public access (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836.</p>
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Sign for 'Kilmahon Cemetery' on main road
Site Signs	Sign for 'Kilmahon Cemetery' at entrance to graveyard
Visibility	
Intervisibility	
Road Access	Adjacent to local road
Parking	New carpark established within boundary of graveyard
Public Transport	
Approach Topography	Access from carpark, level ground.
Approach Surface	Tarmacadam surface on carpark
Approach Safety	Free from hazards

Approach Width	>1.8m	Approach Gate width	Gate leading from main road to grav
Gate type	Double gate leading from carpark to graveyard; additional gate from main road with a stile at one side.		
Site Topography	Generally level ground in graveyard, with a slight rise in centre		
Site Paths	Two pathways maintained through grass, with open area in front of newly installed altar.		
Paths Surfacing	Small area of hardcore leading from carpark into graveyard and area of concrete at roadside gate. Otherwise site is grass-covered.		
Paths Width	>1.8m		
Hazards	No apparent hazards. No lighting on-site		
Maintenance	Neat and tidy; paths well-maintained. Grass elsewhere in graveyard may require more frequent cutting.		
Condition of Monument	Graveyard still in use		
Child friendly <input checked="" type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input checked="" type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	2 benches installed, at either side of alter.		
Notes	The circular shape of graveyard suggests it was originally an early medieval foundation.		

RMP Ref: LF-	005-016	Monument	Ritual Site - Holy Well
Location/ Townland	Cartrongolan	National Grid Ref:	217372 E 284049 N
		RPS Ref	
		National Monument Ref	
Description	St. Patrick's Well. Well is enclosed by a modern concrete construction, surmounted with a statue of St. Patrick. A rose bush to the rear of the well acts as a holy bush, with rags and other scraps tied to it (not recorded in the RMP), as are modern Stations of the Cross.		
Ownership	Public	Date of Inspection	23/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign at site, not at roadside entrance.
Visibility	Visible from roadside
Intervisibility	
Road Access	Accessed from small country road, then right-of-way through field.
Parking	
Public Transport	
Approach Topography	Ground slopes upwards from road to side.
Approach Surface	Loose hardcore path, grassed-over in places
Approach Safety	Access path is not fenced off from field in which farm animals are grazing
Approach Width	0.8 - 2m
	Approach Gate width Gate at well is c.0.8m
Gate type	Wrought iron 'kissing gate' at roadside - not accessible for wheelchairs or buggies. Easily opened

	gate at well itself.
<i>Site Topography</i>	Uneven with steps to rear of well.
<i>Site Paths</i>	Path in front of well and steps to rear of well and holy bush/tree.
<i>Paths Surfacing</i>	Concrete path in front of well; steps at rear of well also concrete.
<i>Paths Width</i>	c.1.8m at front of well and c.1.2m at rear - in area of stations of the cross.
<i>Hazards</i>	No visible hazards. No on-site lighting.
<i>Maintenance</i>	Well-maintained.
<i>Condition of Monument</i>	Modern surrounds.
<i>Child friendly</i> <input checked="" type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	No access for wheelchairs or buggies through access gate at road. Access pathway is also not suitable for wheelchair users.

RMP Ref: LF-	005-017	Monument	Megalithic Tomb - Passage Tomb possible		
Location/ Townland	Corneddán, Dooroc		National Grid Ref:	218772 E	284214 N
			RPS Ref		
			National Monument Ref		
Description	Largest of 3 cairns, situated at the summit of Corn Hill. A trigonometrical station has been fixed at the top of the cairn. An RTE booster mast and associated complex is situated immediately to the southeast of the cairn. Located within plantation coniferous forest.				
Ownership	Public/Private	Date of Inspection	23/09/09	Inspected By	SMcG
				Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included under 'Cairn Hill' in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	Road signs for Corn Hill, not specifically for monument.
Site Signs	
Visibility	Visible with trigonometric station on top, from access road through forest.
Intervisibility	Intervisible with one of the smaller cairn (LF-005-018). Any previous intervisibility with other sites is bl
Road Access	Forest access laneway leading from road (L1031). However, this is not open to casual traffic and the
Parking	Parking for a maximum of 2 cars at bottom of approach lane.
Public Transport	
Approach Topography	Steep incline up to summit of hill - area around communications mast has been flattened.
Approach Surface	Approach lane has tarred surface.
Approach Safety	No apparent hazards. Care would have to be taken if forest works were on-going or if forestry-related traffic was present.
Approach Width	>1.8m wide
Approach Gate width	>800mm

<i>Gate type</i>	Wide gate at bottom of access road, but locked. Access may be gained by block stiles at either side of gate.
<i>Site Topography</i>	Level area around communications mast, otherwise uneven, heath-covered ground.
<i>Site Paths</i>	No path around or between monuments
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Presence of RTE booster mast; possible presence of forest-related machinery at times. Uneven footing. Cairns are constructed of loose stone and any attempts to climb on them can result in injury and also damage to the monument.
<i>Maintenance</i>	Not maintained.
<i>Condition of Monument</i>	Partly damaged by presence of trigonometrical station on the top.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	May benefit from information signs explaining monument and cautioning against climbing on the monument.

RMP Ref: LF-	005-018	Monument	Cairn
Location/ Townland	Corneddán, Dooroc		National Grid Ref: 218584 E 284145 N
		RPS Ref	
		National Monument Ref	
Description	Located c.50m to the west of the main cairn (LF005-017) and almost completely obscured by heather and bogland plants. Stones are apparent in a circular mound with some protruding from the heather.		
Ownership	Public	Date of Inspection	23/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included under 'Cairn Hill' in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	Road signs for Corn Hill, not specifically for monument.
Site Signs	
Visibility	Visible with trigonometric station on top, from access road through forest.
Intervisibility	Intervisible with one of the smaller cairn (LF005-017). Any previous intervisibility with other sites is blo
Road Access	Forest access laneway leading from road (L1031). However, this is not open to casual traffic and the
Parking	Parking for a maximum of 2 cars at bottom of approach lane.
Public Transport	
Approach Topography	Steep incline up to summit of hill - area around communications mast has been flattened.
Approach Surface	Approach lane has tarred surface.
Approach Safety	Care would have to be taken if forest works were on-going or if forestry-related traffic was present. Uneven footing with undergrowth away from main laneway.
Approach Width	>1.8m wide
Approach Gate width	>800mm

<i>Gate type</i>	Wide gate at bottom of access road, but locked. Access may be gained by block stiles at either side of gate.
<i>Site Topography</i>	Level area around communications mast, otherwise uneven, heath-covered ground.
<i>Site Paths</i>	No path around or between monuments
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Presence of RTE booster mast; possible presence of forest-related machinery at times. Uneven footing. Cairns are constructed of loose stone and any attempts to climb on them can result in injury and also damage to the monument.
<i>Maintenance</i>	Not maintained.
<i>Condition of Monument</i>	Largely obscured by overgrowth.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	005-020	Monument	Cairn
Location/ Townland	Corneddan, Dooroc		National Grid Ref: <input type="text"/> E <input type="text"/> N
		RPS Ref	<input type="text"/>
		National Monument Ref	<input type="text"/>
Description	Not considered an RMP on www.archaeology.ie website - SMR number only. Exact location not recorded. Located on the ground as a small cairn, some 120m to the west of LF005-018, on the opposite side of a field boundary. A T-shaped trench cut through the possible cairn suggests it may have been recently excavated.		
Ownership	Public/Private	Date of Inspection	23/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to Corn Hill included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included under 'Cairn Hill' in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	Road signs for Corn Hill, not specifically for monument.
Site Signs	
Visibility	
Intervisibility	
Road Access	Forest access laneway leading from road (L1031). However, this is not open to casual traffic and the
Parking	Parking for a maximum of 2 cars at bottom of approach lane.
Public Transport	
Approach Topography	Steep incline up to summit of hill - area around communications mast has been flattened.
Approach Surface	Approach lane has tarred surface; elsewhere ground is uneven with heather and undergrowth
Approach Safety	Care would have to be taken if forest works were on-going or if forestry-related traffic was present. Uneven footing with undergrowth away from main laneway.
Approach Width	>1.8m wide
Approach Gate width	>800mm

<i>Gate type</i>	Wide gate at bottom of access road, but locked. Access may be gained by block stiles at either side of gate.
<i>Site Topography</i>	Level area around communications mast, otherwise uneven, heath-covered ground.
<i>Site Paths</i>	No path around or between monuments
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Presence of RTE booster mast; possible presence of forest-related machinery at times. Uneven footing. Cairns are constructed of loose stone and any attempts to climb on them can result in injury and also damage to the monument.
<i>Maintenance</i>	Not maintained.
<i>Condition of Monument</i>	Disturbed
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	006-004	Monument	Megalithic Tomb - Portal Tomb
Location/ Townland	Cleenrah	National Grid Ref:	226622 E 289766 N
		RPS Ref	
		National Monument Ref	
Description	Portal tomb with 4 lintel stones and a very large capstone. A narrow entrance leads to a small internal chamber. Small stones cover the base of the interior of the tomb.		
Ownership	Private	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from very narrow lane, accessed off L1043, from Aughnacliff to Lough Gowna.
Intervisibility	
Road Access	
Parking	No designated parking. Very limited parking opportunity along laneway.
Public Transport	
Approach Topography	Mildly undulating
Approach Surface	Pasture-land.
Approach Safety	No visible hazards - laneway is narrow, with little opportunity for cars to pass.
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Fairly level in immediate surroundings of monument
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	None
<i>Condition of Monument</i>	In good condition. However, people should be discouraged from climbing in and on the monument.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	On private land so permission required before visiting.

RMP Ref: LF-	006-017	Monument	Megalithic Tomb - Portal Tomb
Location/ Townland	Aghnacliff (aka Aghnacliffe)		National Grid Ref: 226340 <i>E</i> 288690 <i>N</i>
		RPS Ref	
		National Monument Ref	????
Description	Aghnacliff / Aghnacliffe Dolmen. Portal tomb with 2 large capstones - the upper of which is of particularly impressive proportions. Part of lintel chamber absent, but capstones appear stable.		
Ownership	Public?	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	B/C

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	Sign for 'Dolmen' at roadside in Aghnacliff village
Site Signs	Only a sign indicating that monument is under state care
Visibility	Not visible unless approaching the monument
Intervisibility	
Road Access	Not adjacent to road, L1042. Accessed by right-of-way across two fields.
Parking	No designated parking. Roadside parking is possible
Public Transport	Public transport to Aghnacliff village
Approach Topography	Right of way through fields. Initially upslope, a double gate and steps down lead to a second field where the ground slopes steeply down to the monument.
Approach Surface	Grass with uneven footing due to use of field by cattle. Concrete steps between fields.
Approach Safety	Possible presence of cattle in fields.
Approach Width	Open fields. Steps c.1.2m wide. Approach Gate width Smaller gates c.1.2m; Field gate c.

<i>Gate type</i>	Initial field gate locked. Gates between fields are spring-loaded, thus easily opened.
<i>Site Topography</i>	Ground slopes down to monument, accessed by concrete steps, but levels out in vicinity of monument itself.
<i>Site Paths</i>	No paths. Open grassy field
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	None
<i>Condition of Monument</i>	In good condition
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input checked="" type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	006-021	Monument	Ringfort - Rath
Location/ Townland	Larkfield	National Grid Ref:	229943 E 288066 N
		RPS Ref	
		National Monument Ref	640
Description	National monument in state care. Univallate bank and ditch with an entrance in the east.		
Ownership	Private	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Only visible on approach through field
Intervisibility	
Road Access	Access via farm access-lane only
Parking	No designated parking
Public Transport	
Approach Topography	Gentle uphill slope
Approach Surface	Grass-covered, but muddy
Approach Safety	Very very wet, muddy ground in immediate vicinity of field gate.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	By nature undulating across bank and ditch. Trees growing around monument
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Electric fencing around monument to exclude cattle. Uneven footing in wooded area.
<i>Maintenance</i>	None. Some modern dumping of rubbish in ditch
<i>Condition of Monument</i>	Overgrown in places.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	Monument on private lands and not accessible to general public. 'Private' signs up.

RMP Ref: LF-	006-025001	Monument	Ritual Site - Holy Well
Location/ Townland	Toome (Granard By.)	National Grid Ref:	233511 E 288118 N
		RPS Ref	
		National Monument Ref	
Description	St. Patrick's Well. Rectangular well. Saint's stone (LF006-025002) at entrance of holy well, holy tree (LF006-025003) to rear of well. Area of monuments fenced off from rest of field.		
Ownership	Public - uncertain	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Access through private land.
Parking	No designated parking.
Public Transport	
Approach Topography	Some steeply sloping sections along approach, including a steep, narrow path downhill to monument.
Approach Surface	Pasture, generally muddy. Loose, stony path for part of approach
Approach Safety	Barbed wire fence and wooden plank at pallet gate may be hazardous.
Approach Width	
	Approach Gate width
Gate type	Field gates and wooden stiles. Pallet in use as gate at monument itself.

<i>Site Topography</i>	Area of monuments appears marshy and overgrown
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Open drain near well, partially hidden by overgrowth. Barbed wire fencing around monument.
<i>Maintenance</i>	None
<i>Condition of Monument</i>	Partly overgrown, otherwise clean
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	006-025002	Monument	Ritual Site - Holy/Saint's Stone
Location/ Townland	Toome (Granard By.)	National Grid Ref:	233507 E 288120 N
		RPS Ref	
		National Monument Ref	
Description	Stone located at access point of holy well (LF006-025001) with two shallow depressions which are said to represent St. Patrick's kneeprints.		
Ownership	Public-uncertain.	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Access through private land.
Parking	No designated parking.
Public Transport	
Approach Topography	Some steeply sloping sections along approach, including a steep, narrow path downhill to monument.
Approach Surface	Pasture, generally muddy. Loose, stony path for part of approach
Approach Safety	Barbed wire fence and wooden plank at pallet gate may be hazardous.
Approach Width	
	Approach Gate width
Gate type	Field gates and wooden stiles. Pallet in use as gate at monument itself.

<i>Site Topography</i>	Area of monuments appears marshy and overgrown
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Open drain near well, partially hidden by overgrowth. Barbed wire fencing around monument.
<i>Maintenance</i>	None
<i>Condition of Monument</i>	Partly overgrown, otherwise clean
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	006-025003	Monument	Ritual Site - Holy Tree/Bush
Location/ Townland	Toome (Granard By.)	National Grid Ref:	233512 E 288116 N
		RPS Ref	
		National Monument Ref	
Description	Hawthorn bush to which numerous rags have been tied. Located at rear of holy well (LF006-025001).		
Ownership	Public???	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Access through private land.
Parking	No designated parking.
Public Transport	
Approach Topography	Some steeply sloping sections along approach, including a steep, narrow path downhill to monument.
Approach Surface	Pasture, generally muddy. Loose, stony path for part of approach
Approach Safety	Barbed wire fence and wooden plank at pallet gate may be hazardous.
Approach Width	
	Approach Gate width
Gate type	Field gates and wooden stiles. Pallet in use as gate at monument itself.

<i>Site Topography</i>	Area of monuments appears marshy and overgrown
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Open drain near well, partially hidden by overgrowth. Barbed wire fencing around monument.
<i>Maintenance</i>	None
<i>Condition of Monument</i>	Partly overgrown, otherwise clean
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	006-031	Monument	Ringfort - Rath
Location/ Townland	Sonnagh	National Grid Ref:	226363 E 286855 N
		RPS Ref	
		National Monument Ref	598
Description	Large bivallate enclosure with double bank and ditch apparent. Very overgrown with brambles, gorse and bracken. National Monument sign located on one side. No fence to separate monument from grazing animals and in places bank has been damaged by cattle.		
Ownership	Public	Date of Inspection	
		Inspected By	
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	No National Monument sign present.
Visibility	Although within view of road, level of overgrowth inhibits visibility of monument
Intervisibility	Monuments on Inchmore islands are visible
Road Access	Access from small road
Parking	No designated parking
Public Transport	
Approach Topography	Gentle slope in field.
Approach Surface	Pasture
Approach Safety	Cattle may be present.
Approach Width	No path present. Approach Gate width >800m
Gate type	Field gate, damaged and hanging off its hinge.

<i>Site Topography</i>	Heavily overgrown. Banks and ditches quite steep and largely hidden in overgrowth
<i>Site Paths</i>	Areas of cleared vegetation within enclosure - no true paths
<i>Paths Surfacing</i>	Grass
<i>Paths Width</i>	
<i>Hazards</i>	Heavily overgrown, with overgrowth masking limits of ditches in places.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Heavily overgrown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	006-032001	Monument	Graveyard
Location/ Townland	Inchmore Island	National Grid Ref:	228512 E 286031 N
		RPS Ref	
		National Monument Ref	
Description	Sub-rectangular graveyard close to western shore of island, containing remains of abbey and church.		
Ownership	Private	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	On information board in Aghnacliffe village.
Local Sources Directions	
Graveyard Survey	#43 Inchmore Island graveyard, Colmcille. Currently closed; public ownership; no wheelchair access (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from numerous parts of shore
Intervisibility	
Road Access	Access to slipway from minor local road. Access to island by boat only.
Parking	Carpark located at slipway in Dring
Public Transport	
Approach Topography	Ground slopes upwards from shore to monuments
Approach Surface	Rough grass and rushes
Approach Safety	Open lake water to get to island.
Approach Width	No set paths
Approach Gate width	c.1.4m

<i>Gate type</i>	Entry to interior of graveyard via a stile with one step on the outside and three steep steps on the inside.
<i>Site Topography</i>	Steep step up to interior. Interior itself is overgrown with weeds.
<i>Site Paths</i>	No paths present
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Overgrowth conceals some low stones and grave markers. Nettles and thistles present across site.
<i>Maintenance</i>	None
<i>Condition of Monument</i>	Largely overgrown.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None, but toilets and picnic area at Dring slipway.
<i>Notes</i>	Location of monuments on island restricts accessibility.

RMP Ref: LF-	006-032002	Monument	Religious House - Augustinian Canons				
Location/ Townland	Inchmore Island		National Grid Ref:	228500	E	286043	N
			RPS Ref				
			National Monument Ref				
Description	A single masonry wall of the Abbey survives, with window opes.						
Ownership	Private	Date of Inspection	20/10/09	Inspected By	SMcG	Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs			
Site Signs			
Visibility	Visible from numerous parts of shore		
Intervisibility			
Road Access	Access to slipway from minor local road. Access to island by boat only.		
Parking	Carpark located at slipway in Dring		
Public Transport			
Approach Topography	Ground slopes upwards from shore to monuments		
Approach Surface	Rough grass and rushes		
Approach Safety	Open lake water to get to island.		
Approach Width	No set paths	Approach Gate width	c.1.4m
Gate type	Entry to interior of graveyard via a stile with one step on the outside and three steep steps on the		

	inside.
<i>Site Topography</i>	Steep step up to interior. Interior itself is overgrown with weeds.
<i>Site Paths</i>	No paths present
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Overgrowth conceals some low stones and grave markers. Nettles and thistles present.
<i>Maintenance</i>	None
<i>Condition of Monument</i>	Partly overgrown.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None, but toilets and picnic area at Dring slipway.
<i>Notes</i>	Location of monuments on island restricts accessibility.

RMP Ref: LF-	006-032003	Monument	Church
Location/ Townland	Inchmore Island	National Grid Ref:	228526 E 286000 N
		RPS Ref	
		National Monument Ref	
Description	One upstanding wall and a square bell tower are evident within the graveyard (LF066-032001), with window opes apparent. Access to tower through a low door. A small sub-rectangular stone foundation is located outside the walls of the graveyard, near the church.		
Ownership	Private	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from numerous parts of shore
Intervisibility	
Road Access	Access to slipway from minor local road. Access to island by boat only.
Parking	Carpark located at slipway in Dring
Public Transport	
Approach Topography	Ground slopes upwards from shore to monuments
Approach Surface	Rough grass and rushes
Approach Safety	Open lake water to get to island.
Approach Width	No set paths Approach Gate width c.1.4m
Gate type	Entry to interior of graveyard via a stile with one step on the outside and three steep steps on the

	inside.
<i>Site Topography</i>	Steep step up to interior. Interior itself is overgrown with weeds.
<i>Site Paths</i>	No paths present
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Overgrowth conceals some low stones and grave markers. Nettles and thistles present.
<i>Maintenance</i>	None
<i>Condition of Monument</i>	Partly overgrown.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None, but toilets and picnic area at Dring slipway.
<i>Notes</i>	Location of monuments on island restricts accessibility.

RMP Ref: LF-	006-032004	Monument	Architectural Fragment(s)
Location/ Townland	Inchmore Island	National Grid Ref:	228521 E 286026 N
		RPS Ref	
		National Monument Ref	
Description	A number of pillars and architectural fragments have been used as grave markers. It was uncertain as to which of these the RMP refers.		
Ownership	Private	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from numerous parts of shore
Intervisibility	
Road Access	Access to slipway from minor local road. Access to island by boat only.
Parking	Carpark located at slipway in Dring
Public Transport	
Approach Topography	Ground slopes upwards from shore to monuments
Approach Surface	Rough grass and rushes
Approach Safety	Open lake water to get to island.
Approach Width	No set paths Approach Gate width c.1.4m
Gate type	Entry to interior of graveyard via a stile with one step on the outside and three steep steps on the

	inside.
<i>Site Topography</i>	Steep step up to interior. Interior itself is overgrown with weeds.
<i>Site Paths</i>	No paths present
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Overgrowth conceals some low stones and grave markers. Nettles and thistles present.
<i>Maintenance</i>	None
<i>Condition of Monument</i>	Partly overgrown.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None, but toilets and picnic area at Dring slipway.
<i>Notes</i>	Location of monuments on island restricts accessibility.

RMP Ref: LF-	006-033	Monument	Ritual Site - Holy/Saint's Stone
Location/ Townland	Inchmore Island	National Grid Ref:	228584 E 285908 N
		RPS Ref	
		National Monument Ref	
Description	Located to the southeast of the graveyard in an area of rushes, close to the shore. Two stones situated side-by-side, one of which has a cross inscribed. The second stone has a shallow depression, said to be a saint's kneepoint.		
Ownership	Private	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from numerous parts of shore
Intervisibility	
Road Access	Access to slipway from minor local road. Access to island by boat only.
Parking	Carpark located at slipway in Dring
Public Transport	
Approach Topography	Ground slopes upwards from shore to monuments
Approach Surface	Rough grass and rushes
Approach Safety	Open lake water to get to island.
Approach Width	No set paths Approach Gate width c.1.4m
Gate type	Entry to interior of graveyard via a stile with one step on the outside and three steep steps on the

	inside.
<i>Site Topography</i>	Steep step up to interior. Interior itself is overgrown with weeds.
<i>Site Paths</i>	No paths present
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Overgrowth conceals some low stones and grave markers. Nettles and thistles present.
<i>Maintenance</i>	None
<i>Condition of Monument</i>	Partly overgrown.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None, but toilets and picnic area at Dring slipway.
<i>Notes</i>	Location of monuments on island restricts accessibility.

RMP Ref: LF-	006-036	Monument	Ringfort - Rath
Location/ Townland	Derrycassan	National Grid Ref:	229570 E 286570 N
		RPS Ref	
		National Monument Ref	
Description	Located within Derrycassan, to the southwestern side of Lough Gowna. Univallate enclosure with visible bank and ditch. Tree-covered along bank and interior. A pathway runs around perimeter outside the ditch.		
Ownership	Public	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	Included in 'Woodland & Bog Walks in County Longford' (Longford Community Resources Ltd. Rural Social Scheme, 2008).
Local Sources Directions	Marked on map in 'Woodland & Bog Walks in County Longford' (Longford Community Resources Ltd. Rural Social Scheme, 2008).
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Road signs to forest, although not mentioning ringfort	
Site Signs	Signposted along forest paths	
Visibility	Visibility obscured due to afforestation	
Intervisibility		
Road Access	Monuments located well within forest, c.20-25 mins brisk walk along forest path	
Parking	At entrance to forest only	
Public Transport		
Approach Topography	Pathway through forest occasionally undulating, with slope upwards to monument	
Approach Surface	Gravel path	
Approach Safety	No visible hazards	
Approach Width	>2m wide, except around perimeter of ringfort.	Approach Gate width

<i>Gate type</i>	None
<i>Site Topography</i>	Level around perimeter, interior covered in trees
<i>Site Paths</i>	Path around perimeter of monument
<i>Paths Surfacing</i>	Gravel - forest path
<i>Paths Width</i>	1 - 1.5m width around rath
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Covered in forest plantation
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Seating and picnic areas/benches are provided along forest path, although not at monument itself.
<i>Notes</i>	

RMP Ref: LF-	006-066	Monument	Linear Earthwork
Location/ Townland	Ballinulty Lower, Carrickduff, Dring		National Grid Ref: 230790 <i>E</i> 284860 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	The Black Pig's Dyke (see also LF010-018 and LF011-009). Intermittent stretches of banks and ditches running between Lough Gowna and Lough Kinale. In parts consisting of bank and ditch, in other parts only the ditch is apparent.		
Ownership	Private	Date of Inspection	16/10/09
		Inspected By	SMcG
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in a list of places of interest under 'Heritage and Places' in Co. Longford at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from road but may not be immediately identifiable
Intervisibility	In close proximity to a number of enclosures and ringforts (e.g.. RMP no. LF006-065)
Road Access	Also intersected by roads in places.
Parking	No designated parking
Public Transport	
Approach Topography	Can be viewed from roadside or adjacent fields
Approach Surface	Tarmac, grass
Approach Safety	No footpath or road crossings at any point. Ditch is open in places
Approach Width	
	Approach Gate width >800mm
Gate type	Where present, field gates.

<i>Site Topography</i>	Bank & ditch feature, often incorporated into field boundaries - by nature undulating & uneven footing.
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Open ditch in places. Barbed wire fence running along sides of ditch elsewhere.
<i>Maintenance</i>	Not maintained. Used as field boundary for much of its length. Occasional litter/rubbish present.
<i>Condition of Monument</i>	Largely overgrown.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	Although easily viewed from roadside, this monument may not be readily identifiable or interpreted within the landscape. A reduction of overgrowth on a section of the earthworks close to the road would greatly enhance the appreciation of the monument.

RMP Ref: LF-	006-074	Monument	Church
Location/ Townland	Cloonagh (Granard By.)		National Grid Ref: 231790 <i>E</i> 287550 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	No upstanding remains. Site of church only adjacent to graveyard. Modern church built to the south, in the 1930s.		
Ownership	Private	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Noted on information board in Mullanalaghta village.
Local Sources Directions	
Graveyard Survey	Wheelchair access to entranceway only. No designated parking space. Private access (RC Church). Graveyard opened in 1826 (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Plaque at entrance to graveyard.
Visibility	
Intervisibility	
Road Access	Graveyard located adjacent to road.
Parking	Space for a number of cars on the northwest side of the graveyard
Public Transport	?
Approach Topography	The graveyard is located on a steep slope, with a slope throughout the graveyard.
Approach Surface	Tarmac, with grass in interior of graveyard
Approach Safety	
Approach Width	Verge only on roadside - no footpath
	Approach Gate width >800mm

<i>Gate type</i>	Double gate on southern side with a number of pedestrian gates along other sides
<i>Site Topography</i>	Overall, the graveyard slopes downwards to the north, although the site of the former church is located in the more low-lying, level part.
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	Grass cover throughout graveyard
<i>Paths Width</i>	
<i>Hazards</i>	No noticeable hazards
<i>Maintenance</i>	Well maintained, but grass slightly overgrown
<i>Condition of Monument</i>	Non-extant. No evidence on the ground of location of church site.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	008-011001	Monument	Church
Location/ Townland	Castleforbes Demesne	National Grid Ref:	209002 E 280398 N
		RPS Ref	35
		National Monument Ref	
Description	Church ruins within demesne of Castle Forbes, associated with family graveyard (LF008-011003) and bullaun stone (LF008-011002).		
Ownership	Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	Site was inaccessible for graveyard survey (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Hidden within wooded area in demesne
Intervisibility	
Road Access	Access via demesne driveway.
Parking	Private parking only, at Castle Forbes
Public Transport	
Approach Topography	Level paths through demesne
Approach Surface	Gravel and occasional woodland debris
Approach Safety	No noticeable hazards
Approach Width	Approach Gate width >800mm

<i>Gate type</i>	Double gate at entrance to Demesne grounds
<i>Site Topography</i>	Fairly level ground but presence of tree roots create uneven footing.
<i>Site Paths</i>	No paths on-site
<i>Paths Surfacing</i>	Grass-covered.
<i>Paths Width</i>	
<i>Hazards</i>	Uneven footing;
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Ruined but in good condition
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	This is located in the grounds of a private residence, owned by Lady Georgina Forbes. Viewing is strictly by appointment only and access may be denied. Also, modern coffins visible within family crypt.

RMP Ref: LF-	008-011002	Monument	Bullaun Stone
Location/ Townland	Castleforbes Demesne	National Grid Ref:	209031 <i>E</i> 280385 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Large stone with deep depression, located within church ruins (LF008-011001).		
Ownership	Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	Site was inaccessible for graveyard survey (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Located within church ruins.
Intervisibility	
Road Access	Access via demesne driveway.
Parking	Private parking only, at Castle Forbes
Public Transport	
Approach Topography	Level paths through demesne
Approach Surface	Gravel and occasional woodland debris
Approach Safety	No noticeable hazards
Approach Width	
	Approach Gate width >800mm

<i>Gate type</i>	Double gate and adjacent turnstile at entrance to Demesne grounds
<i>Site Topography</i>	Fairly level ground but presence of tree roots create uneven footing.
<i>Site Paths</i>	No paths on-site
<i>Paths Surfacing</i>	Grass-covered.
<i>Paths Width</i>	
<i>Hazards</i>	Uneven footing;
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	This is located in the grounds of a private residence, owned by Lady Georgina Forbes. Viewing is strictly by appointment only and access may be denied. Also, modern coffins visible within family crypt.

RMP Ref: LF-	008-011003	Monument	Graveyard
Location/ Townland	Castleforbes Demesne	National Grid Ref:	208996 E 280394 N
		RPS Ref	
		National Monument Ref	
Description	Family graveyard associated with Castle Forbes demesne. Adjacent to church ruins (LF008-011001)		
Ownership	Private	Date of Inspection	
		Inspected By	
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	Site was inaccessible for graveyard survey (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Hidden within wooded area in demesne
Intervisibility	
Road Access	Access via demesne driveway.
Parking	Private parking only, at Castle Forbes
Public Transport	
Approach Topography	Level paths through demesne
Approach Surface	Gravel and occasional woodland debris
Approach Safety	No noticeable hazards
Approach Width	
	Approach Gate width >800mm

<i>Gate type</i>	Double gate and adjacent turnstile at entrance to Demesne grounds
<i>Site Topography</i>	Fairly level ground but presence of tree roots create uneven footing.
<i>Site Paths</i>	No paths on-site
<i>Paths Surfacing</i>	Grass-covered.
<i>Paths Width</i>	
<i>Hazards</i>	Uneven footing;
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	This is located in the grounds of a private residence, owned by Lady Georgina Forbes. Viewing is strictly by appointment only and access may be denied. Also, modern coffins visible within family crypt.

RMP Ref: LF-	008-012006	Monument	Inscribed Stone (16th century)
Location/ Townland	Castleforbes Demesne	National Grid Ref:	209873 E 280161 N
		RPS Ref	
		National Monument Ref	
Description	<p>Located at gateway to the rose garden in Castleforbes Demesne. Set into wall adjacent to gateway. Inscription reads: 'This Yere 1562 Sir Henry Sidney L Deputy General brought the Irish heden in subjecto to the Crown of England subdyeteal the northe and vanquished the great rebel Shane O'Nele for the great quiet of the Realm'.</p> <p>Other monuments within the demesne include LF008-042 House (16th/17th century); LF008-012001 Castle - unclassified, Site of; LF008-012002 Armorial Plaque (17th Century); LF008-012003 Bawn; LF008-012004 Armorial Plaque (16th Century); LF008-012005 Dovecote.</p>		
Ownership	Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Within demesne grounds
Intervisibility	
Road Access	Accessed via demesne driveway
Parking	Private parking at house only
Public Transport	
Approach Topography	Driveway, some speed-ramps present.
Approach Surface	Tarmac
Approach Safety	No visible hazards

Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	Double gate and adjacent turnstile at entrance to Demesne grounds		
Site Topography	Generally even.		
Site Paths	All monuments except the dovecote are accessed via formal pathways.		
Paths Surfacing	Gravel pathway to the rose garden, driveway leading to house is tarmac. Other demesne pathways are gravel.		
Paths Width	>1.8m		
Hazards	No noticeable hazards		
Maintenance	Grounds are very well maintained		
Condition of Monument	In good condition. Private residence.		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	Garden and house staff present. No public facilities.		
Notes	This is located in the grounds of a private residence, owned by Lady Georgina Forbes. Viewing is strictly by appointment only and access may be denied.		

RMP Ref: LF-	008-014001	Monument	Church
Location/ Townland	Lisbrack (Longford By., Newtownforbes ED)	National Grid Ref:	210887 E 280236 N
		RPS Ref	
		National Monument Ref	
Description	Rectangular church ruins, located within field. Heavily overgrown, particularly on one side where overgrowth blocks entrance. Burials are located within the church ruins as well as outside to the eastern side of the ruins. The outer graves are located within small metal-railed plots. A small number of gravestones are also evident in overgrowth along the southern side of the church. However, the limits of the graveyard are not defined.		
Ownership	Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from road
Intervisibility	
Road Access	Adjacent to main road
Parking	No designated parking but parking possible at roadside
Public Transport	Public transport to Newtownforbes. Monument located a short distance outside of the town.
Approach Topography	Level road leading to fairly level field.
Approach Surface	Tarmac, then grass
Approach Safety	No footpath provided on road, which is busy with traffic.
Approach Width	
	Approach Gate width >800mm

<i>Gate type</i>	Field Gate.
<i>Site Topography</i>	Fairly level ground around church
<i>Site Paths</i>	No paths present
<i>Paths Surfacing</i>	Grass pastureland
<i>Paths Width</i>	
<i>Hazards</i>	Stability of ruin uncertain. Partially covered metal uprights of railings and general overgrowth may present hazards to the unwary.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Heavily overgrown and partially concealed
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No facilities
<i>Notes</i>	On private land but a public right-of-way exists.

RMP Ref: LF-	008-014002	Monument	Graveyard				
Location/ Townland	Lisbrack (Longford By., Newtownforbes ED)		National Grid Ref:	210887	E	280225	N
			RPS Ref				
			National Monument Ref				
Description	Rectangular church ruins, located within field. Heavily overgrown, particularly on one side where overgrowth blocks entrance. Burials are located within the church ruins as well as outside to the eastern side of the ruins. The outer graves are located within small metal-railed plots. A small number of gravestones are also evident in overgrowth along the southern side of the church. However, the limits of the graveyard are not defined.						
Ownership	Private	Date of Inspection	19/10/09	Inspected By	SMcG	Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#39 Lisbrack Graveyard, Clonguish. Currently closed; Heavily overgrown; no wheelchair access; private ownership (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from road
Intervisibility	
Road Access	Adjacent to main road
Parking	No designated parking but parking possible at roadside
Public Transport	Public transport to Newtownforbes. Monument located a short distance outside of the town.
Approach Topography	Level road leading to fairly level field.
Approach Surface	Tarmac, then grass
Approach Safety	No footpath provided on road, which is busy with traffic.

Approach Width		Approach Gate width	>800mm
Gate type	Field Gate.		
Site Topography	Fairly level ground around church		
Site Paths	No paths present		
Paths Surfacing	Grass pastureland		
Paths Width			
Hazards	Stability of ruin uncertain. Partially covered metal uprights of railings and general overgrowth may present hazards to the unwary.		
Maintenance	Not maintained		
Condition of Monument	Heavily overgrown and partially concealed		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	No facilities		
Notes	On private land but a public right-of-way exists.		

RMP Ref: LF-	008-035	Monument	Church
Location/ Townland	Townparks (Longford By.)		National Grid Ref: 210817 <i>E</i> 279530 <i>N</i>
		RPS Ref	105
		National Monument Ref	
Description	Regency style church, still in use. Within enclosed graveyard (LF008-035001).		
Ownership	Parish.	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign at entrance indicating the church but no mention of RMP status
Visibility	Visible at side of main road (N4)
Intervisibility	
Road Access	Adjacent to main road (N4)
Parking	Street parking available in Newtownforbes
Public Transport	Public transport to Newtownforbes
Approach Topography	Level pavement to graveyard with tarmac laneway to church
Approach Surface	Tarmac
Approach Safety	Pedestrian crossing present in town. No noticeable hazards
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Double gate leading to church grounds.

<i>Site Topography</i>	Generally level.
<i>Site Paths</i>	Level laneway leading to church and surrounding church. No paths in older part of graveyard.
<i>Paths Surfacing</i>	Tarmac on main lane to church with gravel-covered smaller paths. Well maintained grass where paths are absent.
<i>Paths Width</i>	>1.8m
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	Well maintained overall. Some overgrowth in rear corners of graveyard
<i>Condition of Monument</i>	Good condition
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Toilet is broken and out of use. No seating provided. One spotlight for church building.
<i>Notes</i>	

RMP Ref: LF-	008-035001	Monument	Graveyard
Location/ Townland	Townparks (Longford By.)	National Grid Ref:	210824 <i>E</i> 279512 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Enclosed graveyard associated with church LF008-035, in Newtownforbes town.		
Ownership	Public?	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign at entrance indicating the church but no mention of RMP status
Visibility	Visible at side of main road
Intervisibility	
Road Access	Adjacent to main road
Parking	Street parking available in Newtownforbes
Public Transport	Public transport to Newtownforbes
Approach Topography	Level pavement to graveyard with tarmac laneway to church
Approach Surface	Tarmac
Approach Safety	Pedestrian crossing present in town. No noticeable hazards
Approach Width	>1.8m Approach Gate width >800mm
Gate type	Double gate leading to church grounds.

<i>Site Topography</i>	Generally level.
<i>Site Paths</i>	Level laneway leading to church and surrounding church. No paths in older part of graveyard.
<i>Paths Surfacing</i>	Tarmac on main lane to church with gravel-covered smaller paths. Well maintained grass where paths are absent.
<i>Paths Width</i>	>1.8m
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	Well maintained overall. Some overgrowth in rear corners of graveyard
<i>Condition of Monument</i>	Good condition
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Toilet is broken and out of use. No seating provided. One spotlight for church building.
<i>Notes</i>	

RMP Ref: LF-	008-035002	Monument	Headstone (17th century)
Location/ Townland	Townparks (Longford By.)	National Grid Ref:	210811 <i>E</i> 279513 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	17th century headstone within graveyard LF008-035001. Others present dating to early 18th century.		
Ownership	Public?	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign at entrance indicating the church but no mention of RMP status
Visibility	Visible within graveyard.
Intervisibility	
Road Access	Adjacent to main road
Parking	Street parking available in Newtownforbes
Public Transport	Public transport to Newtownforbes
Approach Topography	Level pavement to graveyard with tarmac laneway to church
Approach Surface	Tarmac
Approach Safety	Pedestrian crossing present in town. No noticeable hazards
Approach Width	>1.8m Approach Gate width >800mm
Gate type	Double gate leading to church grounds.

<i>Site Topography</i>	Generally level.
<i>Site Paths</i>	Level laneway leading to church and surrounding church. No paths in older part of graveyard.
<i>Paths Surfacing</i>	Tarmac on main lane to church with gravel-covered smaller paths. Well maintained grass where paths are absent.
<i>Paths Width</i>	>1.8m
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	Well maintained overall. Some overgrowth in rear corners of graveyard
<i>Condition of Monument</i>	Good condition
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Toilet is broken and out of use. No seating provided. One spotlight for church building.
<i>Notes</i>	

RMP Ref: LF-	008-038	Monument	Settlement Cluster (17th century)
Location/ Townland	Lisbrack (Longford By., Newtownforbes ED), Townparks (Longford By.)	National Grid Ref:	210953 E 279686 N
		RPS Ref	
		National Monument Ref	
Description	No upstanding evidence of 17th century remains. Buildings along main street in Newtownforbes all appear modern, with new (1997) housing estate to the rear on the eastern side.		
Ownership	Public & Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	No visible remains
Intervisibility	
Road Access	
Parking	Streetside parking in town
Public Transport	
Approach Topography	Level footpaths
Approach Surface	Tarmac
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

Site Topography

Site Paths

Paths Surfacing

Paths Width

Hazards

Maintenance

Condition of Monument

Child friendly *On-site Information* *On-site Staff* *On-site Seating* *On-site Toilets*

On-site facilities

Notes

RMP Ref: LF-	008-039	Monument	Deerpark Boundary
Location/ Townland	Deerpark (Longford By.)	National Grid Ref:	<input type="text"/> E <input type="text"/> N
		RPS Ref	<input type="text"/>
		National Monument Ref	<input type="text"/>
Description	Not with RMP status on www.archaeology.ie website. Well-built, high masonry wall, part of which stretches along the roadside and part separated from the road by a field. Fields are grazed by horses and sheep, and so are not accessible to the general public. Wall is largely intact and partially ivy covered. Some modern repairs are evident.		
Ownership	Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	<input type="text"/>
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	<input type="text"/>
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	<input type="text"/>
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	<input type="text"/>
Visibility	Clearly visible from roadside
Intervisibility	<input type="text"/>
Road Access	Road runs adjacent to wall in places
Parking	Roadside parking may be possible
Public Transport	<input type="text"/>
Approach Topography	Roadside
Approach Surface	Tarmac
Approach Safety	Busy main road
Approach Width	<input type="text"/>
	Approach Gate width <input type="text"/>
Gate type	<input type="text"/>

<i>Site Topography</i>	Sections of wall can be viewed from road
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Traffic on main road
<i>Maintenance</i>	Modern repairs in parts. Otherwise not maintained - ivy covered in places. Some litter evident along roadside and former demesne entrance.
<i>Condition of Monument</i>	Appears structurally stable, but ivy may destabilise stone
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No facilities
<i>Notes</i>	

RMP Ref: LF-	009-001	Monument	Ritual Site - Holy Well
Location/ Townland	Bawn (Longford By.)	National Grid Ref:	214515 E 282813 N
		RPS Ref	
		National Monument Ref	
Description	St. Patrick's Well. Not identifiable on site. Possibly filled in. Rectangular raised area partly fenced off from rest of field may be mound (LF009-001002). Holy/Saint's Stone (LF009-001001) visible on top of mound as buried or outcrop bullaun stone.		
Ownership	Private	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Not identifiable
Intervisibility	
Road Access	Access via farm lane and across field
Parking	No designated parking
Public Transport	
Approach Topography	Road is generally level
Approach Surface	Grass
Approach Safety	Necessary to cross field and near-levelled wall
Approach Width	
	Approach Gate width
Gate type	No gate, but have to cross demolished section of field wall

<i>Site Topography</i>	Fairy level field, but ground churned up from farm animals and uneven underfoot.
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Located on farmland.
<i>Maintenance</i>	
<i>Condition of Monument</i>	Not readily identifiable
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No facilities
<i>Notes</i>	

RMP Ref: LF-	009-001001	Monument	Ritual Site - Holy/Saint's Stone
Location/ Townland	Bawn (Longford By.)	National Grid Ref:	214515 E 282813 N
		RPS Ref	
		National Monument Ref	
Description	Embedded into top of low mound (LF009-001001), this appears to be a bullaun stone (buried or outcrop bullaun) which has filled with water. The stone is marked by a number of rounded, which encircle it. A further stone has been placed on top of the bullaun, protecting it. A number of coins have been put into the bullaun, indicating local tradition and ritual associated with it. It is possible the stone is equated with the holy well (LF-009-001) which could not be separately identified.		
Ownership	Private	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Not immediately visible as covered by stone.
Intervisibility	
Road Access	Access via farm lane and across field
Parking	No designated parking
Public Transport	
Approach Topography	Road is generally level
Approach Surface	Grass
Approach Safety	Necessary to cross field and near-levelled wall
Approach Width	
	Approach Gate width

<i>Gate type</i>	No gate, but have to cross demolished section of field wall
<i>Site Topography</i>	Fairy level field, but ground churned up from farm animals and uneven underfoot.
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Located on farmland.
<i>Maintenance</i>	
<i>Condition of Monument</i>	Good condition
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No facilities.
<i>Notes</i>	

RMP Ref: LF-	009-006	Monument	Ringfort - Rath
Location/ Townland	Aghaward	National Grid Ref:	223456 E 282573 N
		RPS Ref	
		National Monument Ref	630
Description	Impressive enclosure with a high earthen bank and external ditch (the bank rises up to 2.5m from the base of the ditch). The monument, however, is partly overgrown with trees growing on the bank and outside the ditch. A fence runs around the external side of the ditch so it is not possible to follow the line of the monument from the exterior.		
Ownership	Public	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Only visible from house or field, although the monument itself is hidden by trees
Intervisibility	
Road Access	Right-of-way leads through field from road
Parking	No designated parking. Roadside parking may be possible
Public Transport	
Approach Topography	Right-of-way is uphill, with a mild slope.
Approach Surface	Grass. However access to monument is currently blocked by overgrowth at the edge of the field. Approach from the garden of Aghaward House is easier.
Approach Safety	Right-of-way entrance into monument overgrown.
Approach Width	
	Approach Gate width >800m
Gate type	Field gate at roadside. No gate at entrance to monument

<i>Site Topography</i>	By nature ditch and bank are steeply undulating. Bank and ditch is crossed in two places. General ground is uneven due to woodland growth and hidden logs on the ground.
<i>Site Paths</i>	No paths present
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Presence of brambles, hidden woodland debris creating very uneven footing. Also the external sides of the bank are quite steep.
<i>Maintenance</i>	Not maintained. Right-of-way not properly maintained
<i>Condition of Monument</i>	Overgrown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No facilities.
<i>Notes</i>	Monument is in state ownership but surrounding grounds are in private ownership. Accessibility would benefit from maintenance of right-of-way and clearance of overgrowth at entrance to monument.

RMP Ref: LF-	009-023	Monument	Historic Town
Location/ Townland	Ballinalee (aka Saint Johnstown)		National Grid Ref: 222600 <i>E</i> 280644 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Historic town of Ballinalee / Saint Johnstown.		
Ownership	Public/Private	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin. 1891. PP: 146, 152-154, 157-159, 164, 169, 202, 263, 285, 286, 289, 305. (http://www.archive.org/stream/cu31924028071029/cu31924028071029_djvu.txt)
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Architectural inventory carried out by the National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?county=LF&name=&town=ballinalee&townland=&type=quick&page=1 http://www.buildingsofireland.ie/niah/search.jsp?county=LF&name=&town=ballinalee&townland=&type=quick&page=2
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Information board in village. However, not in original location so directional information is misleading. Currently located in green space, behind wall which obscures information if viewed from low level and creates distance between sign and viewer.
Visibility	
Intervisibility	
Road Access	R194
Parking	Street parking in village centre and at RC church
Public Transport	Weekly rural transport bus service: Route 5 from Castlebrock/Drumeel to Ballinalee
Approach Topography	Concrete paths/sidewalk throughout
Approach Surface	

Approach Safety	No designated road crossing on main road - difficult & hazardous for those with vision or mobility concerns.	
Approach Width		Approach Gate width N/A
Gate type	N/A	
Site Topography		
Site Paths	Concrete paths/sidewalk throughout	
Paths Surfacing		
Paths Width		
Hazards	Lack of designated road crossing in village.	
Maintenance		
Condition of Monument		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>
	On-site Seating <input type="checkbox"/>	On-site Toilets <input type="checkbox"/>
On-site facilities		
Notes		

RMP Ref: LF-	009-023001	Monument	Church possible
Location/ Townland	Ballinalee (aka Saint Johnstown)		National Grid Ref: 222586 <i>E</i> 280852 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Not apparent on the ground. In the vicinity of Bully's Acre (LF009-023002)		
Ownership	Public	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information board in village. However, not in original location so directional information is misleading. Currently located in green space, behind wall which obscures information if viewed from low level and creates distance between sign and viewer.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	Parking available in village of Ballinalee
Public Transport	Weekly rural transport bus service: Route 5 from Castlebrock/Drumeel to Ballinalee
Approach Topography	Steps but currently blocked off.
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	Uneven ground, overgrown
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	N/A
<i>Paths Width</i>	N/A
<i>Hazards</i>	Uneven ground
<i>Maintenance</i>	Currently not open for public access. Not maintained
<i>Condition of Monument</i>	Unknown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	009-023002	Monument	Graveyard
Location/ Townland	Ballinalee (aka Saint Johnstown)	National Grid Ref:	222583 E 280834 N
		RPS Ref	143
		National Monument Ref	
Description	Graveyard with identifiable gravestones dating from 1760 onwards, now very overgrown. Also known as Bully's Acre, the burial site of executed United Irishmen in 1798.		
Ownership	Public	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information Information board in village. However, not in original location so directional information is misleading. Currently located in green space, behind wall which obscures information if viewed from low level and creates distance between sign and viewer.

Local Sources Directions

Graveyard Survey #30 Bully's Acre graveyard, Clonbroney. Not wheelchair accessible. Limited designated space. Public access but gate blocked off. Vegetation well-mowed at time of graveyard survey. Information panels present (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836.

National Sources Information

National Sources Directions

International Guidebooks

Internet Information <http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF®no=13304010>:
 "Description
 Graveyard on irregular wedge shaped-plan, laid out c. 1798. Site of executions and burial following the Battle of Ballinamuck in 1798. Cut stone recumbent table tomb, dated 1763, and collection of mainly uninscribed upright gravestones to interior. Site bounded by largely modern rubble limestone boundary wall having memorial plaque, dated 1998. Located to the north end of Ballinalee.
 Appraisal
 This simple site is of historical significance as the burial place of Irish rebels executed following the Battle of Ballinamuck in 1798, an important event in the history of Ireland (see record 13301004 for battlefield). The men were hanged from trees in the locality and the number of executions and burials here varies from 53, to 130 to 143 depending on the historical source. The graveyard contains a collection of grave markers, including a recumbent table-like monument, with the date 1763. This is also the possible site of a pre-1700 AD church(LF009-02301-/LF009-02302-). A two-storey building to the south, a former Masonic hall (13304013), is reputedly the place where Lord Cornwallis tried and sentenced to death those who are now buried in Bully's Acre."

Internet Directions

Field Survey:

Road Signs Information panel in village centre with map showing location of site.

Site Signs Memorial stone at entrance to graveyard identifying it as Bully's Acre.

Visibility

Intervisibility

Road Access	Access to memorial stone only		
Parking	Parking in Ballinalee village and space at entrance to site.		
Public Transport	Weekly rural transport bus service: Route 5 from Castlebrock/Drumeel to Ballinalee		
Approach Topography	Steps - blocked off at top of steps by wooden panel		
Approach Surface	Concrete		
Approach Safety			
Approach Width	Narrow	Approach Gate width	
Gate type			
Site Topography	Uneven ground, overgrown		
Site Paths	None		
Paths Surfacing	N/A		
Paths Width	N/A		
Hazards	Uneven ground		
Maintenance	Currently not open for public access. Not maintained		
Condition of Monument	Overgrown		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities			
Notes			

RMP Ref: LF-	009-023003	Monument	Church
Location/ Townland	Ballinalee (aka Saint Johnstown)	National Grid Ref:	<input type="text"/> E <input type="text"/> N
		RPS Ref	150
		National Monument Ref	<input type="text"/>
Description	St. John's, Church of Ireland. Located at south of Ballinalee town. Currently undergoing renovations. Not included as an RMP on the www.archaeology.ie website.		
Ownership	Private	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	<input type="text"/>

Desk-Based Survey

Local Sources Information	Information board in village. However, not in original location so directional information is misleading. Currently located in green space, behind wall which obscures information if viewed from low level and creates distance between sign and viewer.
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	<input type="text"/>
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	<p>http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13304009:</p> <p>"Description: Detached Church of Ireland church on cruciform-plan, built in 1825 and enlarged in 1830, with three-bay nave, two-bay transept to the east, single-bay transept to the west, three-stage tower on a square-plan attached to the south, and with a two-bay single-storey vestry to the east elevation, added c. 1860. Possibly incorporating the fabric of an earlier church building to site. Now out of use. Pitched natural slate roofs with crenellated parapet and with moulded cut stone cornice. Crenellated parapet to tower with cut limestone corner pinnacles with moulded cut stone finials over. Snecked dressed limestone walls over dressed limestone plinth. Claspings corner buttresses and limestone date plaque to tower. Roughcast render to east transept. Pointed arch window openings with chamfered dressed limestone surrounds and sills, carved limestone hoodmouldings over and stained glass windows with timber Y-tracery. Tudor-arched five-light window opening to chancel gable (north) with chamfered dressed limestone surround, carved limestone hoodmoulding, stained glass windows with timber Y-tracery. Paired square-headed openings to tower at second stage level with chamfered dressed limestone surrounds, carved limestone hoodmouldings and with stained glass or fixed timber windows. Pointed arch openings to tower at belfry level (third stage) with chamfered dressed limestone surrounds, carved limestone hoodmouldings and metal or timber louvers. Pointed arch door opening to door with timber battened double doors, limestone steps, chamfered carved limestone surround and carved limestone hoodmoulding. Pointed arch opening to vestry with timber battened door, chamfered dressed limestone surround and carved limestone hoodmoulding, approached by flight of limestone steps. Set in graveyard with collection of cut stone grave markers. Set back from road to the south end of Ballinalee with rubble limestone boundary walls to road-frontage (west). Dressed limestone gate piers (on square-plan) with cut limestone capstones and cast-iron gates.</p> <p>Appraisal An attractive early nineteenth-century Church of Ireland church, built in a Gothic Revival style, which retains its early form, character and fabric. Although now vacant, its salient features remain intact. This church is of a more elaborate form than is more typically found in rural Longford, as is the standard of the cut limestone detailing, particularly to the openings and to the pinnacles of the tower. The large window openings are particularly impressive, particularly the large Tudor-arched five-light</p>

window to the chancel gable. The layout of this church is typical of the standard hall and tower church, which were built in large numbers, particularly between 1808 - 1830, using loans and grants from the Board of First Fruits (1722 - 1833). These small, simple, but well-built churches have become almost iconographic features of the rural Irish countryside. Lewis (1837) records that this church at Ballinalee was constructed using a gift of £1100 and a loan of £300 from the Board of First Fruits, and that it was enlarged in 1830 by aid of a loan of £300 from the same Board, and with a donation of £100 from the Countess Dowager of Rosse. It was built to designs by the eminent architect John Hargrave (c. 1788 - 1833), an architect that worked extensively in County Longford during the 1820s. It is not unlike a simpler and reduced version of Hargrave's fine church at Portnashangan in County Westmeath (15401215) in that it shares the crenellated parapet, the wide pointed arch window openings to the nave, the five-light Tudor-arched window opening to the chancel and has a similar style of corner pinnacles to the tower. Local sources suggest that the architect of this Church of Ireland church was William Farrell (died 1851). Farrell designed the Church of Ireland church at Keenagh (13313025) in 1832, also under the patronage of Countess Dowager of Rosse. Perhaps Farrell's input here was the 1830 enlargement mentioned by Lewis (1837), which may have been an extension of the east transept. The vestry at Ballinalee appears to have been added sometime later, perhaps c. 1860. The fine church is an important element of the built heritage of County Longford and of the social history of the Ballinalee area. The simply boundary walls, the entrance gates and the collection of grave markers in the surrounding graveyard complete the setting and add to this notable composition. The earliest grave marker here is dated 1736, suggesting the present church occupies the site of an earlier church building. It forms a pair of related structures with the former Church of Ireland rectory (13304007) to the southwest. The interior retains interesting plasterwork to the ceilings."

**Internet
Directions**

--

Field Survey:

Road Signs

--

Site Signs

--

Visibility

Visible from L1065.

Intervisibility

--

Road Access

Main road through village.

Parking

Parking available in village

Public Transport

Weekly rural transport bus service: Route 5 from Castlebrock/Drumeel to Ballinalee
--

**Approach
Topography**

Level

Approach Surface

Tarmac pathway

Approach Safety

No noticeable hazards.

Approach Width

>1.8m	<i>Approach Gate width</i>	>800mm
-------	----------------------------	--------

Gate type

Closed at time of survey during refurbishments
--

Site Topography

Level

Site Paths

Pathway leads through graveyard to church

Paths Surfacing

Tarmac

Paths Width

>1.8m

Hazards

Church undergoing refurbishment at time of survey

Maintenance

Well maintained

**Condition of
Monument**

undergoing renovations

Child friendly

On-site Information

On-site Staff

On-site Seating

On-site Toilets

On-site facilities

--

Notes

--

RMP Ref: LF-	009-023004	Monument	Graveyard
Location/ Townland	Ballinalee (aka Saint Johnstown)	National Grid Ref:	<input type="text"/> E <input type="text"/> N
		RPS Ref	<input type="text"/>
		National Monument Ref	<input type="text"/>
Description	Associated with St. John's Church. Gravestones are largely 19th and 20th century. This is no longer included as an RMP on the www.archaeology.ie website.		
Ownership	Private	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	<input type="text"/>

Desk-Based Survey

Local Sources Information	Information board in village. However, not in original location so directional information is misleading. Currently located in green space, behind wall which obscures information if viewed from low level and creates distance between sign and viewer.
Local Sources Directions	<input type="text"/>
Graveyard Survey	#35 Saint John's Graveyard (Ballinalee), Clonbroney. Still in use; limited wheelchair access; private ownership (C of I) (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	<input type="text"/>
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	<input type="text"/>
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	<input type="text"/>
Visibility	Visible from L1056.
Intervisibility	<input type="text"/>
Road Access	Main road through village.
Parking	Parking available in village
Public Transport	Weekly rural transport bus service: Route 5 from Castlebrock/Drumeel to Ballinalee
Approach Topography	Level
Approach Surface	Tarmac pathway
Approach Safety	No noticeable hazards.

Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	Closed at time of survey during refurbishments		
Site Topography	Level		
Site Paths	Pathway leads through graveyard to church		
Paths Surfacing	Tarmac		
Paths Width	>1.8m		
Hazards	Church undergoing refurbishment at time of survey		
Maintenance	Well maintained		
Condition of Monument	undergoing renovations		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/>
On-site facilities			
Notes			

RMP Ref: LF-	009-023005	Monument	Structure
Location/ Townland	Ballinalee (aka Saint Johnstown)		National Grid Ref: 222551 E 280762 N
		RPS Ref	
		National Monument Ref	
Description	Freemason's Lodge. Unroofed stone building with doors and windows boarded up. Also known as "The Granary".		
Ownership	Public	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information board in village. However, not in original location so directional information is misleading. Currently located in green space, behind wall which obscures information if viewed from low level and creates distance between sign and viewer.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	<p>http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13304013: "Description Detached four-bay two-storey former Masonic hall, built or altered c. 1773. Later in use as an outbuilding, now out of use. Flight of limestone flagged steps to the north gable end gives access to first floor. Pitched natural slate roof, now collapsing. Rubble limestone walls with roughcast render over. Square-headed window openings, fittings now gone. Cut stone lintel over window opening at ground floor to main elevation (east). Shallow segmental-headed carriage arch, now partially infilled, to the south end of the east elevation having tooled limestone voussoirs over; oculus opening over with brick surround. Round-headed window opening to the south gable end at first floor level with brick surrounds, now partially blocked, with cantilevered dressed limestone ledge below. Set back from road to the north end of Ballinalee and to the south of Bully's Acre (13304010). Modern housing estate to the west/southwest.</p> <p>Appraisal Although derelict, this building is an important element of the built heritage and social history of Ballinalee. It was reputedly built (or altered for use) as a Masonic hall in 1773. It was in the ownership of the Brethren of Saint Johnstown/Ballinalee (Lodge No. 505) from Sept. 1773 until January 1830 when the warrant was cancelled. It is reputedly the site where Lord Cornwallis tried and sentenced to death a number of Irish rebels following the Battle of Ballinamuck in 1798. These rebels were hanged and buried in Bully's Acre (13304010) adjacent to the north. It forms part of an interesting collection of sites associated with the Battle of Ballinamuck (see 13301004 for battlefield), which was an important event in the history of Ireland. It was later converted for use as an outbuilding c. 1840 and the carriage arch and many of the openings were probably added around this time."</p>
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Large stone building
Intervisibility	
Road Access	Accessed from main road in village
Parking	Some space for vehicles adjacent to building
Public Transport	Weekly rural transport bus service: Route 5 from Castlebrock/Drumeel to Ballinalee
Approach Topography	At roadside, with paved area in fore of building with flush kerb.
Approach Surface	Tarred road & paved yard area
Approach Safety	No visible hazards
Approach Width	<input type="text"/> Approach Gate width <input type="text"/>
Gate type	None
Site Topography	Viewable from outside only. Interior not accessible to public
Site Paths	N/A
Paths Surfacing	N/A
Paths Width	N/A
Hazards	Exterior masonry appears sound. No visible hazards
Maintenance	Exterior well maintained
Condition of Monument	ruined
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>
	On-site Staff <input type="checkbox"/>
	On-site Seating <input type="checkbox"/>
	On-site Toilets <input type="checkbox"/>
On-site facilities	None
Notes	

RMP Ref: LF-	009-026001	Monument	Church possible
Location/ Townland	Killoe Glebe	National Grid Ref:	219761 E 277900 N
		RPS Ref	
		National Monument Ref	
Description	No visible structural remains. A 19th century church and small outhouse are situated to one side of the graveyard (LF009-026002), in a separate enclosure. A second, small graveyard is attached to the modern church.		
Ownership	Parish.	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	Wheelchair accessible to entrance only. No designated parking space. Public access (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Modern church and graveyards on hill, visible from road. (L1065)
Intervisibility	
Road Access	Accessed via laneway from road.(L1065)
Parking	Some (non-designated) parking at front of church, on grass surface.
Public Transport	
Approach Topography	Sloping laneway, but wide enough for cars.
Approach Surface	Grass and gravel
Approach Safety	
Approach Width	
	Approach Gate width >800mm

<i>Gate type</i>	Double metal gates, and adjacent 'kissing gate'.
<i>Site Topography</i>	Graveyard is generally level
<i>Site Paths</i>	No laid out paths.
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Slightly overgrown, some headstone debris around edges. Possibility of trip hazards.
<i>Maintenance</i>	Grass slightly overgrown
<i>Condition of Monument</i>	Not identifiable
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	009-026002	Monument	Graveyard		
Location/ Townland	Killoe Glebe		National Grid Ref:	219763 E	277890 N
			RPS Ref		
			National Monument Ref		
Description	RC graveyard within partly circular enclosure. Modern (19th century) C of I church and graveyard in adjoining, separate walled enclosure. Legible headstones within graveyard date to 19th and 20th century. The circular nature of the enclosing wall suggests an original early medieval origin for the site. Some earthworks in front of the church may relate to the original enclosure.				
Ownership	Parish.	Date of Inspection	14/10/09	Inspected By	SMcG
				Accessibility Rating	B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#75 Killoe Glebe Graveyard (RC), Killoe. Wheelchair accessible to church only. No designated parking space. Private access (Church of Ireland) (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Modern church and graveyards on hill, visible from road. (L1065)
Intervisibility	
Road Access	Accessed via laneway from road.
Parking	Some (non-designated) parking at front of church, on grass surface.
Public Transport	
Approach Topography	Sloping laneway, but wide enough for cars.
Approach Surface	Grass and gravel
Approach Safety	

<i>Approach Width</i>		<i>Approach Gate width</i>	>800mm
<i>Gate type</i>	Double metal gates, and adjacent 'kissing gate'.		
<i>Site Topography</i>	Graveyard is generally level		
<i>Site Paths</i>	No laid out paths.		
<i>Paths Surfacing</i>			
<i>Paths Width</i>			
<i>Hazards</i>	Slightly overgrown, some headstone debris around edges. Possibility of trip hazards.		
<i>Maintenance</i>	Grass slightly overgrown. Maintenance shed present.		
<i>Condition of Monument</i>	Not identifiable		
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>	<i>On-site Staff</i> <input type="checkbox"/>	<i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None		
<i>Notes</i>			

RMP Ref: LF-	010-017001	Monument	Graveyard
Location/ Townland	Clogh (Granard By.)	National Grid Ref:	231808 <i>E</i> 283778 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Rectangular enclosure, delimited by low, collapsed dry-stone wall. Located within field. No headstones or markers visible.		
Ownership	Private	Date of Inspection	16/10/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#04 Clogh Graveyard, Abbeylara. Not wheelchair accessible. No designated parking. Private ownership (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Trees along roadside block visibility from road.
Intervisibility	
Road Access	
Parking	May be possible to park at roadside
Public Transport	
Approach Topography	Need to cross a number of fields from road entrance, as no entrance from road into field containing site. Gently undulating land with uneven footing.
Approach Surface	Fields under pasture
Approach Safety	Cattle grazing in fields.
Approach Width	
	Approach Gate width

<i>Gate type</i>	Field gate
<i>Site Topography</i>	Uneven ground due to presence of tree roots and scattered, part-buried stones from enclosing element.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Roots, branches and hidden stones represent trip hazards
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	No upstanding features present.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	010-017002	Monument	Church possible
Location/ Townland	Clogh (Granard By.)	National Grid Ref:	231808 E 283778 N
		RPS Ref	
		National Monument Ref	
Description	No upstanding remains visible. Associated with graveyard LF010-017001.		
Ownership	Private	Date of Inspection	16/10/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	No remains visible
Intervisibility	
Road Access	
Parking	May be possible to park at roadside
Public Transport	
Approach Topography	Need to cross a number of fields from road entrance, as no entrance from road into field containing site. Gently undulating land with uneven footing.
Approach Surface	Fields under pasture
Approach Safety	Cattle grazing in fields.
Approach Width	
	Approach Gate width
Gate type	Field gate

<i>Site Topography</i>	Uneven ground due to presence of tree roots and scattered, part-buried stones from enclosing element.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Roots, branches and hidden stones represent trip hazards
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	No upstanding features present.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	010-018	Monument	Linear Earthwork
Location/ Townland	Aghnagarron, Carrickduff, Clogh (Granard By.), Dalystown, Tromra.		National Grid Ref: 230790 <i>E</i> 284860 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	The Black Pig's Dyke (see also LF006-066 and LF011-009). Intermittent stretches of banks and ditches running between Lough Gowna and Lough Kinale. In parts consisting of bank and ditch, in other parts only the ditch is apparent.		
Ownership		Date of Inspection	
		Inspected By	
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in a list of places of interest under 'Heritage and Places' in Co. Longford at http://www.longfordtourism.ie http://en.wikipedia.org/wiki/Black_Pig's_Dyke
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	010-055	Monument	Historic Town				
Location/ Townland	Granard, Rathcroan		National Grid Ref:	233275	E	280980	N
			RPS Ref				
			National Monument Ref				
Description	Granard historic town.						
Ownership	Public/Private	Date of Inspection	16/10/09	Inspected By	SMcG	Accessibility Rating	B/C

Desk-Based Survey

Local Sources Information	A map along the main street. indicates the presence of an information board which is not at the location indicated. However an information board is located at a small green space. However this is not immediately accessible as it is approached via a steep uphill slope and steps.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in list of places of interest under 'Heritage and Places' in Co. Longford at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Signs for Granard town	
Site Signs	Information board in town - not readily accessible as steps outside green area where board is located.	
Visibility		
Intervisibility	Intervisible with other RMP within the town e.g.. Motte LF010-080001.	
Road Access	On main road (R194 & N55)	
Parking	Street parking within town	
Public Transport	Public transport to Granard town.	
Approach Topography	Centre of town is level. However there is a steep incline uphill towards church, graveyard and the information board.	
Approach Surface	Road, pavements	
Approach Safety	Pedestrian crossings provided.	
Approach Width	>1.8m	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	Centre of town is level. However there is a steep incline uphill towards church, graveyard and the information board.
<i>Site Paths</i>	Pavements throughout town
<i>Paths Surfacing</i>	Concrete, paving, tarmac
<i>Paths Width</i>	>1.8m
<i>Hazards</i>	No pedestrian crossing on the main street.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No public toilets or seating in town centre.
<i>Notes</i>	

RMP Ref: LF-	010-055001	Monument	Church possible
Location/ Townland	Granard	National Grid Ref:	232948 E 280883 N
		RPS Ref	
		National Monument Ref	
Description	No extant remains. Located on site of modern Church of Ireland church.		
Ownership	Private	Date of Inspection	16/10/09
		Inspected By	SMcG
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	A map along the main street. indicates the presence of an information board which is not at the location indicated. However an information board is located at a small green space. However this is not immediately accessible as it is approached via a steep uphill slope and steps.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13305002 - Description and appraisal of St. Patrick's and site.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Located off main road (R194 & L5133)
Parking	Parking at church
Public Transport	Public transport to Granard town.
Approach Topography	Steep incline uphill from town centre to church, laneway from road to church.
Approach Surface	Pavement, tarmac.
Approach Safety	No visible hazards
Approach Width	>1.8m
Approach Gate width	Double gate is >800mm

<i>Gate type</i>	Double, metal railing gates open onto laneway to church. Additional pedestrian gate from street to graveyard does not open fully.
<i>Site Topography</i>	Some uneven, slightly undulating ground in graveyard. General fall-off in ground from the church.
<i>Site Paths</i>	Laneway to front of church. No laid paths elsewhere
<i>Paths Surfacing</i>	Tarmac laneway. Grass elsewhere
<i>Paths Width</i>	>1.8m on laneway
<i>Hazards</i>	Some uneven footing in graveyard.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	No above ground remains.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	010-055002	Monument	Graveyard
Location/ Townland	Granard	National Grid Ref:	232956 E 280857 N
		RPS Ref	
		National Monument Ref	
Description	Graveyard associated with Church LF010-055001. Located within rectangular enclosure. Visible grave markers largely date to the 19th and 20th century, although a few may be of earlier date.		
Ownership	Private	Date of Inspection	16/10/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	A map along the main street. indicates the presence of an information board which is not at the location indicated. However an information board is located at a small green space. However this is not immediately accessible as it is approached via a steep uphill slope and steps.
Local Sources Directions	
Graveyard Survey	#62 Granard (C of I) Graveyard, Granard. Wheelchair access to church only. Limited parking space available. Pathway to church only. Private access (Church of Ireland) (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Located off main road (R194 & L5133).
Parking	Parking at church
Public Transport	Public transport to Granard town.
Approach Topography	Steep incline uphill from town centre to church, laneway from road to church.
Approach Surface	Pavement, tarmac.
Approach Safety	No visible hazards

Approach Width	>1.8m	Approach Gate width	Double gate is >800mm
Gate type	Double, metal railing gates open onto laneway to church. Additional pedestrian gate from street to graveyard does not open fully.		
Site Topography	Some uneven, slightly undulating ground in graveyard. General fall-off in ground from the church.		
Site Paths	Laneway to front of church. No laid paths elsewhere		
Paths Surfacing	Tarmac laneway. Grass elsewhere		
Paths Width	>1.8m on laneway		
Hazards	Some uneven footing in graveyard.		
Maintenance	Well maintained as part of the Rural Social Scheme.		
Condition of Monument	No above ground remains.		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/>
On-site facilities	None		
Notes			

RMP Ref: LF-	010-062001	Monument	Religious House - Unclassified
Location/ Townland	Clonbroney	National Grid Ref:	226160 E 279920 N
		RPS Ref	
		National Monument Ref	
Description	No upstanding structure apparent at ground level.		
Ownership	Public	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	The site is known as Old Clonbroney cemetery. Believed to locally be an early Christian convent.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Recognisable only by the presence of a small cross on each gate-pillar.
Visibility	No extant remains visible
Intervisibility	
Road Access	Located at side of minor local road, accessed from the R194, which terminates a short distance to the
Parking	Some parking at wide grass verge at entrance to graveyard
Public Transport	
Approach Topography	Level area in front of approach gate but heavily overgrown with grass at present making footing unsure.
Approach Surface	Hardcore and grass
Approach Safety	No through road so little traffic
Approach Width	>1.8m Approach Gate width c.1.2m
Gate type	Cast-iron gate, but not functional. A stepped stone stile in the wall to one side of the gate allows

	for some pedestrian access.
<i>Site Topography</i>	Undulating and heavily overgrown with very uneven surface
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	Overgrown grass & weed covering over entire site
<i>Paths Width</i>	N/A
<i>Hazards</i>	Degree of overgrowth, uneven ground and presence of low gravestones and loose stone create trip hazards
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Overgrown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	Clearance of overgrowth is necessary to fully assess extant remains of any religious structure. However, in general the site has restricted accessibility.

RMP Ref: LF-	010-062002	Monument	Graveyard		
Location/ Townland	Clonbroney		National Grid Ref:	226160 <i>E</i>	279920 <i>N</i>
			RPS Ref		
			National Monument Ref		
Description	Circular graveyard, enclosed by low stone wall and hedge. Heavily overgrown so that internal features are not readily identifiable				
Ownership	Public	Date of Inspection	22/09/09	Inspected By	SMcG
				Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#32 Clonbroney (Old) Graveyard, Clonbroney. Currently closed and overgrown; no wheelchair access; public ownership (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Recognisable only by the presence of a small cross on each gate-pillar.
Visibility	Visible at close quarters.
Intervisibility	
Road Access	Located at side of minor local road which terminates a short distance to the northeast, so no through r
Parking	Some parking at wide grass verge at entrance to graveyard
Public Transport	
Approach Topography	Level area in front of approach gate but heavily overgrown with grass at present making footing unsure.
Approach Surface	Hardcore and grass
Approach Safety	No through road so little traffic
Approach Width	>1.8m
Approach Gate width	c.1.2m

<i>Gate type</i>	Cast-iron gate, but not functionable. A stepped stone stile in the wall to one side of the gate allows for some pedestrian access.
<i>Site Topography</i>	Undulating and heavily overgrown with very uneven surface
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	Overgrown grass & weed covering over entire site
<i>Paths Width</i>	N/A
<i>Hazards</i>	Degree of overgrowth, uneven ground and presence of low gravestones and loose stone create trip hazards
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Overgrown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	Clearance of overgrowth is necessary to fully assess features within the graveyard. However, in general the site has restricted accessibility.

RMP Ref: LF-	010-062003	Monument	Church possible
Location/ Townland	Clonbroney	National Grid Ref:	226160 E 279920 N
		RPS Ref	
		National Monument Ref	
Description	No upstanding structure apparent at ground level.		
Ownership	Public	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Recognisable only by the presence of a small cross on each gate-pillar.
Visibility	No extant remains visible
Intervisibility	
Road Access	Located at side of minor local road which terminates a short distance to the northeast, so no through r
Parking	Some parking at wide grass verge at entrance to graveyard
Public Transport	
Approach Topography	Level area in front of approach gate but heavily overgrown with grass at present making footing unsure.
Approach Surface	Hardcore and grass
Approach Safety	No through road so little traffic
Approach Width	>1.8m
	Approach Gate width c.1.2m
Gate type	Cast-iron gate, but not functional. A stepped stone stile in the wall to one side of the gate allows

	for some pedestrian access.
<i>Site Topography</i>	Undulating and heavily overgrown with very uneven surface
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	Overgrown grass & weed covering over entire site
<i>Paths Width</i>	N/A
<i>Hazards</i>	Degree of overgrowth, uneven ground and presence of low gravestones and loose stone create trip hazards
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Overgrown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	Clearance of overgrowth is necessary to fully assess extant remains of any structure. However, in general the site has restricted accessibility.

RMP Ref: LF-	010-062004	Monument	Pillar Stone possible
Location/ Townland	Clonbroney	National Grid Ref:	226160 E 279920 N
		RPS Ref	
		National Monument Ref	
Description	Low sub-rectangular stone to one side of graveyard. No markings were apparent. Uncertain antiquity.		
Ownership	Public	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible at close quarters.
Intervisibility	
Road Access	Located at side of minor local road which terminates a short distance to the northeast, so no through r
Parking	Some parking at wide grass verge at entrance to graveyard
Public Transport	
Approach Topography	Level area in front of approach gate but heavily overgrown with grass at present making footing unsure.
Approach Surface	Hardcore and grass
Approach Safety	No through road so little traffic
Approach Width	>1.8m Approach Gate width c.1.2m
Gate type	Cast-iron gate, but not functional. A stepped stone stile in the wall to one side of the gate allows

	for some pedestrian access.
<i>Site Topography</i>	Undulating and heavily overgrown with very uneven surface
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	Overgrown grass & weed covering over entire site
<i>Paths Width</i>	N/A
<i>Hazards</i>	Degree of overgrowth, uneven ground and presence of low gravestones and loose stone create trip hazards
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Overgrown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	010-063	Monument	Ringfort - Rath
Location/ Townland	Killeen (Granard By.)		National Grid Ref: 228857 <i>E</i> 280834 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Circular enclosure, with low bank and ditch, partially encircled with bushes. Interior slightly raised. Located within field. A rectangular area cut into the bank in the north may represent quarrying of the bank at some point.		
Ownership	Private	Date of Inspection	16/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible only within field
Intervisibility	
Road Access	Access through fields
Parking	
Public Transport	
Approach Topography	Field slopes upwards to ringfort. Long approach through fields.
Approach Surface	Pasture, grazed by cattle. Surface mildly churned by hoof-marks
Approach Safety	Cattle present in fields
Approach Width	
	Approach Gate width >800mm
Gate type	Field gates

<i>Site Topography</i>	Nature of site is undulating. Barbed wire fence along top of bank must be crossed to access interior
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Barbed wire fence, uneven footing where bank and ditch are overgrown. Presence of cattle in the field.
<i>Maintenance</i>	Overgrowth on bank, otherwise the site is relatively clear of overgrowth, although probably not actively maintained.
<i>Condition of Monument</i>	Overgrown in places.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	010-078002	Monument	Church possible
Location/ Townland	Granardkill	National Grid Ref:	231970 E 280120 N
		RPS Ref	
		National Monument Ref	
Description	No upstanding remains visible. Possibly located at raised area within graveyard (LF010-078004).		
Ownership	Public	Date of Inspection	16/10/09
		Inspected By	SMcG
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	Joy Burns and Bernadette Grier (eds), "Granard - its history, our heritage". Granard Guild I.C.A., Longford, 1987
Local Sources Directions	
Graveyard Survey	
National Sources Information	Excavation took place on site in 2006: http://www.excavations.ie/Pages/Details.php?Year=&County=Longford&id=10035
National Sources Directions	
International Guidebooks	
Internet Information	http://www.excavations.ie/Pages/Details.php?Year=&County=Longford&id=10035
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Located along side of road
Intervisibility	Deserted settlement LF010-078001 is located on opposite of road. Granard motte (LF010-080002) is
Road Access	Beside road
Parking	Not designated but widened area at side of road for parking.
Public Transport	
Approach Topography	Entrance from main road
Approach Surface	Tarmac
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	4 pedestrian gates and 1 double gate. Some of the pedestrian gates have a slight step to interior of

	site.
<i>Site Topography</i>	Rise in central part of graveyard.
<i>Site Paths</i>	Paths in newer section of graveyard.
<i>Paths Surfacing</i>	Gravel
<i>Paths Width</i>	1.2 - 1.8
<i>Hazards</i>	Steep drop from graveyard to road in one place
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Not identifiable / non-extant.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input checked="" type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	1 bench seat provided in graveyard.
<i>Notes</i>	

RMP Ref: LF-	010-078003	Monument	Hospital possible		
Location/ Townland	Granardkill		National Grid Ref:	<input type="text"/> E	<input type="text"/> N
			RPS Ref	<input type="text"/>	
			National Monument Ref	<input type="text"/>	
Description	No precise location for this. No extant upstanding remains. The hospital is known from historical references only. Not considered an RMP site on www.archaeology.ie				
Ownership	Private	Date of Inspection	16/10/09	Inspected By	SMcG
				Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Joy Burns and Bernadette Grier (eds), "Granard - its history, our heritage". Granard Guild I.C.A., Longford, 1987
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	2006 archaeological excavation report: http://www.excavations.ie/Pages/Details.php?Year=&County=Longford&id=10035
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	<input type="text"/>
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	A sign declaring the site as a National Monument (a 'Fogra') is located in an adjoining field, although the site is not listed on the current National Monuments list.
Visibility	<input type="text"/>
Intervisibility	<input type="text"/>
Road Access	<input type="text"/>
Parking	<input type="text"/>
Public Transport	<input type="text"/>
Approach Topography	<input type="text"/>
Approach Surface	<input type="text"/>
Approach Safety	<input type="text"/>
Approach Width	<input type="text"/>
	Approach Gate width <input type="text"/>

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	010-078004	Monument	Graveyard	
Location/ Townland	Granardkill		National Grid Ref:	231970 <i>E</i> 280120 <i>N</i>
			RPS Ref	
			National Monument Ref	
Description	Large graveyard, still in use. Central area of graveyard is raised and possibly represents the location of church LF010-078002.			
Ownership	Public	Date of Inspection	16/10/09	Inspected By SMcG Accessibility Rating

Desk-Based Survey

Local Sources Information	Joy Burns and Bernadette Grier (eds), "Granard - its history, our heritage". Granard Guild I.C.A., Longford, 1987
Local Sources Directions	
Graveyard Survey	#64 Granardkille Graveyard, Granard. Limited wheelchair accessibility. No designated parking. Gravel pathways present. Public access (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	2006 excavation report: http://www.excavations.ie/Pages/Details.php?Year=&County=Longford&id=10035
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Located along side of road
Intervisibility	Deserted settlement LF010-078001 is located on opposite of road. Granard motte (LF010-080002) is
Road Access	Beside road
Parking	Not designated but widened area at side of road for parking.
Public Transport	
Approach Topography	Entrance from main road
Approach Surface	Tarmac
Approach Safety	No visible hazards

Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	4 pedestrian gates and 1 double gate. Some of the pedestrian gates have a slight step to interior of site.		
Site Topography	Rise in central part of graveyard.		
Site Paths	Paths in newer section of graveyard.		
Paths Surfacing	Gravel		
Paths Width	1.2 - 1.8		
Hazards	Steep drop from graveyard to road in one place		
Maintenance	Well maintained		
Condition of Monument	Not identifiable / non-extant.		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input checked="" type="checkbox"/>
On-site facilities	1 bench seat provided in graveyard.		
Notes			

RMP Ref: LF-	010-078005	Monument	Pit-Burial		
Location/ Townland	Granardkill		National Grid Ref:	<input type="text"/> E	<input type="text"/> N
			RPS Ref	<input type="text"/>	
			National Monument Ref	<input type="text"/>	
Description	Uncovered during archaeological excavations in 2003-2004. No longer in-situ.				
Ownership	Private	Date of Inspection	16/10/09	Inspected By	SMcG
				Accessibility Rating	D

Desk-Based Survey

Local Sources Information	<input type="text"/>
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	<input type="text"/>
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	http://www.excavations.ie/Pages/Details.php?Year=&County=Longford&id=10035
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	A sign declaring the site as a National Monument (a 'Fogra') is located in an adjoining field, although the site is not listed on the current National Monuments list.
Visibility	<input type="text"/>
Intervisibility	<input type="text"/>
Road Access	<input type="text"/>
Parking	<input type="text"/>
Public Transport	<input type="text"/>
Approach Topography	<input type="text"/>
Approach Surface	<input type="text"/>
Approach Safety	<input type="text"/>
Approach Width	<input type="text"/>
	Approach Gate width <input type="text"/>

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	010-078006	Monument	Souterrain		
Location/ Townland	Granardkill	National Grid Ref:	232140	<i>E</i>	280240
		RPS Ref			
		National Monument Ref			
Description	Uncovered during archaeological excavations in 2003-2004. No longer in-situ. Associated with Deserted Settlement LF010-078001.				
Ownership		Date of Inspection		Inspected By	
				Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	http://www.excavations.ie/Pages/Details.php?Year=&County=Longford&id=10035
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	010-080001	Monument	Castle - Motte And Bailey
Location/ Townland	Moatfield	National Grid Ref:	232978 E 280712 N
		RPS Ref	
		National Monument Ref	263
Description	Granard Motte. Large, high motte with associated bailey, enclosed within impressively large banks & fosse, rock-cut in places. Panoramic views over surrounding countryside on all sides.		
Ownership	Private	Date of Inspection	16/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Included on information board in Granard town, although this is not in a very accessible location. Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford. J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891. P. 256, Joy Burns and Bernadette Grier (eds), "Granard - its history, our heritage". Granard Guild I.C.A., Longford, 1987
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided. Information on 1930s statue of St. Patrick available on the National Inventory of Architectural Heritage, http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13305004
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Frame for sign present, but sign no longer present
Visibility	Highly visible monument in the landscape
Intervisibility	Due to prominent location, monument is intervisible with other monuments in the area, as well as Inch
Road Access	Access via small laneway from main road
Parking	Some parking possible at the RC Church, although this includes a walk to the monument. No parking at the monument.
Public Transport	Public transport to Granard town centre only.

Approach Topography	Slight slope on laneway leading to field
Approach Surface	Grassy laneway, probably soft and muddy in poor weather
Approach Safety	No visible hazards.
Approach Width	>1/8m Approach Gate width >800m but unopenable.
Gate type	Main field gate and stile now blocked by pallets and not accessible
Site Topography	Very undulating due to nature of monument with steep-sided banks and ditches, while the motte itself is steep-sided. Field in general is churned up by hoof-marks from grazing cattle
Site Paths	No paths present, although a break in the banks to the south does allow passage between them.
Paths Surfacing	
Paths Width	
Hazards	Grazing cattle in field. Some very steep drops from banks.
Maintenance	Not maintained
Condition of Monument	Good condition.
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>
	On-site Staff <input type="checkbox"/>
	On-site Seating <input type="checkbox"/>
	On-site Toilets <input type="checkbox"/>
On-site facilities	None.
Notes	

RMP Ref: LF-	010-080002	Monument	Hilltop Enclosure
Location/ Townland	Granard, Moatfield	National Grid Ref:	232980 <i>E</i> 280693 <i>N</i>
		RPS Ref	
		National Monument Ref	263
Description	Large enclosure with impressive banks and fosse, surrounding motte and bailey (LF010-080001).		
Ownership	Private	Date of Inspection	16/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Included on information board in Granard town, although this is not in a very accessible location. J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891. P. 256, Joy Burns and Bernadette Grier (eds), "Granard - its history, our heritage". Granard Guild I.C.A., Longford, 1987
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Frame for sign present, but sign no longer present
Visibility	Highly visible monument in the landscape
Intervisibility	Due to prominent location, monument is intervisible with other monuments in the area, as well as Inch
Road Access	Access via small laneway from main road
Parking	Some parking possible at the RC Church, although this includes a walk to the monument. No parking at the monument.
Public Transport	Public transport to Granard town centre only.
Approach Topography	Slight slope on laneway leading to field
Approach Surface	Grassy laneway, probably soft and muddy in poor weather

Approach Safety	No visible hazards.	
Approach Width	>1/8m	Approach Gate width >800m but unopenable.
Gate type	Main field gate and stile now blocked by pallets and not accessible	
Site Topography	Very undulating due to nature of monument with steep-sided banks and ditches, while the motte is steep-sided. Field in general is churned up by hoof-marks from grazing cattle	
Site Paths	No paths present, although a break in the banks to the south does allow passage between them.	
Paths Surfacing		
Paths Width		
Hazards	Grazing cattle in field. Some very steep drops from banks.	
Maintenance	Not maintained	
Condition of Monument	Good condition.	
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>
	On-site Seating <input type="checkbox"/>	On-site Toilets <input type="checkbox"/>
On-site facilities	None.	
Notes		

RMP Ref: LF-	010-080003	Monument	Inauguration Site
Location/ Townland	Moatfield	National Grid Ref:	232985 <i>E</i> 280741 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Inauguration site of the O'Farrells. Exact location unknown but associated with motte (LF010-080001) and enclosure (LF010-080002).		
Ownership	Private	Date of Inspection	16/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Included on information board in Granard town, although this is not in a very accessible location. J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891. P. 256, Joy Burns and Bernadette Grier (eds), "Granard - its history, our heritage". Granard Guild I.C.A., Longford, 1987
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Frame for sign present, but sign no longer present
Visibility	Highly visible monument in the landscape
Intervisibility	Due to prominent location, monument is intervisible with other monuments in the area, as well as Inch
Road Access	Access via small laneway from main road
Parking	Some parking possible at the RC Church, although this includes a walk to the monument. No parking at the monument.
Public Transport	Public transport to Granard town centre only.
Approach Topography	Slight slope on laneway leading to field
Approach Surface	Grassy laneway, probably soft and muddy in poor weather

Approach Safety	No visible hazards.	
Approach Width	>1/8m	Approach Gate width >800m but unopenable.
Gate type	Main field gate and stile now blocked by pallets and not accessible	
Site Topography	Very undulating due to nature of monument with steep-sided banks and ditches, while the motte is steep-sided. Field in general is churned up by hoof-marks from grazing cattle	
Site Paths	No paths present, although a break in the banks to the south does allow passage between them.	
Paths Surfacing		
Paths Width		
Hazards	Grazing cattle in field. Some very steep drops from banks.	
Maintenance	Not maintained	
Condition of Monument	Not identifiable.	
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>
	On-site Seating <input type="checkbox"/>	On-site Toilets <input type="checkbox"/>
On-site facilities	None.	
Notes		

RMP Ref: LF-	010-080004	Monument	Castle - Unclassified possible
Location/ Townland	Moatfield	National Grid Ref:	232998 <i>E</i> 280725 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	No upstanding remains visible.		
Ownership	Private	Date of Inspection	16/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Included on information board in Granard town, although this is not in a very accessible location. J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891. P. 256, Joy Burns and Bernadette Grier (eds), "Granard - its history, our heritage". Granard Guild I.C.A., Longford, 1987
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Frame for sign present, but sign no longer present
Visibility	Highly visible monument in the landscape
Intervisibility	Due to prominent location, monument is intervisible with other monuments in the area, as well as Inch
Road Access	Access via small laneway from main road
Parking	Some parking possible at the RC Church, although this includes a walk to the monument. No parking at the monument.
Public Transport	Public transport to Granard town centre only.
Approach Topography	Slight slope on laneway leading to field
Approach Surface	Grassy laneway, probably soft and muddy in poor weather

Approach Safety	No visible hazards.	
Approach Width	>1/8m	Approach Gate width >800m but unopenable.
Gate type	Main field gate and stile now blocked by pallets and not accessible	
Site Topography	Very undulating due to nature of monument with steep-sided banks and ditches, while the motte is steep-sided. Field in general is churned up by hoof-marks from grazing cattle	
Site Paths	No paths present, although a break in the banks to the south does allow passage between them.	
Paths Surfacing		
Paths Width		
Hazards	Grazing cattle in field. Some very steep drops from banks.	
Maintenance	Not maintained	
Condition of Monument	Not upstanding / non-extant.	
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>
	On-site Seating <input type="checkbox"/>	On-site Toilets <input type="checkbox"/>
On-site facilities	None.	
Notes		

RMP Ref: LF-	010-084	Monument	Ritual Site - Holy Well
Location/ Townland	Cartron (Granard By.)	National Grid Ref:	232603 <i>E</i> 280073 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Access to well is blocked by a recent widening and deepening of the stream and field boundary (fed by water from the well/spring). A stream opening has been created through stone wall at roadside and a seating area is provided here also.		
Ownership	Private	Date of Inspection	16/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Joy Burns and Bernadette Grier (eds), "Granard - its history, our heritage". Granard Guild I.C.A., Longford, 1987
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Access through 2 fields and in marshy land, containing grazing cattle
Parking	Parking is possible at the side of the main road, but not designated.
Public Transport	
Approach Topography	Upslope and marshy
Approach Surface	Marshy pasture
Approach Safety	Cattle grazing in fields
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Site was not accessible
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Not accessible
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Seating at side of road only. No facilities near site.
<i>Notes</i>	

RMP Ref: LF-	010-123	Monument	Cross-Inscribed Pillar
Location/ Townland	Grassyard		National Grid Ref: 232981 E 281834 N
		RPS Ref	
		National Monument Ref	
Description	Small pillar stone, less than 1m in height, with a small cross inscribed on one face. Located near field entrance.		
Ownership	Private	Date of Inspection	16/10/09
		Inspected By	SMcG
		Accessibility Rating	B/C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Only visible on approach through field
Intervisibility	
Road Access	Monument is located 2 fields away from public road
Parking	No designated parking
Public Transport	
Approach Topography	Initially steeply sloped, evening out closer to monument
Approach Surface	Pasture - soft ground
Approach Safety	Electric fences present between fields (but gates are present).
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Immediate surrounds are level.
<i>Site Paths</i>	No paths present
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Nearby electric fences. Possibility of cattle grazing in field.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	010-128	Monument	Standing Stone
Location/ Townland	Grassyard	National Grid Ref:	233104 E 281695 N
		RPS Ref	
		National Monument Ref	
Description	Small (less than 1m in height), sub-rectangular standing stone, superficially similar to LF010-123, which is located in a nearby field.		
Ownership	Private	Date of Inspection	16/10/09
		Inspected By	SMcG
		Accessibility Rating	B/C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Only visible on approach through field
Intervisibility	
Road Access	Monument is locate 2 fields away from public road
Parking	No designated parking. Roadside parking may be possible
Public Transport	
Approach Topography	Initially steeply sloping, levelling out near monument.
Approach Surface	Pasture - soft ground
Approach Safety	Electric fences present between fields (but gates are present).
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Immediate surrounds are level.
<i>Site Paths</i>	No paths present
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Nearby electric fences. Possibility of cattle grazing in field.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	011-009	Monument	Linear Earthwork
Location/ Townland	Abbeylara, Ballinrud East, Ballinrud Glebe, Ballinrud West, Carragh, Cartronbore, Springtown, Toberfelim, Tonymore North, Tonymore South, Tromra		National Grid Ref: 230790 E 284860 N
		RPS Ref	
		National Monument Ref	
Description	The Black Pig's Dyke (see also LF006-066 and LF010-018). Intermittent stretches of banks and ditches running between Lough Gowna and Lough Kinale. In parts consisting of bank and ditch, in other parts only the ditch is apparent.		
Ownership		Date of Inspection	
		Inspected By	
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in a list of places of interest under 'Heritage and Places' in Co. Longford at http://www.longfordtourism.ie Wikipedia entry at: http://en.wikipedia.org/wiki/Black_Pig's_Dyke
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	011-016	Monument	Stone Circle	
Location/ Townland	Cartronbore		National Grid Ref:	235376 <i>E</i> 281262 <i>N</i>
			RPS Ref	
			National Monument Ref	
Description	Circle consisting of 10 stones, 1 of which is partially buried and a second is broken. Two noticeable gaps in the circle may represent the location of 2 further stones. Two outlying stones extend towards the southeast.			
Ownership	Private	Date of Inspection	17/09/09	Inspected By SMcG Accessibility Rating D

Desk-Based Survey

Local Sources Information	Described on information board in Abbeylara. Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Vague directions from Abbeylara information board. Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included as 'Abbeylara Stone Circle' in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	No Entry sign on gate - not accessible to general public.
Visibility	Visible from main road
Intervisibility	
Road Access	Located adjacent to main road
Parking	No official parking
Public Transport	
Approach Topography	Generally level but uneven underfoot.
Approach Surface	Rough pasture
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	Field Gate - not open to public
<i>Site Topography</i>	Open field, under grazing.
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Field is part of working farm, grazed by cattle. Not accessible to the general public.
<i>Maintenance</i>	
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	011-024	Monument	Ecclesiastical Enclosure
Location/ Townland	Ballynacross, Toberfelim		National Grid Ref: 235440 <i>E</i> 280680 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Low enclosure bank with outer ditch apparent in places. Slightly raised central area. Full enclosure not readily apparent at ground level.		
Ownership	Private	Date of Inspection	
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	Intervisible with Toberfelim holy well (LF011-053) which is probably related.
Road Access	Located in field off driveway to Toberfelim House B&B
Parking	
Public Transport	
Approach Topography	Open field with uneven ground
Approach Surface	Pasture
Approach Safety	Field is part of working farm and grazed by sheep and cattle
Approach Width	
	Approach Gate width
Gate type	Field gate

<i>Site Topography</i>	Undulating pastureland.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Grazing animals, very uneven ground.
<i>Maintenance</i>	
<i>Condition of Monument</i>	Bisected by field boundary.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	011-032001	Monument	Graveyard
Location/ Townland	Kilbride	National Grid Ref:	235645 <i>E</i> 279841 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	No graveslabs or markers apparent. Raised mound, over 1.2m in height with some suggestion of a low internal bank. This bank has been damaged in placed by animals and where damage has occurred stone is visible within the bank.		
Ownership	Private	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#06 Kilbride Graveyard, Abbeylara. Not wheelchair accessible. No designated parking space. Private ownership (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Not visible until approach through field.
Intervisibility	The Cistercian Abbey at Abbeylara is visible.
Road Access	
Parking	
Public Transport	
Approach Topography	Undulating, steep rise near site.
Approach Surface	Muddy laneway and grass/pasture.
Approach Safety	Through open field which is part of farmland.
Approach Width	
	Approach Gate width

<i>Gate type</i>	Field gates.
<i>Site Topography</i>	Steep incline
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Within farmland so not accessible to general public.
<i>Maintenance</i>	
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	011-032002	Monument	Church possible
Location/ Townland	Kilbride	National Grid Ref:	235629 <i>E</i> 279843 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	No upstanding structural remains evident.		
Ownership	Private	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Not visible until approach through field.
Intervisibility	The Cistercian Abbey at Abbeylara is visible.
Road Access	
Parking	
Public Transport	
Approach Topography	Undulating, steep rise near site.
Approach Surface	Muddy laneway and grass/pasture.
Approach Safety	Through open field which is part of farmland.
Approach Width	
	Approach Gate width
Gate type	Field gates.

<i>Site Topography</i>	Steep incline
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Within farmland so not accessible to general public.
<i>Maintenance</i>	
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	011-036001	Monument	Religious House - Cistercian Monks
Location/ Townland	Abbeylara	National Grid Ref:	236581 <i>E</i> 279567 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Ruins of medieval abbey.		
Ownership	Public	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Included on information board in Abbeylara - located across main road. J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891. Pg. 157
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in historical places 'Around Longford County' at http://www.goireland.com/longford/attractions-activities.htm . A short, descriptive paragraph is provided, but it does not provide information regarding accessibility.
Internet Directions	

Field Survey:

Road Signs	Signpost from the main road in Abbeylara.
Site Signs	
Visibility	Easily seen from road
Intervisibility	
Road Access	Accessed via laneway from main road, (R396)
Parking	Small gravel-surfaced area for parking at end of laneway. Parking also possible along roadside.
Public Transport	Bus stop in Abbeylara, on Granard-Dublin route.
Approach Topography	Reasonably level laneway
Approach Surface	Loose Gravel
Approach Safety	No apparent hazards
Approach Width	2-lane width on laneway
	Approach Gate width >800mm

<i>Gate type</i>	Double gate - wide enough for car to pass through
<i>Site Topography</i>	Generally even path leading from carpark, slightly uneven ground around site.
<i>Site Paths</i>	Pathway leading from carpark to Abbey; elsewhere open grass-covered area.
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Uneven ground and slightly overgrown - possible unseen trip hazards
<i>Maintenance</i>	Generally well-kept; more frequent grass-cutting required
<i>Condition of Monument</i>	Ruined but appears structurally sound.
<i>Child friendly</i> <input checked="" type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Low ground lighting had been installed but lights were damaged at time of survey.
<i>Notes</i>	A second information panel relating to the Abbey itself would be useful at the entrance to the site (at path).

RMP Ref: LF-	011-036002	Monument	Sheela-na-gig
Location/ Townland	Abbeylara	National Grid Ref:	236575 <i>E</i> 279565 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Weathered carved stone figure, inset in wall of abbey ruins (LF011-036001). This is located within the abbey ruin, high on the south wall.		
Ownership	Public	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891. Pg. 157
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Signpost to Abbey from the main road in Abbeylara.
Site Signs	
Visibility	Difficult to find if location on Abbey wall not known. Abbey itself clearly visible from road.
Intervisibility	
Road Access	Accessed via laneway from main road, (R396)
Parking	Small gravel-surfaced area for parking at end of laneway. Parking also possible along roadside.
Public Transport	Bus stop in Abbeylara, on Granard-Dublin route.
Approach Topography	Reasonably level laneway and pathway.
Approach Surface	Loose Gravel
Approach Safety	No apparent hazards
Approach Width	2-lane width on laneway Approach Gate width >800mm
Gate type	Double gate - wide enough for car to pass through

<i>Site Topography</i>	Generally even path leading from carpark, slightly uneven ground around site.
<i>Site Paths</i>	Pathway leading from carpark to Abbey; elsewhere open grass-covered area.
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Uneven ground and slightly overgrown - possible unseen trip hazards
<i>Maintenance</i>	
<i>Condition of Monument</i>	Weathered appearance. Detail not readily apparent.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Low ground lighting had been installed but lights were damaged at time of survey.
<i>Notes</i>	

RMP Ref: LF-	011-036003	Monument	Church
Location/ Townland	Abbeylara	National Grid Ref:	236558 E 279598 N
		RPS Ref	
		National Monument Ref	
Description	Foundation level only - visible as rectangular stone outline to the northwest of the Abbey.		
Ownership	Public	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891. Pg. 157
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Signpost to Abbey from the main road in Abbeylara.
Site Signs	
Visibility	Abbey and graveyard are clearly visible from road.
Intervisibility	
Road Access	Accessed via laneway from main road, (R396)
Parking	Small gravel-surfaced area for parking at end of laneway. Parking also possible along roadside.
Public Transport	Bus stop in Abbeylara, on Granard-Dublin route.
Approach Topography	Reasonably level laneway and pathway.
Approach Surface	Loose Gravel
Approach Safety	No apparent hazards
Approach Width	2-lane width on laneway Approach Gate width >800mm
Gate type	Double gate - wide enough for car to pass through

<i>Site Topography</i>	Generally even path leading from carpark, slightly uneven ground around site.
<i>Site Paths</i>	Pathway leading from carpark to Abbey; elsewhere open grass-covered area.
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Uneven ground and slightly overgrown - possible unseen trip hazards
<i>Maintenance</i>	
<i>Condition of Monument</i>	Foundation stones only, partially overgrown.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Low ground lighting had been installed but lights were damaged at time of survey.
<i>Notes</i>	

RMP Ref: LF-	011-036004	Monument	Graveyard
Location/ Townland	Abbeylara	National Grid Ref:	236558 <i>E</i> 279577 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Graveyard associated with the Cistercian Abbey. Overgrown with grass, with some upstanding headstones.		
Ownership	Public	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Included on information board in Abbeylara - located across main road. J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891. Pg. 157
Local Sources Directions	
Graveyard Survey	#01 Abbeylara at Cistercian Abbey, Abbeylara. Wheelchair accessible from road to graveyard. Limited parking space available. Information panes on road outside site. References to site in Journals and books held in the Local Studies Section at Longford Library HQ (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Signpost to Abbey from the main road in Abbeylara.
Site Signs	
Visibility	Difficult to find if location on Abbey wall not known. Abbey itself clearly visible from road.
Intervisibility	
Road Access	Accessed via laneway from main road, (R396)
Parking	Small gravel-surfaced area for parking at end of laneway. Parking also possible along roadside.
Public Transport	Bus stop in Abbeylara, on Granard-Dublin route.
Approach Topography	Reasonably level laneway and pathway.
Approach Surface	Loose Gravel

Approach Safety	No apparent hazards	
Approach Width	2-lane width on laneway	Approach Gate width >800mm
Gate type	Double gate - wide enough for car to pass through	
Site Topography	Generally even path leading from carpark, slightly uneven ground around site.	
Site Paths	Pathway leading from carpark to Abbey; elsewhere open grass-covered area.	
Paths Surfacing		
Paths Width		
Hazards	Uneven ground and slightly overgrown - possible unseen trip hazards	
Maintenance		
Condition of Monument	Slightly overgrown.	
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>
	On-site Seating <input type="checkbox"/>	On-site Toilets <input type="checkbox"/>
On-site facilities	Low ground lighting had been installed but lights were damaged at time of survey.	
Notes		

RMP Ref: LF-	011-049	Monument	Crannog possible
Location/ Townland	Derragh Lough	National Grid Ref:	239631 <i>E</i> 279263 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Low reed-encircled island at southern edge of lake. Not generally accessible to public although readily viewed from lake edge. Lake amenable to small fishing boats.		
Ownership	Private	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information on Derragh lough and Crannogs on information board at Abbeylara. Information regarding crannogs on Derragh Lough is included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Good directions given in S. Moore's (2007) book.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Roadsigns for Derragh Lough on main road
Site Signs	
Visibility	Good visibility from road and from lake edge
Intervisibility	Intervisible with second crannog (LF011-051).
Road Access	A public laneway runs from the main road to the lakeshore.
Parking	Parking at lakeshore for c.10 cars. Not sufficient space for a bus.
Public Transport	
Approach Topography	Laneway
Approach Surface	Tarmac,
Approach Safety	No through road, so little traffic
Approach Width	>1.8m
	Approach Gate width

<i>Gate type</i>	Cattle grid present.
<i>Site Topography</i>	Site not accessible
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Approachable only by boat; uncertain of suitability for landing. Lakeshore itself is unfenced.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	overgrown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	Two further RMP sites have recently been added on the shores of Derragh Lough: a possible crannog (LF011-068) and a lithic scatter (LF011-074). Neither of these sites were apparent on the ground, but should be included in any information regarding the lake and crannogs. Although the islands themselves are not accessible, their context within the landscape can be experienced from the lakeshore. Information panels at the shore would enhance this experience, along with a viewing platform and seating.

RMP Ref: LF-	011-050	Monument	Ritual Site - Holy Well
Location/ Townland	Ballyboy	National Grid Ref:	235969 E 278440 N
		RPS Ref	
		National Monument Ref	
Description	Named as Toberreendoney. The well was not apparent during site inspection. The nearby ringfort (LIF011-040) was visible to the north east as a low mound.		
Ownership	Private	Date of Inspection	
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Monument not visible.
Intervisibility	
Road Access	Accessed through private lands only.
Parking	
Public Transport	
Approach Topography	
Approach Surface	Fields under pasture
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	Field gates.

<i>Site Topography</i>	Uneven
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	None
<i>Condition of Monument</i>	Overgrown or non-extant
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	011-051	Monument	Crannog possible
Location/ Townland	Derragh Lough	National Grid Ref:	239486 E 279469 N
		RPS Ref	
		National Monument Ref	
Description	Low tree-covered, reed encircled island in the centre of Derragh Lough. Not generally accessible to public although readily viewed from lake edge. Lake amenable to small fishing boats.		
Ownership	Private	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information on Derragh lough and Crannogs on information board at Abbeylara.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Roadsigns for Derragh Lough on main road
Site Signs	
Visibility	Good visibility from road and from lake edge
Intervisibility	Intervisible with second crannog (LF011-049).
Road Access	A public laneway runs from the main road to the lakeshore.
Parking	Parking at lakeshore for c.10 cars. Not sufficient space for a bus.
Public Transport	
Approach Topography	Laneway
Approach Surface	Tarmac,
Approach Safety	No through road, so little traffic
Approach Width	>1.8m
	Approach Gate width
Gate type	Cattle grid present.

<i>Site Topography</i>	Site not accessible
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Approachable only by boat; uncertain of suitability for landing. Lakeshore itself is unfenced.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	overgrown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	Two further RMP sites have recently been added on the shores of Derragh Lough: a possible crannog (LF011-068) and a lithic scatter (LF011-074). Neither of these sites were apparent on the ground, but should be included in any information regarding the lake and crannogs. Although the islands themselves are not accessible, their context within the landscape can be experienced from the lakeshore. Information panels at the shore would enhance this experience, along with a viewing platform and seating.

RMP Ref: LF-	011-053	Monument	Ritual Site - Holy Well
Location/ Townland	Toberfelim	National Grid Ref:	235645 <i>E</i> 280584 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Only visible as natural wet area in field. Well may have been filled in.		
Ownership	Private	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Marked on map on information board at Abbeylara, but not precise location		
Site Signs			
Visibility	Not readily apparent		
Intervisibility			
Road Access	Access through private lands only		
Parking			
Public Transport			
Approach Topography	Uneven ground		
Approach Surface	Field under pasture		
Approach Safety			
Approach Width		Approach Gate width	
Gate type	Field gate		

<i>Site Topography</i>	Uneven ground, wet and muddy ground which is disturbed by cattle.
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Not identifiable
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	On private lands, utilised by grazing cattle. Holy well is not readily identifiable and appears to have gone out of use, with no evidence of a public right-of-way. It cannot be considered accessible to the general public.

RMP Ref: LF-	011-057	Monument	Ritual Site - Holy Well
Location/ Townland	Abbeylara	National Grid Ref:	236370 E 279690 N
		RPS Ref	
		National Monument Ref	
Description	Tobernamaneeve. Located at side of laneway. Stone superstructure over well, incorporated into stone wall. Step leads down to water level. Locked iron gate at entrance to well.		
Ownership	Public	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	No signpost but location indicated on information board in Abbeylara		
Site Signs			
Visibility	Not visible from road, but easily recognisable on laneway		
Intervisibility			
Road Access	Accessed via laneway from main road.		
Parking	Parking in Abbeylara and along street		
Public Transport	Public transport to Abbeylara		
Approach Topography	Level laneway		
Approach Surface	Compact gravel		
Approach Safety	pedestrian access, no traffic.		
Approach Width	c.1.2m	Approach Gate width	
Gate type	No gate		

<i>Site Topography</i>	Well located at side of laneway
<i>Site Paths</i>	Laneway runs by well.
<i>Paths Surfacing</i>	Compact gravel
<i>Paths Width</i>	c.1.2m
<i>Hazards</i>	Well is protected by metal gate (locked). Step up at entrance to well may present trip hazard to people with vision impairment.
<i>Maintenance</i>	Wall and superstructure appears well maintained but some litter has drifted or been thrown into well itself giving a dirty appearance.
<i>Condition of Monument</i>	Secure structure.
<i>Child friendly</i> <input checked="" type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	Lighting in general area would be beneficial as trees and bushes along laneway obscure light.

RMP Ref: LF-	013-016001	Monument	Church
Location/ Townland	Templemichael Glebe	National Grid Ref:	214272 E 276030 N
		RPS Ref	
		National Monument Ref	
Description	Heavily overgrown ruins of stone-built church.		
Ownership	Private	Date of Inspection	28/09/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Poor visibility due to overgrowth
Intervisibility	
Road Access	Located off private laneway
Parking	
Public Transport	
Approach Topography	Level ground
Approach Surface	Grass-covered garden area
Approach Safety	No apparent hazards
Approach Width	
	Approach Gate width
Gate type	

<i>Site Topography</i>	Uneven ground, heavily overgrown.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Structural stone on church remains and graveyard wall are not secure; uneven ground and overgrowth with tree roots and brambles present hazards in navigating the site.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Fragile, overgrown.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	Clearance of site to make it accessible would impinge on the archaeological integrity of the site and its setting. As this site is privately owned, permission is required to visit the site.

RMP Ref: LF-	013-016002	Monument	Graveyard
Location/ Townland	Templemichael Glebe	National Grid Ref:	214209 <i>E</i> 276045 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Heavily overgrown graveyard associated with church remains (LF013-016001). Only 2 gravestones are visible in the overgrowth.		
Ownership	Private	Date of Inspection	28/09/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#21 Templemichael Glebe Graveyard, Ballymacormack & Templemichael. Not wheelchair accessible. No designated parking. No pathways. Private ownership (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Poor visibility due to overgrowth
Intervisibility	
Road Access	Located off private laneway
Parking	
Public Transport	
Approach Topography	Level ground
Approach Surface	Grass-covered garden area
Approach Safety	No apparent hazards
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	Uneven ground, heavily overgrown.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Structural stone on church remains and graveyard wall are not secure; uneven ground and overgrowth with tree roots and brambles present hazards in navigating the site.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Fragile, overgrown.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	Clearance of site to make it accessible would impinge on the archaeological integrity of the site and its setting. As this site is privately owned, permission is required to visit the site.

RMP Ref: LF-	013-018	Monument	Church
Location/ Townland	Cloondara (aka Clondra)	National Grid Ref:	206170 E 275880 N
		RPS Ref	
		National Monument Ref	
Description	Stone-built large rectangular structure, unroofed. Evidence of reconstruction work to secure building at some time in the past. Windows have been largely blocked up. An annexe to the main building is roofed in stone with a stairs (now blocked off); the entrance to this room appears to have been reconstructed.		
Ownership	Public	Date of Inspection	
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Clearly visible at side of road.
Intervisibility	
Road Access	Adjacent to main road
Parking	Parking at roadside only
Public Transport	
Approach Topography	Even - sidewalk.
Approach Surface	Concrete
Approach Safety	No pedestrian crossing.
Approach Width	>1.8m
Approach Gate width	>800mm
Gate type	Double gate

<i>Site Topography</i>	Site is generally level but with graves and grave markers both inside and outside church
<i>Site Paths</i>	Paths between new church and ruined church, extending along 2 sides of the ruins and in parts of the graveyard. Grassed surface within ruins.
<i>Paths Surfacing</i>	Concrete and tarmac throughout
<i>Paths Width</i>	Generally c.1.2m, except path from entrance to new church which is c.2m
<i>Hazards</i>	No apparent hazards
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Appears structurally sound.
<i>Child friendly</i> <input checked="" type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	Variety of features associated with church and graveyard. The moveable monuments (cross-slabs and bullaun stone) are located within cases adjacent to the new church, making them very accessible. Information regarding known history of the site and the types of features present would be beneficial.

RMP Ref: LF-	013-018001	Monument	Bullaun Stone
Location/ Townland	Cloondara (aka Clondra)	National Grid Ref:	206180 <i>E</i> 275880 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Large stone with artificial circular hollow, located adjacent to new church (not original location).		
Ownership	Public	Date of Inspection	
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Clearly visible once inside main gate to church/graveyard
Intervisibility	
Road Access	Adjacent to main road
Parking	Parking at roadside only
Public Transport	
Approach Topography	Even - sidewalk.
Approach Surface	Concrete
Approach Safety	No pedestrian crossing.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Double gate

<i>Site Topography</i>	Level area outside modern church
<i>Site Paths</i>	Concrete path from gate to church - bullaun stone lies at edge of this
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.2m
<i>Hazards</i>	no apparent hazards
<i>Maintenance</i>	Area is well maintained
<i>Condition of Monument</i>	good condition
<i>Child friendly</i> <input checked="" type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	Variety of features associated with church and graveyard. The moveable monuments (cross-slabs and bullaun stone) are located within cases adjacent to the new church, making them very accessible. Information regarding known history of the site and the types of features present would be beneficial.

RMP Ref: LF-	013-018002	Monument	Cross-Slab
Location/ Townland	Cloondara (aka Clondra)	National Grid Ref:	206180 <i>E</i> 275870 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	One of 2 inscribed cross-slabs now encased in display frames and located adjacent to enclosing wall near modern church.		
Ownership	Public	Date of Inspection	
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Clearly visible once inside main gate to church/graveyard
Intervisibility	
Road Access	Adjacent to main road
Parking	Parking at roadside only
Public Transport	
Approach Topography	Even - sidewalk.
Approach Surface	Concrete
Approach Safety	No pedestrian crossing.
Approach Width	>1.8m
Approach Gate width	>800mm
Gate type	Double gate

<i>Site Topography</i>	Level area outside modern church
<i>Site Paths</i>	Concrete path from gate to church - bullaun stone lies at edge of this
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.2m
<i>Hazards</i>	no apparent hazards
<i>Maintenance</i>	Area is well maintained
<i>Condition of Monument</i>	Protected from elements by casing.
<i>Child friendly</i> <input checked="" type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	Variety of features associated with church and graveyard. The moveable monuments (cross-slabs and bullaun stone) are located within cases adjacent to the new church, making them very accessible. Information regarding known history of the site and the types of features present would be beneficial.

RMP Ref: LF-	013-018003	Monument	Cross-Slab
Location/ Townland	Cloondara (aka Clondra)	National Grid Ref:	206180 <i>E</i> 275870 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	One of 2 inscribed cross-slabs now encased in display frames and located adjacent to enclosing wall near modern church.		
Ownership	Public	Date of Inspection	
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Clearly visible once inside main gate to church/graveyard
Intervisibility	
Road Access	Adjacent to main road
Parking	Parking at roadside only
Public Transport	
Approach Topography	Even - sidewalk.
Approach Surface	Concrete
Approach Safety	No pedestrian crossing.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Double gate

<i>Site Topography</i>	Level area outside modern church
<i>Site Paths</i>	Concrete path from gate to church - bullaun stone lies at edge of this
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.2m
<i>Hazards</i>	no apparent hazards
<i>Maintenance</i>	Area is well maintained
<i>Condition of Monument</i>	Protected from elements by casing.
<i>Child friendly</i> <input checked="" type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	Variety of features associated with church and graveyard. The moveable monuments (cross-slabs and bullaun stone) are located within cases adjacent to the new church, making them very accessible. Information regarding known history of the site and the types of features present would be beneficial.

RMP Ref: LF-	013-018004	Monument	Graveyard		
Location/ Townland	Cloondara (aka Clondra)		National Grid Ref:	206170	E
				275880	N
			RPS Ref		
			National Monument Ref		
Description	Neatly laid out graveyard, with a combination of older and recent headstones.				
Ownership	Public	Date of Inspection		Inspected By	SMcG
				Accessibility Rating	A

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#70 Clondra Graveyard, Killashee. Wheelchair accessible to church. No designated parking spaces. Private Access (RC church) (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Clearly visible once inside main gate to church/graveyard
Intervisibility	
Road Access	Adjacent to main road
Parking	Parking at roadside only
Public Transport	
Approach Topography	Even - sidewalk.
Approach Surface	Concrete
Approach Safety	No pedestrian crossing.

Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	Double gate		
Site Topography	Site is generally level but with graves and grave markers both inside and outside church		
Site Paths	Paths between new church and ruined church, extending along 2 sides of the ruins and in parts of the graveyard. Grassed surface within ruins.		
Paths Surfacing	Concrete and tarmac throughout		
Paths Width	Generally c.1.2m, except path from entrance to new church which is c.2m		
Hazards	No apparent hazards		
Maintenance	Well maintained		
Condition of Monument			
Child friendly <input checked="" type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities			
Notes	Variety of features associated with church and graveyard. The moveable monuments (cross-slabs and bullaun stone) are located within cases adjacent to the new church, making them very accessible. Information regarding known history of the site and the types of features present would be beneficial.		

RMP Ref: LF-	013-026	Monument	Historic Town				
Location/ Townland	Abbeycartron, Deanscurragh, Demesne (Longford town)		National Grid Ref:	213086	E	275728	N
			RPS Ref				
			National Monument Ref				
Description	Historic part of Longford town.						
Ownership	Public	Date of Inspection	28/09/09	Inspected By	SMcG	Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Included in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	A number of information signs for tourists are located on Main St. and Market Square
Visibility	
Intervisibility	
Road Access	Main road through town
Parking	Pay and Display carpark in town centre
Public Transport	On main Bus Eireann bus route.
Approach Topography	Road
Approach Surface	Tarred, concrete
Approach Safety	Pedestrian crossings in town centre
Approach Width	
	Approach Gate width
Gate type	

<i>Site Topography</i>	Level ground
<i>Site Paths</i>	Road and pavements throughout
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	>1.8m
<i>Hazards</i>	None apparent
<i>Maintenance</i>	
<i>Condition of Monument</i>	
<i>Child friendly</i> <input checked="" type="checkbox"/>	<i>On-site Information</i> <input checked="" type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input checked="" type="checkbox"/> <i>On-site Toilets</i> <input checked="" type="checkbox"/>
<i>On-site facilities</i>	Tourist office present in town but staffed solely by volunteers.
<i>Notes</i>	

RMP Ref: LF-	013-026001	Monument	Religious House - Dominican Friars		
Location/ Townland	Abbeycartron (Longford town)		National Grid Ref:	213264 <i>E</i>	275742 <i>N</i>
			RPS Ref		
			National Monument Ref		
Description	Structure no longer extant. Two walls of the friary are contained within St. John's church, while other remains have been identified within the graveyard to the north of the church.				
Ownership	Public	Date of Inspection	28/09/09	Inspected By	SMcG
				Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information about the site (St. John's Church) included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign for St. John's Church, which is still in use
Visibility	Church visible from main road
Intervisibility	
Road Access	Adjacent to main road.
Parking	Public (pay and display) carpark located at front of site.
Public Transport	Public transport to Longford town
Approach Topography	Level ground in carpark
Approach Surface	Tarmac
Approach Safety	Carpark is located on same side of road as church, although public access to a residential estate runs through carpark
Approach Width	>1.8m
Approach Gate width	>800mm

<i>Gate type</i>	Double gates
<i>Site Topography</i>	Level ground
<i>Site Paths</i>	Paths to church and to part of associated graveyard (LF013-026003). However paths have high kerbs. No paths accessing southern part of graveyard.
<i>Paths Surfacing</i>	Tarmac
<i>Paths Width</i>	c.1.2m
<i>Hazards</i>	High kerbing
<i>Maintenance</i>	Area around church well maintained, southern part of graveyard is overgrown.
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	013-026002	Monument	Castle - Unclassified
Location/ Townland	Abbeycartron (Longford town)	National Grid Ref:	213264 E 275742 N
		RPS Ref	
		National Monument Ref	
Description	Non-extant. On same site as the Dominican friary / St. John's Church (LF013-026001).		
Ownership	Public	Date of Inspection	28/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign for St. John's Church, which is still in use
Visibility	Church visible from main road
Intervisibility	
Road Access	Adjacent to main road.
Parking	Public (pay and display) carpark located at front of site.
Public Transport	Public transport to Longford town
Approach Topography	Level ground in carpark
Approach Surface	Tarmac
Approach Safety	Carpark is located on same side of road as church, although public access to a residential estate runs through carpark
Approach Width	>1.8m
Approach Gate width	>800mm

<i>Gate type</i>	Double gates
<i>Site Topography</i>	Level ground
<i>Site Paths</i>	Paths to church and to part of associated graveyard (LF013-026003). However paths have high kerbs. No paths accessing southern part of graveyard.
<i>Paths Surfacing</i>	Tarmac
<i>Paths Width</i>	c.1.2m
<i>Hazards</i>	High kerbing
<i>Maintenance</i>	Area around church well maintained, southern part of graveyard is overgrown.
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	013-026003	Monument	Graveyard
Location/ Townland	Abbeycartron (Longford town)		National Grid Ref: 213280 <i>E</i> 275760 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Graveyard associated with St. John's Church.		
Ownership	Private	Date of Inspection	28/09/09
		Inspected By	SMcG
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#20 Saint John's Longford Graveyard, Ballymacormack & Templemichael. Wheelchair accessible to church and in newer section of graveyard. No designated parking. Private access (Church of Ireland) (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Signs relating to St. John's Church, which is still in use.
Visibility	Located at side of main road
Intervisibility	
Road Access	Adjacent to main road
Parking	Public carpark (Pay & Display) located to front
Public Transport	Public transport to Longford town centre.
Approach Topography	Level ground from carpark
Approach Surface	Tarmac
Approach Safety	Access to a residential estate runs through carpark, so some through traffic.

Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	Double wrought iron gates		
Site Topography	Fairly level ground		
Site Paths	Paths provide access to part of graveyard, but are bordered by kerbing. No paths in the southern part of the graveyard.		
Paths Surfacing	Tarmac		
Paths Width	c.1.2m		
Hazards	Partly overgrown and partially hidden gravemarkers may present trip hazards.		
Maintenance	Section of graveyard close to church is well maintained. Southern part is overgrown.		
Condition of Monument			
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	None.		
Notes			

RMP Ref: LF-	013-026004	Monument	Bridge (17th century)
Location/ Townland	Abbeycartron, Townparks (Longford town)		National Grid Ref: 213129 <i>E</i> 275603 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Camlin River Bridge. Originally built in 1718, rebuilt 1819, widened in 1993 and reopened 1995. Single arched masonry bridge. Not considered an RMP on the www.archaeology.ie website.		
Ownership	Public	Date of Inspection	28/09/09
		Inspected By	SMcG
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	Included in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Plaques on bridge detailing dates of construction and reconstruction.
Visibility	Located at the northern end of Main St.
Intervisibility	Intervisible with main part of historic town.
Road Access	Main street in Longford crossed over bridge.
Parking	Public carpark (Pay & Display) is located at the front of St. John's Church, and there is access from there to the river walk.
Public Transport	Public transport to town centre
Approach Topography	A path running along riverside allows views of one side of bridge, while a newly constructed footbridge accessing Longford town centre will allow further views when it is opened.
Approach Surface	Tarmac pathway, with stone steps leading up to bridge
Approach Safety	Located at river bank, which is unfenced.
Approach Width	>1.8m, but no access ramp for
	Approach Gate width

	wheelchairs.
<i>Gate type</i>	
<i>Site Topography</i>	Level bridge.
<i>Site Paths</i>	Footpath along river and across bridge, allow for viewing.
<i>Paths Surfacing</i>	Tarmac and concrete
<i>Paths Width</i>	>1.8m
<i>Hazards</i>	No barrier along river. Busy road crossing over bridge.
<i>Maintenance</i>	Well maintained with street lighting
<i>Condition of Monument</i>	Little if any of original monument remaining.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	013-032001	Monument	Church
Location/ Townland	Mullaghavorneen	National Grid Ref:	211869 <i>E</i> 272852 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Ruined remains of rectangular stone-built church. Three walls and part of 4th surviving, although much overgrown with ivy. Door also survives. Burials plots are evident in the interior. A stone holy water font is visible inside the church. Associated with graveyard LF013-032002.		
Ownership	Public	Date of Inspection	25/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Signs for Ballymacormack Graveyard
Site Signs	Sign present at new entrance to graveyard, none at the older entrance.
Visibility	Visible at side of road
Intervisibility	
Road Access	Two main roads run adjacent to church and graveyard
Parking	Space for parking at roadside, opposite graveyard
Public Transport	
Approach Topography	Level
Approach Surface	Tarmac pathway
Approach Safety	No pedestrian crossing on busy roads.
Approach Width	c.1.4m in width Approach Gate width >800mm
Gate type	Gates located at newer section of graveyard. Double gate leading to older part is locked

Site Topography	Uphill slope in new part of graveyard, although the older part is level. Uneven ground in interior of church.
Site Paths	Paths run through graveyard, although less in the older section
Paths Surfacing	Tarmac
Paths Width	1 - 2m along central line
Hazards	Overgrowth in older section may hide low grave markers or loose stone. Stability of church ruin is unknown.
Maintenance	Generally well maintained, although some overgrowth in older part of graveyard and church is partly ivy covered.
Condition of Monument	Ruined but largely upstanding.
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/> On-site Staff <input type="checkbox"/> On-site Seating <input checked="" type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	Seating located outside church ruins.
Notes	

RMP Ref: LF-	013-032002	Monument	Graveyard		
Location/ Townland	Mullaghavorneen	National Grid Ref:	211870	<i>E</i>	272878
		RPS Ref			
		National Monument Ref			
Description	Graveyard associated with church LF013-032002. Still in use, having been expanded from original size. One possible older gravestone was noted - a small rectangular grave marker with a simple roughly carved cross.				
Ownership	Public	Date of Inspection	25/09/09	Inspected By	SMcG
				Accessibility Rating	B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#16 Ballymacormack (Mullaghvorneen) Graveyard, Ballymacormack & Templemichael. Partly wheelchair accessible. No designated parking space. Gravel and concrete pathways. Public access (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Signs for Ballymacormack Graveyard
Site Signs	Sign present at new entrance to graveyard, none at the older entrance.
Visibility	Visible at side of road
Intervisibility	
Road Access	Two main roads run adjacent to church and graveyard
Parking	Space for parking at roadside, opposite graveyard
Public Transport	
Approach Topography	Level
Approach Surface	Tarmac pathway
Approach Safety	No pedestrian crossing on busy roads.

Approach Width	c.1.4m in width	Approach Gate width	>800mm
Gate type	Gates located at newer section of graveyard. Double gate leading to older part is locked		
Site Topography	Uphill slope in new part of graveyard, although the older part is level. Uneven ground in interior of church.		
Site Paths	Paths run through graveyard, although less in the older section		
Paths Surfacing	Tarmac		
Paths Width	1 - 2m along central line		
Hazards	Overgrowth in older section may hide low grave markers or loose stone. Stability of church ruin is unknown.		
Maintenance	Generally well maintained, although some overgrowth in older part of graveyard and church is partly ivy covered.		
Condition of Monument	Partly overgrown.		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input checked="" type="checkbox"/>
On-site facilities	Seating located outside church.		
Notes			

RMP Ref: LF-	013-034	Monument	Church possible
Location/ Townland	Aghafad	National Grid Ref:	211870 <i>E</i> 272878 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	No remains visible		
Ownership	Public	Date of Inspection	28/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Located at end of small residential estate
Parking	On-street parking is possible in the adjacent residential estate
Public Transport	
Approach Topography	Level
Approach Surface	Tarmac, concrete.
Approach Safety	No through road so access traffic only.
Approach Width	>1.8m
	Approach Gate width
Gate type	No gate

<i>Site Topography</i>	Disturbed ground, much overgrown and uneven.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Level of overgrowth, uneven footing. Appears as area of wasteground beside residential estate.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	No upstanding remains visible
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	013-034001	Monument	Ecclesiastical Enclosure
Location/ Townland	Aghafad	National Grid Ref:	213340 E 273840 N
		RPS Ref	
		National Monument Ref	
Description	Enclosure not identifiable. Open, overgrown area at one end of a small residential estate. Ground appears to have been disturbed, possibly during construction of the housing estate.		
Ownership	Public	Date of Inspection	28/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Located at end of small residential estate
Parking	On-street parking is possible in the adjacent residential estate
Public Transport	
Approach Topography	Level
Approach Surface	Tarmac, concrete.
Approach Safety	No through road so access traffic only.
Approach Width	>1.8m
Gate type	No gate
	Approach Gate width

<i>Site Topography</i>	Disturbed ground, much overgrown and uneven.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Level of overgrowth, uneven footing. Appears as area of wasteground beside residential estate.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	No upstanding remains visible
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	013-034002	Monument	Cross-Inscribed Pillar (original location)				
Location/ Townland	Aghafad		National Grid Ref:	213340	E	273850	N
			RPS Ref				
			National Monument Ref				
Description	See also LF013-034003 - Cross Inscribed Pillar (Present Location). Stone was not identifiable and a local source indicated it may have been removed to Longford museum when the housing estate was built.						
Ownership	Public	Date of Inspection	28/09/09	Inspected By	SMcG	Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs		
Site Signs		
Visibility		
Intervisibility		
Road Access	Located at end of small residential estate	
Parking	On-street parking is possible in the adjacent residential estate	
Public Transport		
Approach Topography	Level	
Approach Surface	Tarmac, concrete.	
Approach Safety	No through road so access traffic only.	
Approach Width	>1.8m	
Gate type	No gate	
	Approach Gate width	

<i>Site Topography</i>	Disturbed ground, much overgrown and uneven.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Level of overgrowth, uneven footing. Appears as area of wasteground beside residential estate.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Not identifiable / non-extant.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	013-034003	Monument	Cross-Inscribed Pillar (present location)		
Location/ Townland	Townparks (Longford By.)		National Grid Ref:	213493	E
				275309	N
			RPS Ref		
			National Monument Ref		
Description	See also LF013-034004 - Cross Inscribed Pillar (Original Location). Stone was not identifiable and a local source indicated it was removed to Longford museum when the housing estate was built. Current status is unknown as the museum is now closed with plans to remove artefacts to longterm storage in St. Mel's College, following repackaging and conservation works.				
Ownership	Public	Date of Inspection	28/09/09	Inspected By	SMcG
				Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

Site Topography

Site Paths

Paths Surfacing

Paths Width

Hazards

Maintenance

Condition of Monument

Child friendly *On-site Information* *On-site Staff* *On-site Seating* *On-site Toilets*

On-site facilities

Notes

RMP Ref: LF-	013-045001	Monument	Ecclesiastical Enclosure possible				
Location/ Townland	Ballynakill	National Grid Ref:	204805	E	271929	N	
		RPS Ref					
		National Monument Ref					
Description	Some suggestion of an outer enclosure, outside the graveyard is preserved in the field boundaries, but this is not clearly identifiable.						
Ownership	Public	Date of Inspection	30/09/09	Inspected By	SMcG	Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Included on Tourist Information board at Killashee.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs			
Site Signs			
Visibility	Not readily apparent		
Intervisibility			
Road Access	Laneway leads from road to graveyard.		
Parking	Small parking area (for c.10-12 cars) located on opposite side of road.		
Public Transport			
Approach Topography	Level laneway		
Approach Surface	Grass lane, well-kept		
Approach Safety	No pedestrian crossing from parking area, but road is quiet with little traffic.		
Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	Double wrought-iron gate and small 'kissing gate' leading from laneway to site with a second set of		

	similar gate and 'kissing gate' leading to inner enclosure of graveyard.
<i>Site Topography</i>	Overall fairly level, but ground is uneven due to antiquity of graveyard.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	Grass cover throughout site
<i>Paths Width</i>	
<i>Hazards</i>	Uneven underfoot in parts.
<i>Maintenance</i>	Generally well-kept
<i>Condition of Monument</i>	Enclosure is not readily identifiable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input checked="" type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Bench provided in graveyard. Two small information plaques for the 'Pre-Norman Grave Stones' and a graveslab 'Known locally as the Bishop's Grave' are now nearly illegible. No lighting within site.
<i>Notes</i>	

RMP Ref: LF-	013-045002	Monument	Church
Location/ Townland	Ballynakill	National Grid Ref:	204808 E 271918 N
		RPS Ref	
		National Monument Ref	
Description	Two walls of church partially survive within the graveyard (LF013-045001). A display of cross-slabs and architectural fragments mounted on a concrete display area is located along one of the walls.		
Ownership	Public	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Included on Tourist Information board at Killashee.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible within graveyard
Intervisibility	
Road Access	Laneway leads from road to graveyard.
Parking	Small parking area (for c.10-12 cars) located on opposite side of road.
Public Transport	
Approach Topography	Level laneway
Approach Surface	Grass lane, well-kept
Approach Safety	No pedestrian crossing from parking area, but road is quiet with little traffic.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Double wrought-iron gate and 'kissing gate' leading from laneway to site with a second set of similar

	gate and 'kissing gate', leading to inner enclosure of graveyard.
<i>Site Topography</i>	Overall fairly level, but ground is uneven due to antiquity of graveyard.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	Grass cover throughout site
<i>Paths Width</i>	
<i>Hazards</i>	Uneven underfoot in parts.
<i>Maintenance</i>	Generally well-kept
<i>Condition of Monument</i>	Ruined. Church represented by 2 low, dry-stone walls.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input checked="" type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Bench provided in graveyard. Two small information plaques for the 'Pre-Norman Grave Stones' and a graveslab 'Known locally as the Bishop's Grave' are now nearly illegible. No lighting within site.
<i>Notes</i>	

RMP Ref: LF-	013-045003	Monument	Architectural Fragment(s)
Location/ Townland	Ballynakill	National Grid Ref:	204796 <i>E</i> 271926 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Uncertain as to what fragments this refers. There are numerous architectural fragments scattered around church and graveyard, some reused at grave markers. A decorated fragment is included on the concreted display wall, situated on top of a plinth at one top corner of the arch.		
Ownership	Public	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Included on Tourist Information board at Killashee.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible within graveyard
Intervisibility	
Road Access	Laneway leads from road to graveyard.
Parking	Small parking area (for c.10-12 cars) located on opposite side of road.
Public Transport	
Approach Topography	Level laneway
Approach Surface	Grass lane, well-kept
Approach Safety	No pedestrian crossing from parking area, but road is quiet with little traffic.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Double wrought-iron gate and 'kissing gate' leading from laneway to site with a second set of similar

	gate and 'kissing gate' leading to inner enclosure of graveyard.
<i>Site Topography</i>	Overall fairly level, but ground is uneven due to antiquity of graveyard.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	Grass cover throughout site
<i>Paths Width</i>	
<i>Hazards</i>	Uneven underfoot in parts.
<i>Maintenance</i>	Generally well-kept
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input checked="" type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Bench provided in graveyard. Two small information plaques for the 'Pre-Norman Grave Stones' and a graveslab 'Known locally as the Bishop's Grave' are now nearly illegible. No lighting within site.
<i>Notes</i>	

RMP Ref: LF-	013-045004	Monument	Cross-Slab
Location/ Townland	Ballynakill	National Grid Ref:	204817 E 271918 N
		RPS Ref	
		National Monument Ref	
Description	Mounted onto an upright, arched concrete display, located along one wall of the church.		
Ownership	Public	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Included on Tourist Information board at Killashee.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible within graveyard
Intervisibility	
Road Access	Laneway leads from road to graveyard.
Parking	Small parking area (for c.10-12 cars) located on opposite side of road.
Public Transport	
Approach Topography	Level laneway
Approach Surface	Grass lane, well-kept
Approach Safety	No pedestrian crossing from parking area, but road is quiet with little traffic.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Double wrought-iron gate and 'kissing gate' leading from laneway to site with a second set of similar

	gate and 'kissing gate' leading to inner enclosure of graveyard.
<i>Site Topography</i>	Overall fairly level, but ground is uneven due to antiquity of graveyard.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	Grass cover throughout site
<i>Paths Width</i>	
<i>Hazards</i>	Uneven underfoot in parts.
<i>Maintenance</i>	Generally well-kept
<i>Condition of Monument</i>	Fragment.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input checked="" type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Bench provided in graveyard. Two small information plaques for the 'Pre-Norman Grave Stones' and a graveslab 'Known locally as the Bishop's Grave' are now nearly illegible. No lighting within site.
<i>Notes</i>	

RMP Ref: LF-	013-045006	Monument	Bullaun Stone		
Location/ Townland	Ballynakill		National Grid Ref:	204802	E
				271935	N
			RPS Ref		
			National Monument Ref		
Description	Located within graveyard LF013-045001. Stone with circular depression, embedded in ground. Partly filled with water at time of survey.				
Ownership	Public	Date of Inspection	30/09/09	Inspected By	SMcG
				Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Included on Tourist Information board at Killashee.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible within graveyard
Intervisibility	
Road Access	Laneway leads from road to graveyard.
Parking	Small parking area (for c.10-12 cars) located on opposite side of road.
Public Transport	
Approach Topography	Level laneway
Approach Surface	Grass lane, well-kept
Approach Safety	No pedestrian crossing from parking area, but road is quiet with little traffic.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Double wrought-iron gate and 'kissing gate' leading from laneway to site with a second set of similar

	gate and 'kissing gate' leading to inner enclosure of graveyard.
<i>Site Topography</i>	Overall fairly level, but ground is uneven due to antiquity of graveyard.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	Grass cover throughout site
<i>Paths Width</i>	
<i>Hazards</i>	Uneven underfoot in parts.
<i>Maintenance</i>	Generally well-kept
<i>Condition of Monument</i>	Good condition
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input checked="" type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Bench provided in graveyard. Two small information plaques for the 'Pre-Norman Grave Stones' and a graveslab 'Known locally as the Bishop's Grave' are now nearly illegible. No lighting within site.
<i>Notes</i>	

RMP Ref: LF-	013-045009	Monument	Graveyard		
Location/ Townland	Ballynakill	National Grid Ref:	204800	<i>E</i>	271920
		RPS Ref			
		National Monument Ref			
Description	Enclosed graveyard, well maintained. Contains modern graves and older ones. Enclosed by stone wall, curved at the southern end and containing some impressively sized stones.				
Ownership	Public	Date of Inspection	30/09/09	Inspected By	SMcG
				Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Included on Tourist Information board at Killashee.
Local Sources Directions	
Graveyard Survey	#69 Ballynakill Graveyard, Killashee. Not wheelchair accessible. Limited parking space. Accessed through private lands. Still in use in 2004 (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible within graveyard
Intervisibility	
Road Access	Laneway leads from road to graveyard.
Parking	Small parking area (for c.10-12 cars) located on opposite side of road.
Public Transport	
Approach Topography	Level laneway
Approach Surface	Grass lane, well-kept
Approach Safety	No pedestrian crossing from parking area, but road is quiet with little traffic.

Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	Double wrought-iron gate and 'kissing gate' leading from laneway to site with a second set of similar gate and 'kissing gate' leading to inner enclosure of graveyard.		
Site Topography	Overall fairly level, but ground is uneven due to antiquity of graveyard.		
Site Paths	None		
Paths Surfacing	Grass cover throughout site		
Paths Width			
Hazards	Uneven underfoot in parts.		
Maintenance	Generally well-kept		
Condition of Monument	Good condition		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input checked="" type="checkbox"/>
On-site facilities	Bench provided in graveyard. Two small information plaques for the 'Pre-Norman Grave Stones' and a graveslab 'Known locally as the Bishop's Grave' are now nearly illegible. No lighting within site.		
Notes			

RMP Ref: LF-	013-045010	Monument	Cross-Slab
Location/ Townland	Ballynakill	National Grid Ref:	204817 E 271918 N
		RPS Ref	
		National Monument Ref	
Description	Mounted onto an upright, arched concrete display, located along one wall of the church.		
Ownership	Public	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Included on Tourist Information board at Killashee.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible within graveyard
Intervisibility	
Road Access	Laneway leads from road to graveyard.
Parking	Small parking area (for c.10-12 cars) located on opposite side of road.
Public Transport	
Approach Topography	Level laneway
Approach Surface	Grass lane, well-kept
Approach Safety	No pedestrian crossing from parking area, but road is quiet with little traffic.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Double wrought-iron gate and 'kissing gate' leading from laneway to site with a second set of similar

	gate and 'kissing gate' leading to inner enclosure of graveyard.
<i>Site Topography</i>	Overall fairly level, but ground is uneven due to antiquity of graveyard.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	Grass cover throughout site
<i>Paths Width</i>	
<i>Hazards</i>	Uneven underfoot in parts.
<i>Maintenance</i>	Generally well-kept
<i>Condition of Monument</i>	Fragment.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input checked="" type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Bench provided in graveyard. Two small information plaques for the 'Pre-Norman Grave Stones' and a graveslab 'Known locally as the Bishop's Grave' are now nearly illegible. No lighting within site.
<i>Notes</i>	

RMP Ref: LF-	013-045011	Monument	Cross-Slab
Location/ Townland	Ballynakill	National Grid Ref:	204817 E 271918 N
		RPS Ref	
		National Monument Ref	
Description	Mounted onto an upright, arched concrete display, located along one wall of the church.		
Ownership	Public	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Included on Tourist Information board at Killashee.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible within graveyard
Intervisibility	
Road Access	Laneway leads from road to graveyard.
Parking	Small parking area (for c.10-12 cars) located on opposite side of road.
Public Transport	
Approach Topography	Level laneway
Approach Surface	Grass lane, well-kept
Approach Safety	No pedestrian crossing from parking area, but road is quiet with little traffic.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Double wrought-iron gate and 'kissing gate' leading from laneway to site with a second set of similar

	gate and 'kissing gate' leading to inner enclosure of graveyard.
<i>Site Topography</i>	Overall fairly level, but ground is uneven due to antiquity of graveyard.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	Grass cover throughout site
<i>Paths Width</i>	
<i>Hazards</i>	Uneven underfoot in parts.
<i>Maintenance</i>	Generally well-kept
<i>Condition of Monument</i>	Fragment.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input checked="" type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Bench provided in graveyard. Two small information plaques for the 'Pre-Norman Grave Stones' and a graveslab 'Known locally as the Bishop's Grave' are now nearly illegible. No lighting within site.
<i>Notes</i>	

RMP Ref: LF-	013-045012	Monument	Cross-Slab
Location/ Townland	Ballynakill	National Grid Ref:	204817 <i>E</i> 271918 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Mounted onto an upright, arched concrete display, located along one wall of the church.		
Ownership	Public	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Included on Tourist Information board at Killashee.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible within graveyard
Intervisibility	
Road Access	Laneway leads from road to graveyard.
Parking	Small parking area (for c.10-12 cars) located on opposite side of road.
Public Transport	
Approach Topography	Level laneway
Approach Surface	Grass lane, well-kept
Approach Safety	No pedestrian crossing from parking area, but road is quiet with little traffic.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Double wrought-iron gate and 'kissing gate' leading from laneway to site with a second set of similar

	gate and 'kissing gate' leading to inner enclosure of graveyard.
<i>Site Topography</i>	Overall fairly level, but ground is uneven due to antiquity of graveyard.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	Grass cover throughout site
<i>Paths Width</i>	
<i>Hazards</i>	Uneven underfoot in parts.
<i>Maintenance</i>	Generally well-kept
<i>Condition of Monument</i>	Fragment.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input checked="" type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Bench provided in graveyard. Two small information plaques for the 'Pre-Norman Grave Stones' and a graveslab 'Known locally as the Bishop's Grave' are now nearly illegible. No lighting within site.
<i>Notes</i>	

RMP Ref: LF-	013-045013	Monument	Cross-Slab
Location/ Townland	Ballynakill	National Grid Ref:	204817 E 271918 N
		RPS Ref	
		National Monument Ref	
Description	Mounted onto an upright, arched concrete display, located along one wall of the church.		
Ownership	Public	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Included on Tourist Information board at Killashee.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible within graveyard
Intervisibility	
Road Access	Laneway leads from road to graveyard.
Parking	Small parking area (for c.10-12 cars) located on opposite side of road.
Public Transport	
Approach Topography	Level laneway
Approach Surface	Grass lane, well-kept
Approach Safety	No pedestrian crossing from parking area, but road is quiet with little traffic.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Double wrought-iron gate and 'kissing gate' leading from laneway to site with a second set of similar

	gate and 'kissing gate' leading to inner enclosure of graveyard.
<i>Site Topography</i>	Overall fairly level, but ground is uneven due to antiquity of graveyard.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	Grass cover throughout site
<i>Paths Width</i>	
<i>Hazards</i>	Uneven underfoot in parts.
<i>Maintenance</i>	Generally well-kept
<i>Condition of Monument</i>	Fragment.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input checked="" type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Bench provided in graveyard. Two small information plaques for the 'Pre-Norman Grave Stones' and a graveslab 'Known locally as the Bishop's Grave' are now nearly illegible. No lighting within site.
<i>Notes</i>	

RMP Ref: LF-	013-057	Monument	Graveyard
Location/ Townland	Trillickatemple	National Grid Ref:	214000 E 217360 N
		RPS Ref	
		National Monument Ref	
Description	No above-ground features. A slightly raised sub-triangular bank encloses a slightly raised central area within a field. Marked as 'disused' on the 1914 OS map.		
Ownership	Private	Date of Inspection	28/09/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#22 Trillickatemple Graveyard, Ballymacormack & Templemichael. Not wheelchair accessible. No designated parking. Private ownership (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib/her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Located at side of main road
Parking	Parking possible at widened verge, on opposite side of road. Not designated.
Public Transport	
Approach Topography	Level
Approach Surface	Road and grass verge
Approach Safety	Main road, with no footpath and no pedestrian crossing at site.
Approach Width	>1.8m
Approach Gate width	>800mm

<i>Gate type</i>	Double field gate
<i>Site Topography</i>	Slightly uneven ground with low undulations over earthworks.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	Site is grass-covered field
<i>Paths Width</i>	
<i>Hazards</i>	Field is under grazing and animals may be present
<i>Maintenance</i>	None
<i>Condition of Monument</i>	Not readily identifiable. No upstanding graveyard features
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	013-058	Monument	Ritual Site - Holy Well
Location/ Townland	Bunacloy	National Grid Ref:	205730 E 272170 N
		RPS Ref	
		National Monument Ref	
Description	'Ardneev's Well'. Not accessible.		
Ownership	Private	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	No entry sign on field gate which reads 'Strictly Preserved No Entry Poison'
Visibility	Visible from road, as clump of trees and bushes in centre of field.
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

Site Topography

Site Paths

Paths Surfacing

Paths Width

Hazards

Maintenance

Condition of Monument

Child friendly *On-site Information* *On-site Staff* *On-site Seating* *On-site Toilets*

On-site facilities

Notes

RMP Ref: LF-	013-061	Monument	Fortification possible	
Location/ Townland	Abbeycartron (Longford town)		National Grid Ref:	213115 <i>E</i> 275655 <i>N</i>
			RPS Ref	
			National Monument Ref	
Description	No upstanding remains. The market house was built on the site of this fortification, now incorporated into the barracks. Not publicly accessible at present.			
Ownership	Public	Date of Inspection	28/09/09	Inspected By SMcG Accessibility Rating D

Desk-Based Survey

Local Sources Information	Included under 'Market House' in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in historical places 'Around Longford Town' at http://www.goireland.com/longford/attractions-activities.htm , under 'The Military Barracks'. A short, descriptive paragraph is provided, but it does not provide information regarding accessibility.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

Site Topography

Site Paths

Paths Surfacing

Paths Width

Hazards

Maintenance

Condition of Monument

Child friendly *On-site Information* *On-site Staff* *On-site Seating* *On-site Toilets*

On-site facilities

Notes

RMP Ref: LF-	014-049	Monument	Barrow - Ring-barrow possible
Location/ Townland	Moatfarrell	National Grid Ref:	223753 E 275868 N
		RPS Ref	
		National Monument Ref	
Description	Raised central mound surrounded by well-defined double ditch and bank. Partially overgrown.		
Ownership	Private	Date of Inspection	15/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Only visible on approach through field
Intervisibility	Intervisible with moated site (LF014-051), Fortified House (LF014-057) and Motte (LF014-050).
Road Access	Access is via two fields.
Parking	No designated parking. Parking may be possible at roadside.
Public Transport	
Approach Topography	Undulating pastureland, uneven ground
Approach Surface	Grass - under grazing
Approach Safety	Possibility of grazing animals in fields
Approach Width	
	Approach Gate width >800mm
Gate type	Field gates

<i>Site Topography</i>	Very undulating due to nature of monument - banks and ditches present
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Possible presence of grazing animals. Very uneven footing
<i>Maintenance</i>	None
<i>Condition of Monument</i>	Good condition with well-defined banks and ditches.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	014-050	Monument	Castle - Motte And Bailey
Location/ Townland	Moatfarrell	National Grid Ref:	223532 <i>E</i> 275417 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Substantial, steep-sided motte. A slightly raised area around the motte may represent the remains of a bailey. The motte is located on the highest point of a ridge, providing panoramic views from the summit. A ditch runs across the ridge on the northwest side. Numerous stones are strewn around the side, possibly originally from a structure. The O'Farrell clan rally is held here every few years, with access granted by the landowner.		
Ownership	Private	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Can be seen through trees, from the road.
Intervisibility	Intervisible with Fortified House (LF014-057), Moated Site (LF014-051) and Ring-barrow (LF014-049).
Road Access	Located in field beside road.
Parking	Layby at side of road with room for c.3-4 cars.
Public Transport	
Approach Topography	Steep incline uphill to base of motte.
Approach Surface	Uneven, pastureland.
Approach Safety	No pedestrian crossing on road, and no footpath. Sheep grazing in field.
Approach Width	
	Approach Gate width

<i>Gate type</i>	No gate at roadside. Gap in fence is used.
<i>Site Topography</i>	Steep sided. Very uneven ground as located in field of rough grazing, grazed by sheep.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Uneven footing and presence of grazing animals.
<i>Maintenance</i>	None
<i>Condition of Monument</i>	Good. Prominent monument.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	014-051	Monument	Moated Site
Location/ Townland	Moatfarrell	National Grid Ref:	223949 <i>E</i> 275440 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Rectangular enclosure with an internal bank, ditch and external bank. The banks have been damaged in places by grazing animals, forming routes into centre of enclosure. Heavily overgrown and overgrowth masks features and outline of the monument. Overall form of site is clearer from aerial photos than when viewing at ground level.		
Ownership	Private	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Only visible on approach through field
Intervisibility	Intervisible with Fortified House (LF014-057) and Motte (LF014-050)
Road Access	Access via two fields
Parking	No designated parking. Parking may be possible at roadside.
Public Transport	
Approach Topography	Undulating ground and uneven underfoot
Approach Surface	Pastureland with grassed-over field-path in first field.
Approach Safety	Possibility of grazing animals in fields
Approach Width	
	Approach Gate width >800mm
Gate type	Field gates, but second gate is damaged and not readily opened.

<i>Site Topography</i>	Monument is undulating by nature, with uneven ground.
<i>Site Paths</i>	No set paths. Tracks have been worn through the overgrowth by grazing animals.
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Grazing animals may be present.
<i>Maintenance</i>	
<i>Condition of Monument</i>	Partly overgrown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	014-052001	Monument	Church
Location/ Townland	Newtownbond	National Grid Ref:	221903 E 274944 N
		RPS Ref	
		National Monument Ref	
Description	Partial ruins of small stone church, with some loose stone. Interior is uneven and access is not possible. Associated with Newtownbond House, the ruins of which are visible to the west.		
Ownership	Private	Date of Inspection	16/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Hidden by overgrowth
Intervisibility	
Road Access	Accessed via a field laneway leading from main road to site.
Parking	No designated parking.
Public Transport	
Approach Topography	Fairly level field lane.
Approach Surface	
Approach Safety	Grazing animals in field. Field also enclosed by electric fence.
Approach Width	>1.8m Approach Gate width >800mm
Gate type	Field gate, with wrought-iron gate leading to graveyard. This latter is locked and cordoned off with

	barbed wire as is the adjacent stone, stepped stile.
<i>Site Topography</i>	Heavily overgrown and uneven underfoot.
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Large stand of nettles in immediate area of gate and stile; barbed wire running across gate and stile; heavy overgrowth disguising low grave markers and loose rubble from ruins.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Ruined and unstable. Heavily overgrown.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	014-052002	Monument	Graveyard
Location/ Townland	Newtownbond	National Grid Ref:	221910 <i>E</i> 274960 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Small graveyard associated with church ruins (LF014-052001). Graveyard is heavily overgrown and enclosed by modern fencing. 19th century headstones and graveslabs are visible.		
Ownership	Private	Date of Inspection	16/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#76 Newtownbond Graveyard, Killoe. Not wheelchair accessible. No designated parking spaces. Access through private land (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Hidden by overgrowth.
Intervisibility	
Road Access	Accessed via a field laneway leading from main road to site.
Parking	No designated parking.
Public Transport	
Approach Topography	Fairly level field lane.
Approach Surface	
Approach Safety	Grazing animals in field. Field also enclosed by electric fence.

Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	Field gate, with wrought-iron gate leading to graveyard. This latter is locked and cordoned off with barbed wire as is the adjacent stone, stepped stile.		
Site Topography	Heavily overgrown and uneven underfoot.		
Site Paths	No paths		
Paths Surfacing			
Paths Width			
Hazards	Large stand of nettles in immediate area of gate and stile; barbed wire running across gate and stile; heavy overgrowth disguising low grave markers and loose rubble from ruins.		
Maintenance	Not maintained		
Condition of Monument	Heavily overgrown.		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	None.		
Notes			

RMP Ref: LF-	014-052003	Monument	Graveslab (17th century)
Location/ Townland	Newtownbond	National Grid Ref:	221903 <i>E</i> 274944 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Located in graveyard (LF014-052002). Not identifiable due to level of overgrowth in graveyard.		
Ownership	Private	Date of Inspection	16/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Hidden by overgrowth.
Intervisibility	
Road Access	Accessed via a field laneway leading from main road to site.
Parking	No designated parking.
Public Transport	
Approach Topography	Fairly level field lane.
Approach Surface	
Approach Safety	Grazing animals in field. Field also enclosed by electric fence.
Approach Width	>1.8m Approach Gate width >800mm
Gate type	Field gate, with wrought-iron gate leading to graveyard. This latter is locked and cordoned off with

	barbed wire as is the adjacent stone, stepped stile.
<i>Site Topography</i>	Heavily overgrown and uneven underfoot.
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Large stand of nettles in immediate area of gate and stile; barbed wire running across gate and stile; heavy overgrowth disguising low grave markers and loose rubble from ruins.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Heavily overgrown.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	014-055	Monument	Ringfort - Rath
Location/ Townland	Moatfarrell	National Grid Ref:	223370 E 275000 N
		RPS Ref	
		National Monument Ref	
Description	Sub-rectangular enclosure, built up on one side to create level area, as surrounding ground level slopes down steeply to west. Enclosed by a very low bank, not apparent for entire circumference. Hawthorn trees and scrub grow along southern bank.		
Ownership	Private	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	B/C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from roadside.
Intervisibility	
Road Access	Close to main road
Parking	Parking possible in small layby on opposite side of road.
Public Transport	
Approach Topography	Ground slopes gently down to site.
Approach Surface	Grass
Approach Safety	No footpath or pedestrian crossing on road.
Approach Width	
	Approach Gate width >800mm
Gate type	No gate present - open gateway.

<i>Site Topography</i>	Monument itself is level, but surrounding ground slopes down to west.
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Western edge of ringfort drops off sharply.
<i>Maintenance</i>	Not maintained but grass in field very short at time of survey.
<i>Condition of Monument</i>	Not prominent in field.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	014-057	Monument	House - Fortified House
Location/ Townland	Moatfarrell	National Grid Ref:	223860 E 274930 N
		RPS Ref	
		National Monument Ref	
Description	Ruined rectangular stone building located in field, but separated from rest of field by fence. Building is located in a slight depression and interior of building is marshy.		
Ownership	Private	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from road as ruin located behind farm.
Intervisibility	Intervisible with Motte (LF014-050) and Graveyard (LF014-058).
Road Access	Accessed through farmyard from public road - permission required
Parking	No parking at site.
Public Transport	
Approach Topography	Fairly level field, but uneven ground and slopes down closer to house. Area close to house has been churned up by animals and is muddy.
Approach Surface	Grass, bare earth
Approach Safety	Animals grazing in field
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate; must cross fence to access building itself.

<i>Site Topography</i>	Uneven ground in interior,
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Uneven, marshy ground; animals present in field.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Ruined but stable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	014-058001	Monument	Church
Location/ Townland	Moatfarrell	National Grid Ref:	223765 E 274680 N
		RPS Ref	
		National Monument Ref	
Description	Ruins of small dry-stone walled church within graveyard LF014-058002. Ruin appears unstable and is very overgrown in the interior		
Ownership	Public?	Date of Inspection	16/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from road, but partially obscured by hedges along roadside.
Intervisibility	Intervisible with Fortified House (LF014-057) to the north.
Road Access	Adjacent to main road
Parking	No designated parking. Parking at roadside may be possible.
Public Transport	
Approach Topography	Steep overgrown slope immediately inside entrance gate, leading up to site.
Approach Surface	Overgrown grass
Approach Safety	No footpath along road, overgrowth hides uneven ground surface.
Approach Width	>1.8m Approach Gate width >800mm
Gate type	Metal railing gate, heavy and requires strength to open it.

<i>Site Topography</i>	Uneven ground in graveyard
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Uneven footing, overgrowth and hidden stones and rubble present trip hazards. Church ruins also appear unstable.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Ruined, unstable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	014-058002	Monument	Graveyard
Location/ Townland	Moatfarrell	National Grid Ref:	223765 <i>E</i> 274680 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Small walled graveyard associated with ruined church (LF014-058001). Heavily overgrown with upright headstones visible throughout.		
Ownership	Public?	Date of Inspection	16/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#33 Moatfarrell Graveyard, Clonbroney. Not wheelchair accessible. No designated parking. No pathways. In private ownership (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from road, but partially obscured by hedges along roadside.
Intervisibility	Intervisible with Fortified House (LF014-057) to the north.
Road Access	Adjacent to main road
Parking	No designated parking. Parking at roadside may be possible.
Public Transport	
Approach Topography	Steep overgrown slope immediately inside entrance gate, leading up to site.
Approach Surface	Overgrown grass
Approach Safety	No footpath along road, overgrowth hides uneven ground surface.

Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	Metal railing gate, heavy and requires strength to open it.		
Site Topography	Uneven ground in graveyard		
Site Paths	No paths		
Paths Surfacing			
Paths Width			
Hazards	Uneven footing, overgrowth and hidden stones and rubble present trip hazards. Church ruins also appear unstable.		
Maintenance	Not maintained		
Condition of Monument	Ruined, unstable.		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	None.		
Notes			

RMP Ref: LF-	014-066	Monument	Ringfort - Rath		
Location/ Townland	Feraghfad		National Grid Ref:	216393 E	273486 N
			RPS Ref		
			National Monument Ref		
Description	Large ringfort enclosed by earthen bank and ditch. Bank has been damaged by cattle.				
Ownership	Private	Date of Inspection	16/09/09	Inspected By	SMcG
				Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	Intervisible with holy well (LF014-118)
Road Access	Farm lane leads from main road to field containing monument
Parking	No designated parking
Public Transport	
Approach Topography	Undulating ground. Ground is generally uneven and grass covered.
Approach Surface	Grass
Approach Safety	No footpath along roadside. Field entrance located on bend in road. Barbed wire and electric fencing along field.
Approach Width	
	Approach Gate width >800mm

<i>Gate type</i>	Barbed-wire fence. Not easily opened.
<i>Site Topography</i>	Uneven.
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Electric and barbed wire fences in field; cattle present in field.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Damaged by cattle.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	014-078	Monument	Church
Location/ Townland	Corboy	National Grid Ref:	<input type="text"/> E <input type="text"/> N
		RPS Ref	56
		National Monument Ref	<input type="text"/>
Description	Oldest Presbyterian church still in use, outside of Ulster. Built in 1729 and restored in the 1990's. Not considered an RMP on the www.archaeology.ie website.		
Ownership	Private	Date of Inspection	16/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	<input type="text"/>
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	<input type="text"/>
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	<input type="text"/>
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	Sign at junction on main road, for Presbyterian Church
Site Signs	Large sign, containing historical information, at entrance to church and graveyard.
Visibility	Visible from main road, although partly obscured by trees
Intervisibility	<input type="text"/>
Road Access	Accessed via small main road, set back slightly from road.
Parking	Parking space for a number of cars.
Public Transport	<input type="text"/>
Approach Topography	Level, tarmac laneway
Approach Surface	Tarmac
Approach Safety	No visible hazards
Approach Width	>1.8m Approach Gate width >2m
Gate type	Double metal railing gate to carpark and also to graveyard. Slightly stiff to open.

<i>Site Topography</i>	Slight slope on pathways.
<i>Site Paths</i>	Two pathways leading from gate to church.
<i>Paths Surfacing</i>	Tarmac with loose gravel on top.
<i>Paths Width</i>	Wider path is >2m, second path is >1m wide.
<i>Hazards</i>	Step at doorway to church.
<i>Maintenance</i>	Well maintained. Still in use as church.
<i>Condition of Monument</i>	Good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input checked="" type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input checked="" type="checkbox"/> <i>On-site Toilets</i> <input checked="" type="checkbox"/>
<i>On-site facilities</i>	Toilet in church not wheelchair accessible. Lighting in carpark and over church doorway. Seats in church.
<i>Notes</i>	

RMP Ref: LF-	014-092001	Monument	Church
Location/ Townland	Aghintemple		National Grid Ref: 217909 <i>E</i> 272142 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Little remains upstanding - some foundations level walls.		
Ownership	Private	Date of Inspection	16/09/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	No wheelchair access. No designated parking. On private land (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Have to traverse 2 fields to get to monument, crossing fences and ditches.
Parking	No parking area.
Public Transport	
Approach Topography	Uneven ground. Field boundary ditches, fences and electric fences must be crossed.
Approach Surface	Grass
Approach Safety	Have to cross ditches, fences and electric fences.
Approach Width	<input type="text"/> Approach Gate width >800mm

<i>Gate type</i>	Field gate, partially off its hinges, and no safe entrance through electric fence.
<i>Site Topography</i>	Uneven ground. Ground has been disturbed by grazing cattle.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Cattle present, electric fence around field, open ditch around enclosure.
<i>Maintenance</i>	None
<i>Condition of Monument</i>	Poor.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	014-092002	Monument	Ecclesiastical Enclosure
Location/ Townland	Aghintemple	National Grid Ref:	217909 E 272141 N
		RPS Ref	
		National Monument Ref	
Description	Partially obscured and amalgamated into field boundary.		
Ownership	Private	Date of Inspection	16/09/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Have to traverse 2 fields to get to monument, crossing fences and ditches.
Parking	No parking area.
Public Transport	
Approach Topography	Uneven ground. Field boundary ditches, fences and electric fences must be crossed.
Approach Surface	Grass
Approach Safety	Have to cross ditches, fences and electric fences.
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate, partially off its hinges, and no safe entrance through electric fence.

<i>Site Topography</i>	Uneven ground. Ground has been disturbed by grazing cattle.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Cattle present, electric fence around field, open ditch around enclosure.
<i>Maintenance</i>	None
<i>Condition of Monument</i>	Not readily apparent.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	014-118	Monument	Ritual Site - Holy Well
Location/ Townland	Feraghfad	National Grid Ref:	216440 <i>E</i> 273590 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Not identifiable / non-extant. Numerous stones in the vicinity may be related.		
Ownership	Private	Date of Inspection	16/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Not visible
Intervisibility	
Road Access	Accessed via field lane and field, from main road.
Parking	
Public Transport	
Approach Topography	Very undulating with uneven ground
Approach Surface	Rough pasture
Approach Safety	Both electric- and barbed-wire fencing present. Ditches around field.
Approach Width	
	Approach Gate width >800m
Gate type	Barbed wire - must be untangled.

<i>Site Topography</i>	Very uneven footing with numerous rocks and depressions in the area.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Uneven footing represents trip hazards. Nearby electric fence and barbed wire fences.
<i>Maintenance</i>	Not maintained.
<i>Condition of Monument</i>	Site is no longer extant.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	015-061	Monument	Ritual Site - Holy Well
Location/ Townland	Abbey Land	National Grid Ref:	224903 <i>E</i> 271348 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	St. Mary's Well. Not readily identifiable as heavily overgrown. Stone-lined well, overgrown with brambles, nettles and other weed-plants.		
Ownership	Private	Date of Inspection	16/09/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Not readily visible
Intervisibility	
Road Access	Accessed via private lane / driveway.
Parking	None
Public Transport	
Approach Topography	Lane is fairly even, but open grassy area between lane and monument.
Approach Surface	Gravel, grass
Approach Safety	Beside open stream; well is near hidden by tangled overgrowth, including nettles & brambles.
Approach Width	>1.8m
	Approach Gate width
Gate type	No gate present.

<i>Site Topography</i>	Overgrown grass between land and well.
<i>Site Paths</i>	No paths present
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Well is nearly hidden with tangled overgrowth, with no indication of its presence.
<i>Maintenance</i>	No maintenance.
<i>Condition of Monument</i>	Heavily overgrown; no longer in use.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	015-062	Monument	Church possible
Location/ Townland	Abbey Land	National Grid Ref:	224995 E 271352 N
		RPS Ref	
		National Monument Ref	
Description	Not readily identifiable. Outline of stone-built rectangular building visible within enclosure, but very poorly preserved with quantities of stone and rubble strewn around.		
Ownership	Private	Date of Inspection	16/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Not readily visible
Intervisibility	
Road Access	Accessed via open ground from main road or private driveway.
Parking	None
Public Transport	
Approach Topography	Undulating ground interspersed with streams
Approach Surface	Rough pasture, marshy areas and open streams and ditches.
Approach Safety	No means for crossing streams; no footpath on main road; very uneven ground close to monument.
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Very uneven as partially wooded, with stones and rubble strewn around.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Loose stones and presence of tree roots and woodland debris present numerous trip hazards.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Very poor. Largely collapsed.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	015-063	Monument	Historic Town (17th century)
Location/ Townland	Edgeworthstown, Tinnynarr		National Grid Ref: 225930 <i>E</i> 271810 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Established by the Edgeworth family on land granted to them in the 16th century. The town itself primarily dates to the 18th and 19th century. Some of the earlier buildings in the town are outlined on the information board in the town.		
Ownership	Public/Private	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Signs for Edgeworthstown		
Site Signs	Information board and map located at one end of the town.		
Visibility			
Intervisibility	Individual RMPs within the town.		
Road Access	Main road runs through town.		
Parking	Street parking in town.		
Public Transport			
Approach Topography	Fairly level footpaths.		
Approach Surface	Concrete, tarmac		
Approach Safety	Pedestrian crossing in centre of town.		
Approach Width	>1.8m	Approach Gate width	
Gate type			

<i>Site Topography</i>	Fairly level
<i>Site Paths</i>	Street pavement throughout
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	>1.8m
<i>Hazards</i>	No visible hazards.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input checked="" type="checkbox"/> <i>On-site Staff</i> <input checked="" type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Street lighting; tourist office present in town - independent establishment.
<i>Notes</i>	Local, independently run tourist information office is located in the old schoolhouse and has information on the Edgeworth family and some of the O'Farrells.

RMP Ref: LF-	015-063002	Monument	Church
Location/ Townland	Edgeworthstown	National Grid Ref:	226062 E 272007 N
		RPS Ref	213
		National Monument Ref	
Description	St. John's Church. 18th century church on site of a series of earlier churches. No visible upstanding remains of earlier remains. Associated with graveyard (LF015-063005).		
Ownership	Private	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	Wheelchair access to church only. No designated parking spaces. Private access (Church of Ireland) (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Signposts for church from the Main St. in town
Site Signs	Information sign at gate with historical and architectural information, previous example surveyed badly damaged. New plaque erected in August 2011.
Visibility	Visible from approach road, not from Main St.
Intervisibility	Intervisible with graveyard (LF015-063005).
Road Access	Road to one side of graveyard in residential estate. Driveway leading to church
Parking	Parking available within housing estate across road.
Public Transport	Public transport available to town centre.
Approach Topography	Level road
Approach Surface	Tarmac and gravel
Approach Safety	No pedestrian crossing, but little traffic on road as leading to residential estate only.

Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	Double, wrought iron gate. However, kept locked at church not in frequent use.		
Site Topography	Slight incline on driveway leading to church.		
Site Paths	Driveway through part of graveyard, to church; centre aisle within church.		
Paths Surfacing	Tarmac		
Paths Width	>1.8m		
Hazards	No visible hazards		
Maintenance	Well maintained. Church still in use, although infrequently.		
Condition of Monument	Earlier remains - non-extant. Present church - good condition.		
Child friendly	<input type="checkbox"/>	On-site Information	<input checked="" type="checkbox"/>
		On-site Staff	<input type="checkbox"/>
		On-site Seating	<input checked="" type="checkbox"/>
		On-site Toilets	<input type="checkbox"/>
On-site facilities	No external lighting.		
Notes			

RMP Ref: LF-	015-063003	Monument	House - 16th/17th century
Location/ Townland	Edgeworthstown	National Grid Ref:	226060 E 271644 N
		RPS Ref	232
		National Monument Ref	
Description	Edgeworthstown House. Once the family home of the Edgeworth family, the house is now a Nursing Home. Built in the 1720's.		
Ownership	Private	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	B/C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign for 'Manor Nursing Home' at entrance from main road.
Visibility	Visible from main road.
Intervisibility	Intervisible with historic town of Edgeworthstown (LF015-063)
Road Access	Driveway from main road to house
Parking	Designated parking at nursing home. However, on day of survey a garden bench had been placed in a disabled parking space.
Public Transport	Public transport to Edgeworthstown.
Approach Topography	Gentle incline from main road to house.
Approach Surface	Tarmac
Approach Safety	No footpath along entrance driveway.
Approach Width	>1.8m
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	Fairly level ground
<i>Site Paths</i>	Paths provided around grounds. House itself is a private nursing home.
<i>Paths Surfacing</i>	Tarmac, concrete and hardcore pathways around grounds.
<i>Paths Width</i>	>1.8m
<i>Hazards</i>	No visible hazards.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input checked="" type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Some outdoor lighting. No historical information about house on-site.
<i>Notes</i>	

RMP Ref: LF-	015-063005	Monument	Graveyard
Location/ Townland	Edgeworthstown	National Grid Ref:	226058 E 272018 N
		RPS Ref	
		National Monument Ref	
Description	Graveyard associated with St. John's Church (LF015-063002). Largely 18th/19th century gravemarkers visible but a few unusual, possibly earlier examples.		
Ownership	Private	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#85 Saint John's Edgeworthstown, Mostrim. Currently closed; wheelchair access to church only; private ownership (C of I) (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Signposts for church from the Main St. in town
Site Signs	Information sign at gate with historical and architectural information, surveyed example was damaged. Replaced in August 2011.
Visibility	Visible from approach road, not from Main St.
Intervisibility	Intervisible with Church (LF015-063002).
Road Access	Road to one side of graveyard in residential estate. Driveway leading to church
Parking	Parking available within housing estate across road.
Public Transport	Public transport available to town centre.
Approach Topography	Level road
Approach Surface	Tarmac and gravel
Approach Safety	No pedestrian crossing, but little traffic on road as leading to residential estate only.

Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	Double, wrought iron gate. However, kept locked at church not in frequent use.		
Site Topography	Slight incline on driveway leading to church.		
Site Paths	Driveway through part of graveyard, to church; centre aisle within church.		
Paths Surfacing	Tarmac		
Paths Width	>1.8m		
Hazards	No visible hazards		
Maintenance	Well maintained. Church still in use, although infrequently.		
Condition of Monument	Earlier remains - non-extant. Present church - good condition.		
Child friendly <input type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input checked="" type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	No external lighting.		
Notes			

RMP Ref: LF-	015-063006	Monument	Deerpark Boundary (17th century)
Location/ Townland	Edgeworthstown	National Grid Ref:	<input type="text"/> E <input type="text"/> N
		RPS Ref	<input type="text"/>
		National Monument Ref	<input type="text"/>
Description	Not listed as an RMP on the www.archaeology.ie website. Uncertain as to what this refers. A well-build, high stone wall exists close to the house, but appears to be a garden feature (e.g.. a walled garden) rather than the limit of a deer-park. Local sources had no knowledge of the presence of a deer-park.		
Ownership	Private	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	<input type="text"/>
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	<input type="text"/>
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	<input type="text"/>
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	Sign for 'Manor Nursing Home' at entrance from main road.
Visibility	Not readily identifiable.
Intervisibility	Intervisible with historic town of Edgeworthstown (LF015-063)
Road Access	Driveway from main road to house
Parking	Designated parking at nursing home. However, on day of survey a garden bench had been placed in a disabled parking space.
Public Transport	Public transport to Edgeworthstown.
Approach Topography	Gentle incline from main road to house.
Approach Surface	Tarmac
Approach Safety	No footpath along entrance driveway.
Approach Width	>1.8m
Approach Gate width	<input type="text"/>

<i>Gate type</i>	
<i>Site Topography</i>	Fairly level ground
<i>Site Paths</i>	Paths provided around grounds. No set path to wall.
<i>Paths Surfacing</i>	Tarmac, concrete and hardcore pathways around grounds. Grass access to wall.
<i>Paths Width</i>	>1.8m
<i>Hazards</i>	No visible hazards.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input checked="" type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Some outdoor lighting. No historical information about house on-site.
<i>Notes</i>	

RMP Ref: LF-	015-073	Monument	Monumental Structure
Location/ Townland	Edgeworthstown	National Grid Ref:	225990 E 271530 N
		RPS Ref	
		National Monument Ref	
Description	Not identifiable.		
Ownership	Private	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

Site Topography

Site Paths

Paths Surfacing

Paths Width

Hazards

Maintenance

Condition of Monument

Child friendly *On-site Information* *On-site Staff* *On-site Seating* *On-site Toilets*

On-site facilities

Notes

RMP Ref: LF-	015-075	Monument	Church
Location/ Townland	Firmount	National Grid Ref:	226180 E 275820 N
		RPS Ref	
		National Monument Ref	
Description	Non-extant. Site is occupied by former gatehouse, now a private residence.		
Ownership	Private	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

Site Topography

Site Paths

Paths Surfacing

Paths Width

Hazards

Maintenance

Condition of Monument

Child friendly *On-site Information* *On-site Staff* *On-site Seating* *On-site Toilets*

On-site facilities

Notes

RMP Ref: LF-	016-011	Monument	Ritual Site - Holy Well
Location/ Townland	Kilfintan	National Grid Ref:	234329 <i>E</i> 275527 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Not identifiable.		
Ownership	Private	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Access via field lane/track
Parking	None
Public Transport	
Approach Topography	Uneven ground.
Approach Surface	Soft ground, grass and bare earth.
Approach Safety	
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Field gates, rusted and in poor condition.

<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Electric fences in vicinity.
<i>Maintenance</i>	
<i>Condition of Monument</i>	Monument could not be located.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	016-015001	Monument	Church
Location/ Townland	Coolamber	National Grid Ref:	234172 E 273718 N
		RPS Ref	
		National Monument Ref	
Description	Ruins of church. Heavily overgrown.		
Ownership	Public	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from main road
Intervisibility	Intervisible with castle LF016-18
Road Access	Access lane leading from minor road to graveyard
Parking	No designated parking. Parking at grass verge may be possible.
Public Transport	
Approach Topography	Gentle incline to graveyard
Approach Surface	Hardcore/gravel laneway
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width >2m
Gate type	New gate was being installed at time of survey

<i>Site Topography</i>	Overgrown and uneven underfoot
<i>Site Paths</i>	No paths to older part of graveyard, and church. Difference in height from new path makes access difficult.
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Uneven footing.
<i>Maintenance</i>	Older part of graveyard with church ruins is not maintained.
<i>Condition of Monument</i>	Overgrown, ruined.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	016-015002	Monument	Graveyard
Location/ Townland	Coolamber	National Grid Ref:	234172 <i>E</i> 273711 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Graveyard associated with church ruins (LF016-015001). Some early 18th century graveslabs/headstones identifiable. Heavily overgrown and partly damaged during recent excavation and laying of a new concrete path at edge of older graveyard.		
Ownership	Public	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#95 Coolamber Graveyard, Streete. Wheelchair access extends to entrance area only. No designated parking. Public access. Gravel pathways in new section (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from main road
Intervisibility	Intervisible with castle LF016-18
Road Access	Access lane leading from minor road to graveyard
Parking	No designated parking. Parking at grass verge may be possible.
Public Transport	
Approach Topography	Gentle incline to graveyard but sharp increase in ground level from new to old graveyard due to new concrete path.
Approach Surface	Hardcore/gravel laneway
Approach Safety	No visible hazards

Approach Width	>1.8m	Approach Gate width	>2m
Gate type	New gate was being installed at time of survey		
Site Topography	Overgrown and uneven underfoot		
Site Paths	No paths to older part of graveyard, and church. Difference in height from new path makes access difficult.		
Paths Surfacing			
Paths Width			
Hazards	Uneven footing.		
Maintenance	Older part of graveyard with church ruins is not maintained.		
Condition of Monument	Heavily overgrown, damaged at edge.		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities			
Notes			

RMP Ref: LF-	016-018001	Monument	House - Fortified House (17th century)
Location/ Townland	Coolamber	National Grid Ref:	234577 E 273444 N
		RPS Ref	
		National Monument Ref	
Description	Ruined fortified house, on same site as Ringworks castle (LF016-018003) and bawn (LF016-018002). Not stable, with masonry strewn around. Situated on prominent rise, encircled by ditch/moat feature.		
Ownership	Private	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford. J.P. Farrell, "History of County Longford", Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Extant remains of house are very prominent and visible from road.
Intervisibility	
Road Access	Accessed via small country laneway.
Parking	No designated parking
Public Transport	
Approach Topography	Fairly level, field.
Approach Surface	Pasture, grass
Approach Safety	Located at side of quiet lane

<i>Approach Width</i>		<i>Approach Gate width</i>	>800mm
<i>Gate type</i>	Field gate, but not in good condition - partly off its hinges and unopenable.		
<i>Site Topography</i>	Very undulating with ditch/moat and steep rise on which house/castle is located.		
<i>Site Paths</i>	None		
<i>Paths Surfacing</i>			
<i>Paths Width</i>			
<i>Hazards</i>	Very uneven ground, with loose stones; overgrowth; unstable ruins with unsecured openings.		
<i>Maintenance</i>	Not maintained		
<i>Condition of Monument</i>	ruinous, unstable, graffiti on interior walls.		
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>	<i>On-site Staff</i> <input type="checkbox"/>	<i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.		
<i>Notes</i>			

RMP Ref: LF-	016-018002	Monument	Bawn
Location/ Townland	Coolamber	National Grid Ref:	234574 E 273433 N
		RPS Ref	
		National Monument Ref	
Description	Associated with castle - ringworks (LF016-018003) and fortified house (LF016-018001).		
Ownership	Private	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford. J.P. Farrell, "History of County Longford", Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Accessed via small country laneway.
Parking	No designated parking
Public Transport	
Approach Topography	Fairly level, field.
Approach Surface	Pasture, grass
Approach Safety	Located at side of quiet lane

<i>Approach Width</i>		<i>Approach Gate width</i>	>800mm
<i>Gate type</i>	Field gate, but not in good condition - partly off its hinges and unopenable.		
<i>Site Topography</i>	Very undulating with ditch/moat and steep rise on which house/castle is located.		
<i>Site Paths</i>	None		
<i>Paths Surfacing</i>			
<i>Paths Width</i>			
<i>Hazards</i>	Very uneven ground, with loose stones; overgrowth; unstable ruins with unsecured openings.		
<i>Maintenance</i>	Not maintained		
<i>Condition of Monument</i>			
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>	<i>On-site Staff</i> <input type="checkbox"/>	<i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>			
<i>Notes</i>	Would require extensive modifications to make this site (incorporating LF016-018001, LF016-018002, LF016-018003) accessible.		

RMP Ref: LF-	016-018003	Monument	Castle - Ringwork possible
Location/ Townland	Coolamber	National Grid Ref:	234574 E 273433 N
		RPS Ref	
		National Monument Ref	
Description	Associated with castle - ringworks (LF016-018003) and Bawn (LF016-018002).		
Ownership	Private	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Accessed via small country laneway.
Parking	No designated parking
Public Transport	
Approach Topography	Fairly level, field.
Approach Surface	Pasture, grass
Approach Safety	Located at side of quiet lane
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate, but not in good condition - partly off its hinges and unopenable.

<i>Site Topography</i>	Very undulating with ditch/moat and steep rise on which house/castle is located.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Very uneven ground, with loose stones; overgrowth; unstable ruins with unsecured openings.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	017-003	Monument	Historic Town		
Location/ Townland	Aghamore (Ardagh By.), Commons North, Knock, Lanesborough		National Grid Ref:	200753 <i>E</i>	269209 <i>N</i>
			RPS Ref		
			National Monument Ref		
Description	Lanesborough town. Historically important bridging point on the River Shannon.				
Ownership	Public/Private	Date of Inspection	30/09/09	Inspected By	SMcG
				Accessibility Rating	A

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford", Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?county=LF&name=&town=lanesboro&townland=&type=quick&page=1 http://www.buildingsofireland.ie/niah/search.jsp?county=LF&name=&town=lanesboro&townland=&type=quick&page=2 http://www.buildingsofireland.ie/niah/search.jsp?county=LF&name=&town=lanesboro&townland=&type=quick&page=3
Internet Directions	

Field Survey:

Road Signs	Road signs to town
Site Signs	Tourist information board with historical information
Visibility	
Intervisibility	Intervisible with individual RMPs within town
Road Access	Main road through town, N63.
Parking	Street parking; carpark at site of castle
Public Transport	Public transport to town
Approach Topography	Level approach
Approach Surface	Concrete, tarmac

Approach Safety	
Approach Width	>1.8m
Gate type	
Approach Gate width	
Site Topography	Fairly level
Site Paths	Paved street throughout town, pedestrian crossing present.
Paths Surfacing	Concrete, paving.
Paths Width	>1.8m
Hazards	Open, unprotected edge at riverside walk, although footboard present in places.
Maintenance	Well maintained
Condition of Monument	Good
Child friendly <input type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>
	On-site Staff <input type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>
	On-site Toilets <input type="checkbox"/>
On-site facilities	Toilet facilities exist across the bridge, on the Roscommon side. Street lighting. Seating present along riverside.
Notes	

RMP Ref: LF-	017-003001	Monument	Bridge(s)
Location/ Townland	Aghamore (Rathcline By.), Commons North, Lanesborough, River Shannon		National Grid Ref: 200572 <i>E</i> 269355 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Major crossing point on the River Shannon. The original bridge is thought to have been constructed c.1000A.D., with a masonry bridge built in 1140. The bridge is known to have been rebuilt in 1760, while the present reconstruction dates to 1971.		
Ownership	Public	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford", Dollard Printinghouse, Dublin, 1891. Pg. 151: "No. 245: "Sir Robert Newcomen.Bart., and others, of the Counties of Roscommon and Longford, for heads of a bill for charging estates of Irish Papists for rebuilding the Bridge of Lanesborough over the River Shannon. — Presented, 1703, Oct. 30. — Leave granted."
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	<p>National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13310001 "Description Six-arch road bridge over River Shannon, built c. 1835 - 1843. Original metal swivel section to the northwest end replaced c. 1975 by fixed concrete span with concrete piers. Original parapets removed and road/footpaths widened with cantilevered reinforced concrete sections/decks to either side c. 1993. Original round-headed pedestrian arch and walkway built into squared limestone rubble abutment to the west end. Constructed of ashlar limestone with segmental arches having ashlar limestone voussoirs. Rusticated/rock-faced limestone piers with rounded/U-shaped cutwaters to upstream and downstream elevations. Located to the northwest end of Lanesborough, linking County Longford with County Roscommon. Spans border between Leinster and Connaught.</p> <p>Appraisal Despite recent alterations, this fine bridge represents a significant mid-nineteenth century engineering achievement and is an important element of the built heritage of Longford. It is well built using high quality ashlar limestone masonry, while the graceful profile of the arches identifies the civil engineering heritage significance of the site. The rounded/U-shaped cutwaters are typical of the many bridges built across the River Shannon by the Shannon Navigation Commissioners during the mid-nineteenth century. It was probably built to designs by Thomas Rhodes (1789 - 1868), the chief engineer with the Shannon Navigation Commissioners at the time of construction and the engineer responsible for a number of elegant bridges over the Shannon. This bridge formerly had a metal swivel section to the west end, which was built to allow for the passage of river traffic along the Shannon Navigation. It was later replaced by a fixed span, c. 1975. The present bridge replaced an earlier nine-arch stone bridge on this site, which was erected Sir George Lane in 1667. This bridge was described in 1682 as 'in length and breath the largest in the kingdom'."</p>
Internet Directions	

Field Survey:

Road Signs	Road signs to town only.
Site Signs	Tourist information board in town, with historical information about the bridge.
Visibility	
Intervisibility	Intervisible with historic town.
Road Access	Crossed by main road, N63. Also can be viewed from riverside walk.
Parking	Street parking; carpark at site of castle
Public Transport	Public transport to town
Approach Topography	Level approach. Riverside walk is wheelchair accessible.
Approach Surface	Concrete, tarmac.
Approach Safety	Open, unprotected edge at riverside walk, although footboard present in places.
Approach Width	>1.8m
Gate type	
Site Topography	Slight incline down to riverside walk, otherwise fairly level.
Site Paths	Viewing from riverside walk; footpath crossing bridge either side of road.
Paths Surfacing	Concrete, paving, tarmac
Paths Width	>1.8m
Hazards	Open, unprotected edge at riverside walk, although footboard present in places.
Maintenance	Well-maintained
Condition of Monument	Good, but largely reconstructed.
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/> On-site Staff <input type="checkbox"/> On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	Toilet facilities exist across the bridge, on the Roscommon side. Street lighting. Seating present along riverside.
Notes	

RMP Ref: LF-	017-003002	Monument	Castle - Unclassified
Location/ Townland	Lanesborough	National Grid Ref:	200581 E 269287 N
		RPS Ref	
		National Monument Ref	
Description	Site only. Now a public car-park, located to the southeast of the bridge.		
Ownership	Public	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Road signs to town only.
Site Signs	Tourist information board in town, with historical information about the castle.
Visibility	Non-extant
Intervisibility	
Road Access	
Parking	Site of former castle is now a public carpark, off N63 adjacent to the river.
Public Transport	Public transport to town
Approach Topography	Fairly level
Approach Surface	Tarmac, concrete
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width
Gate type	

<i>Site Topography</i>	Level carpark
<i>Site Paths</i>	
<i>Paths Surfacing</i>	Tarmac
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Non-extant.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Street lighting.
<i>Notes</i>	

RMP Ref: LF-	017-003004	Monument	Church
Location/ Townland	Lanesborough	National Grid Ref:	200866 E 269265 N
		RPS Ref	
		National Monument Ref	
Description	St. John's Church. Present day church is 19th century in date, built on the site of an earlier 17th century church. Original ecclesiastical foundation on the site is 5th century abbey. Stretch of foundation level masonry wall in graveyard, represents earlier church. 17th century masonry arch (LF017-003009) is also present at edge of graveyard, but is now blocked up. Not listed as an RMP on the www.archaeology.ie website.		
Ownership	Private	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford", Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign for St. John's Church at church entrance. Copy of 18th century print of earlier church can be seen in church porch.
Visibility	Visible from main road
Intervisibility	
Road Access	Access to church via laneway from main road
Parking	Parking available in front of school
Public Transport	Public transport available to Lanesborough town.
Approach Topography	Fairly level
Approach Surface	Concrete pavement
Approach Safety	No visible hazard.

Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	Double gates		
Site Topography	Fairly level grounds.		
Site Paths	Pathway extends around 2 sides of church; Centre aisle in interior of church. No pathway to older architectural features.		
Paths Surfacing	Gravel		
Paths Width	1.5 - 1.8m		
Hazards	No visible hazards		
Maintenance	Very well maintained.		
Condition of Monument	Little upstanding remains of earlier features.		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input checked="" type="checkbox"/>
On-site facilities	No outdoor lighting.		
Notes			

RMP Ref: LF-	017-003005	Monument	Architectural Fragment(s)
Location/ Townland	Lanesborough	National Grid Ref:	<input type="text"/> E <input type="text"/> N
		RPS Ref	<input type="text"/>
		National Monument Ref	<input type="text"/>
Description	Uncertain as to what feature this refers. There are possible masonry fragments which have been used as gravemarkers in the graveyard. Not listed as an RMP on the www.archaeology.ie website.		
Ownership	Private	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	<input type="text"/>

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford", Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	<input type="text"/>
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	<input type="text"/>
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	Sign for St. John's Church at church entrance.
Visibility	<input type="text"/>
Intervisibility	<input type="text"/>
Road Access	Access to church via laneway from main road
Parking	Parking available in front of school
Public Transport	Public transport available to Lanesborough town.
Approach Topography	Fairly level
Approach Surface	Concrete pavement, grass
Approach Safety	No visible hazard.
Approach Width	>1.8m
Approach Gate width	>800mm
Gate type	Double gates

<i>Site Topography</i>	Fairly level grounds.
<i>Site Paths</i>	Pathway extends around 2 sides of church; Centre aisle in interior of church. No pathway to older architectural features.
<i>Paths Surfacing</i>	Gravel
<i>Paths Width</i>	1.5 - 1.8m
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	
<i>Condition of Monument</i>	Not readily identifiable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	017-003006	Monument	Graveslab (17th century)
Location/ Townland	Lanesborough	National Grid Ref:	200860 <i>E</i> 269239 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Set beside other gravestones. Not original location. Located beside another 18th century graveslab and beside the remains of earlier church wall.		
Ownership	Private	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford", Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign for St. John's Church at church entrance.
Visibility	
Intervisibility	
Road Access	Access to church via laneway from main road
Parking	Parking available in front of school
Public Transport	Public transport available to Lanesborough town.
Approach Topography	Fairly level
Approach Surface	Concrete pavement, grass
Approach Safety	No visible hazard.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Double gates

<i>Site Topography</i>	Fairly level grounds.
<i>Site Paths</i>	Pathway extends around 2 sides of church; No pathway to older architectural features.
<i>Paths Surfacing</i>	Gravel
<i>Paths Width</i>	1.5 - 1.8m
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	017-003007	Monument	Cross (18th century)
Location/ Townland	Lanesborough	National Grid Ref:	200870 <i>E</i> 269243 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Upright rough cut cross in graveyard, with inscription.		
Ownership	Private	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford", Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign for St. John's Church at church entrance.
Visibility	
Intervisibility	
Road Access	Access to church via laneway from main road
Parking	Parking available in front of school
Public Transport	Public transport available to Lanesborough town.
Approach Topography	Fairly level
Approach Surface	Concrete pavement, grass
Approach Safety	No visible hazard.
Approach Width	>1.8m
Approach Gate width	>800mm
Gate type	Double gates

<i>Site Topography</i>	Fairly level grounds.
<i>Site Paths</i>	Pathway extends around 2 sides of church; No pathway to older architectural features.
<i>Paths Surfacing</i>	Gravel
<i>Paths Width</i>	1.5 - 1.8m
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	017-003008	Monument	Graveyard
Location/ Townland	Lanesborough	National Grid Ref:	200859 <i>E</i> 269250 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Enclosed graveyard, associated with St. John's Church. Most graveslabs date from 18th - 20th centuries.		
Ownership	Private	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford", Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	
Graveyard Survey	#89 Lanesboro, Rathcline. Wheelchair accessible to church. No designated parking spaces. Gravel and concrete paths. Private access (Church of Ireland) (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign for St. John's Church at church entrance.
Visibility	Visible from main road
Intervisibility	
Road Access	Access to church via laneway from main road
Parking	Parking available in front of school
Public Transport	Public transport available to Lanesborough town.
Approach Topography	Fairly level
Approach Surface	Concrete pavement, grass
Approach Safety	No visible hazard.

Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	Double gates		
Site Topography	Fairly level grounds.		
Site Paths	Pathway extends around 2 sides of church; No pathway to older architectural features.		
Paths Surfacing	Gravel		
Paths Width	1.5 - 1.8m		
Hazards	No visible hazards		
Maintenance	Well maintained		
Condition of Monument	Good		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/>
On-site facilities	No outdoor lighting.		
Notes			

RMP Ref: LF-	017-003009	Monument	Gateway (17th century)
Location/ Townland	Lanesborough	National Grid Ref:	200841 E 269266 N
		RPS Ref	
		National Monument Ref	
Description	Stone-built archway, dating to 17th century. Located at one edge of the graveyard, now blocked up, incorporating 19th century memorial/grave markers. Archway is included in the print of the 18th century church buildings which can be seen in the modern church porch.		
Ownership	Private	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford", Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign for St. John's Church at church entrance.
Visibility	Visible from main road
Intervisibility	
Road Access	Access to church via laneway from main road
Parking	Parking available in front of school
Public Transport	Public transport available to Lanesborough town.
Approach Topography	Fairly level
Approach Surface	Concrete pavement, grass
Approach Safety	No visible hazard.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Double gates

<i>Site Topography</i>	Fairly level grounds.
<i>Site Paths</i>	No path leading to archway - accessed across grassed area.
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No outdoor lighting.
<i>Notes</i>	

RMP Ref: LF-	017-009001	Monument	Bawn				
Location/ Townland	Rathcline		National Grid Ref:	200040	E	266857	N
			RPS Ref				
			National Monument Ref				
Description	Bawn associated with Tower House (LF017-009002), Fortified House (LF017-009003) and Deerpark (LF017-009004). Large rectangular walled enclosure, containing ruins of a large fortified house at one side. Two arched gateways lead to interior of enclosure.						
Ownership	Private	Date of Inspection	30/09/09	Inspected By	SMcG	Accessibility Rating	D

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford", Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	'Land Preserved' sign on gate - not accessible
Visibility	Visible along roadside
Intervisibility	Intervisible with Fortified House (LF017-009003) .
Road Access	Adjacent to minor road
Parking	
Public Transport	
Approach Topography	Fairly level
Approach Surface	Tarmac, grass
Approach Safety	
Approach Width	
	Approach Gate width >800mm
Gate type	Rusting double railing gate

<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	Not maintained.
<i>Condition of Monument</i>	Ruinous, foliage covered in parts.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None. Interior not accessible but wall and arched gateway can be viewed from roadside.
<i>Notes</i>	Monument itself is not accessible but can be viewed from roadside.

RMP Ref: LF-	017-009002	Monument	Castle - Tower House
Location/ Townland	Rathcline	National Grid Ref:	200063 E 266859 N
		RPS Ref	
		National Monument Ref	
Description	Not identifiable. Possibly incorporated into later Fortified House (LF017-009003). Associated with Bawn (LF017-009001).		
Ownership	Private	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford", Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	'Land Preserved' sign on gate - not accessible
Visibility	Not identifiable
Intervisibility	
Road Access	Adjacent to minor road
Parking	
Public Transport	
Approach Topography	Fairly level
Approach Surface	Tarmac, grass
Approach Safety	
Approach Width	
	Approach Gate width >800mm
Gate type	Rusting double railing gate

<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	Not maintained.
<i>Condition of Monument</i>	Not identifiable
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	017-009003	Monument	House - Fortified House
Location/ Townland	Rathcline	National Grid Ref:	200060 E 266870 N
		RPS Ref	54
		National Monument Ref	
Description	Large ruined fortified house, with two towers at its southern corners, set to one side of a large rectangular walled enclosure. Two arched gateways lead to interior of enclosure. A second ruined building is situated in the western part of the enclosure with foundations of further buildings also apparent, probably representing outbuildings.		
Ownership	Private	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford", Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	'Land Preserved' sign on gate - not accessible
Visibility	Visible along roadside
Intervisibility	Intervisible with Bawn (LF017-009001)
Road Access	Adjacent to minor road
Parking	
Public Transport	
Approach Topography	Fairly level
Approach Surface	Tarmac, grass
Approach Safety	
Approach Width	
	Approach Gate width >800mm
Gate type	Rusting double railing gate

<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Ruined building - appears unstable at collapsed rubble visible.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Ruinous, foliage covered in parts.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	Monument itself is not accessible but can be viewed from roadside.

RMP Ref: LF-	017-009004	Monument	Deerpark Boundary (17th century)
Location/ Townland	Rathcline	National Grid Ref:	<input type="text"/> E <input type="text"/> N
		RPS Ref	<input type="text"/>
		National Monument Ref	<input type="text"/>
Description	Not considered an RMP on www.archaeology.ie website. Not readily identifiable, but may relate to walls around wooded area to the south, and a high wall visible in fields to the east of the Fortified House (LF017-009003).		
Ownership	Private	Date of Inspection	30/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford", Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	<input type="text"/>
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	<input type="text"/>
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	<input type="text"/>
Visibility	Visible from roadside.
Intervisibility	<input type="text"/>
Road Access	<input type="text"/>
Parking	<input type="text"/>
Public Transport	<input type="text"/>
Approach Topography	<input type="text"/>
Approach Surface	<input type="text"/>
Approach Safety	<input type="text"/>
Approach Width	<input type="text"/>
	Approach Gate width <input type="text"/>
Gate type	<input type="text"/>

<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	Unknown
<i>Condition of Monument</i>	Not readily identifiable. Not accessible.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	017-009006	Monument	Inscribed Stone (original location)
Location/ Townland	Rathcline	National Grid Ref:	200063 E 266859 N
		RPS Ref	
		National Monument Ref	
Description	Present location of stone unknown.		
Ownership		Date of Inspection	
		Inspected By	
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford", Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

Site Topography

Site Paths

Paths Surfacing

Paths Width

Hazards

Maintenance

Condition of Monument

Child friendly *On-site Information* *On-site Staff* *On-site Seating* *On-site Toilets*

On-site facilities

Notes

RMP Ref: LF-	017-013001	Monument	Church
Location/ Townland	Glebe (Rathcline By.), Rathcline		National Grid Ref: 199793 <i>E</i> 266065 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Ruined rectangular church within graveyard (LF017-013004). A number of 18th century graves are present within the church, along with a 17th century gravemarker (LF017-013005). Masonry rubble is also strewn around inside of church.		
Ownership	Public	Date of Inspection	29/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13401705
Internet Directions	

Field Survey:

Road Signs	Signs for Rathcline cemetery
Site Signs	
Visibility	Clearly visible on approach
Intervisibility	Intervisible with associated RMPs (LF017-013002; LF017-013003; LF017-013004; LF017-013005)
Road Access	Access via laneway from road
Parking	Parking space outside graveyard for a number of cars. Not designated.
Public Transport	
Approach Topography	Fairly level
Approach Surface	Tarmac
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Modern double, wrought metal gate; easily opened. Adjacent stone stepped stile also present.

<i>Site Topography</i>	Fairly level, with most of area around church covered with graves
<i>Site Paths</i>	Wide area immediately inside gate with 2 pathways leading through graveyard. No paths access the church due to concentration of graves in this area.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	1.3 - 1.8m
<i>Hazards</i>	No visible hazards in graveyard. Loose rubble in interior of church.
<i>Maintenance</i>	Well maintained. Ivy may need cutting back on parts of walls of church.
<i>Condition of Monument</i>	Ruined. Possibly unstable in places.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No lighting.
<i>Notes</i>	

RMP Ref: LF-	017-013002	Monument	Sheela-Na-Gig		
Location/ Townland	Glebe (Rathcline By.)		National Grid Ref:	199796	E
				266064	N
			RPS Ref		
			National Monument Ref		
Description	Carved figure on internal surround of narrow window in western wall of church. Medieval in appearance, with features somewhat worn away.				
Ownership	Public	Date of Inspection	29/09/09	Inspected By	SMcG
				Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13401705
Internet Directions	

Field Survey:

Road Signs	Signs for Rathcline cemetery
Site Signs	
Visibility	Not obvious. Visible from interior of church, but at a height and probably not readily identifiable without
Intervisibility	Intervisible with church (LF017-013001)
Road Access	Access via laneway from road
Parking	Parking space outside graveyard for a number of cars
Public Transport	
Approach Topography	Fairly level
Approach Surface	Tarmac, concrete and grass
Approach Safety	Rubble strewn around interior of church. Church not wheelchair accessible.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Modern double, wrought metal gate; easily opened. Adjacent stone stepped stile also present.

<i>Site Topography</i>	Fairly level, with most of area around church covered with graves
<i>Site Paths</i>	Wide area immediately inside gate with 2 pathways leading through graveyard. No paths access the church due to concentration of graves in this area.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	1.3 - 1.8m
<i>Hazards</i>	No visible hazards in graveyard. Loose rubble in interior of church.
<i>Maintenance</i>	Generally well-maintained. Ivy starting to encroach on carving and should be cut back before it gets established and caused damage.
<i>Condition of Monument</i>	Weathered.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No lighting.
<i>Notes</i>	

RMP Ref: LF-	017-013003	Monument	Ecclesiastical Enclosure
Location/ Townland	Glebe (Rathcline By.)	National Grid Ref:	199787 E 266066 N
		RPS Ref	
		National Monument Ref	
Description	Large enclosure, barely discernible as a low bank and only apparent in places, surrounding graveyard (LF017-013004).		
Ownership	Private	Date of Inspection	29/09/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Signs for Rathcline cemetery
Site Signs	
Visibility	Not obvious.
Intervisibility	Intervisible with Church (LF017-013001), and graveyard (LF017-013004).
Road Access	Access lane leading to graveyard
Parking	Some parking space (not designated) outside graveyard.
Public Transport	
Approach Topography	Fairly level
Approach Surface	Tarmac, concrete and grass
Approach Safety	Visible within field with grazing cattle.
Approach Width	>1.8m
	Approach Gate width
Gate type	

<i>Site Topography</i>	Gently undulating, uneven ground due to presence of cattle
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Grazing cattle in present
<i>Maintenance</i>	None
<i>Condition of Monument</i>	Little or no upstanding features
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	017-013004	Monument	Graveyard
Location/ Townland	Glebe (Rathcline By., Rathcline ED)		National Grid Ref: 199798 <i>E</i> 266071 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Graveyard associated with Church (LF017-013001). Neatly laid out, with visible graves surrounding church and extending into interior of church ruins. Older entrance in surrounding wall is now blocked.		
Ownership	Public	Date of Inspection	29/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	#88 Rathcline Graveyard, Rathcline. Wheelchair access to entrance only. Limited parking space only. Public access (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13401705
Internet Directions	

Field Survey:

Road Signs	Signs for Rathcline cemetery
Site Signs	
Visibility	Clearly visible on approach
Intervisibility	Intervisible with associated RMPs (LF017-013001; LF017-013002; LF017-013003; LF017-013005)
Road Access	Access via laneway from road
Parking	Some parking space (not designated) outside graveyard.
Public Transport	
Approach Topography	Fairly level
Approach Surface	Tarmac
Approach Safety	No visible hazards
Approach Width	>1.8m
Approach Gate width	>800mm

<i>Gate type</i>	Modern double, wrought metal gate; easily opened. Adjacent stone stepped stile also present.
<i>Site Topography</i>	Fairly level, with most of area around church covered with graves
<i>Site Paths</i>	Wide area immediately inside gate with 2 pathways leading through graveyard. No paths access the church due to concentration of graves in this area.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	1.3 - 1.8m
<i>Hazards</i>	No visible hazards in graveyard. Loose rubble in interior of church.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No lighting.
<i>Notes</i>	

RMP Ref: LF-	017-013005	Monument	Graveslab
Location/ Townland	Glebe (Rathcline By., Rathcline ED)		National Grid Ref: 199800 <i>E</i> 266064 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	17th century graveslab in interior of church ruins (LF017-013001). Also early 18th century graveslabs present, including one with skull and crossbones motif.		
Ownership	Public	Date of Inspection	29/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Signs for Rathcline cemetery	
Site Signs		
Visibility	Visible within church only.	
Intervisibility	Intervisible with church (LF017-013001)	
Road Access	Access via laneway from road	
Parking	Some parking space (not designated) outside graveyard.	
Public Transport		
Approach Topography	Fairly level	
Approach Surface	Tarmac, concrete and grass	
Approach Safety	Rubble strewn around interior of church. Church not wheelchair accessible.	
Approach Width	>1.8m	Approach Gate width >800mm
Gate type	Modern double, wrought metal gate; easily opened. Adjacent stone stepped stile also present.	

<i>Site Topography</i>	Fairly level, with most of area around church covered with graves
<i>Site Paths</i>	Wide area immediately inside gate with 2 pathways leading through graveyard. No paths access the church due to concentration of graves in this area.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	1.3 - 1.8m
<i>Hazards</i>	No visible hazards in graveyard. Loose rubble in interior of church.
<i>Maintenance</i>	Generally well-maintained.
<i>Condition of Monument</i>	Weathered.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None. No lighting.
<i>Notes</i>	

RMP Ref: LF-	018-005	Monument	Castle - Tower House
Location/ Townland	Ballyclare (Moydow By., Moydow ED)		National Grid Ref: 209317 <i>E</i> 270614 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Partial ruins of Tower House, adjacent to abandoned house. Heavily covered in ivy. Ruins do not appear stable.		
Ownership	Private	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Although castle is noted on the information board in Killashee town.	
Site Signs		
Visibility	Visible from road, but ivy cover makes it less identifiable	
Intervisibility		
Road Access	Close to main road	
Parking	Parking may be possible on roadside.	
Public Transport		
Approach Topography	Access through farmyard.	
Approach Surface	Grass, soft ground.	
Approach Safety	Farm machinery lying around. No footpath on road.	
Approach Width	>1.8m	Approach Gate width >800mm
Gate type	Field gate.	

<i>Site Topography</i>	Fairly level ground but uneven footing.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Unstable ruins. High level of overgrowth.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Ruinous, heavily overgrown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None. No lighting.
<i>Notes</i>	

RMP Ref: LF-	018-006	Monument	Church
Location/ Townland	Templeton Glebe	National Grid Ref:	207765 E 270059 N
		RPS Ref	
		National Monument Ref	
Description	Modern church in rectangular graveyard, with a second adjoining graveyard to the west. This last is sub-circular with a small addition towards roadside. No evidence of an earlier church.		
Ownership	Public/Private	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	B/C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	Limited wheelchair access. No designated parking. Part public and part private (Church of Ireland) access (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13311001
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Only site referring to current services at church
Visibility	No visible remains
Intervisibility	
Road Access	Located beside main road, N63.
Parking	No designated parking. Parking possible at roadside.
Public Transport	
Approach Topography	Level
Approach Surface	Tarmac; gravel from gate to church; concrete path through second graveyard.
Approach Safety	No footpath on road. No pedestrian crossing.
Approach Width	Gravel path >2m ; Concrete path, c.1.2m
	Approach Gate width >800mm

	wide.
Gate type	Double wrought iron gates at entrance to church; pedestrian gates to second graveyard and annexe (3 in total).
Site Topography	Fairly level but uneven footing
Site Paths	No paths, grass covered.
Paths Surfacing	
Paths Width	
Hazards	No visible hazards
Maintenance	Well maintained
Condition of Monument	No upstanding remains identifiable.
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>
	On-site Staff <input type="checkbox"/>
	On-site Seating <input type="checkbox"/>
	On-site Toilets <input type="checkbox"/>
On-site facilities	No lighting.
Notes	

RMP Ref: LF-	018-009	Monument	Church
Location/ Townland	Curry (Moydow By.)	National Grid Ref:	211730 <i>E</i> 271010 <i>N</i>
		RPS Ref	107
		National Monument Ref	
Description	St. Catherine's Church, Ballymacormick. Centrally located within rectangular graveyard. Present church appears to be 18th or 19th century in construction.		
Ownership	Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13401802
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Only sign at church entrance, with information about church services.
Visibility	Visible from main road, R397.
Intervisibility	
Road Access	Adjacent to main road, R397.
Parking	No designated parking but layby in front of church allows for parking.
Public Transport	
Approach Topography	Fairly level
Approach Surface	Gravel drive leading from gate to church.
Approach Safety	No visible hazards
Approach Width	>2m wide
	Approach Gate width >800mm
Gate type	Double wrought iron gates

<i>Site Topography</i>	Slight slope downwards from rear of church, otherwise generally level
<i>Site Paths</i>	Gravel path to church.
<i>Paths Surfacing</i>	Gravel.
<i>Paths Width</i>	>2m
<i>Hazards</i>	Step up to main door of church.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Unknown. No visible older church remains.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Church was not open at time of survey. No outside lighting.
<i>Notes</i>	

RMP Ref: LF-	018-009001	Monument	Graveyard
Location/ Townland	Curry (Moydow By)	National Grid Ref:	211730 <i>E</i> 271010 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Not considered an RMP on www.archaeology.ie website. Graveyard associated with St. Catherine's Church (see LF018-009).		
Ownership	Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Known as Ballymacormick Church (St. Catherine's Church of Ireland).
Local Sources Directions	
Graveyard Survey	#15 Ballymacormack (Curry) Graveyard, Ballymacormack & Templemichael. Wheelchair accessible to church. Limited parking space. Gravel pathway from entrance to church. Private access (Church of Ireland) (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Only sign at church entrance, with information about church services.
Visibility	Visible from main road, R397.
Intervisibility	
Road Access	Adjacent to main road, R397.
Parking	No designated parking but layby in front of church allows for parking.
Public Transport	
Approach Topography	Fairly level
Approach Surface	Gravel drive leading from gate to church.
Approach Safety	No visible hazards

Approach Width	>2m wide	Approach Gate width	>800mm
Gate type	Double wrought iron gates		
Site Topography	Slight slope downwards from rear of church, otherwise generally level		
Site Paths	Gravel path to church, no other paths in graveyard.		
Paths Surfacing	Gravel		
Paths Width	>2m		
Hazards	No visible hazards.		
Maintenance	Well maintained.		
Condition of Monument			
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	No outdoor lighting.		
Notes			

RMP Ref: LF-	018-022001	Monument	Enclosure
Location/ Townland	Caldraghmore	National Grid Ref:	211470 <i>E</i> 269530 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Large oval enclosure, with identifiable bank and outer ditch. The bank is encircled with trees and bushes and encloses a relatively flat area, which has been used as a Children's Burial Ground (LF018-022002). Located within a field grazed by cattle.		
Ownership	Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Only visible on approach through field.
Intervisibility	
Road Access	Must be accessed via farmyard and field.
Parking	Roadside parking may be possible
Public Transport	
Approach Topography	Ground slopes upwards from farmyard
Approach Surface	Pasture, soft ground churned up by cattle
Approach Safety	
Approach Width	
	Approach Gate width >800mm
Gate type	

<i>Site Topography</i>	By nature undulating with steeply sloping ditch and bank. Interior is fairly level
<i>Site Paths</i>	None. Cattle have created breaks in encircling bushes in places.
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Uneven ground to reach interior. Cattle present in field. Electric fences around field and along trackway over bank leading to the interior of the enclosure.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Perimeter is overgrown. No internal features
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	018-022002	Monument	Children's Burial Ground
Location/ Townland	Caldraghmore	National Grid Ref:	211470 E 269530 N
		RPS Ref	
		National Monument Ref	
Description	Located within large oval enclosure (LLF018-022001). No visible sign of burial ground.		
Ownership	Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Only visible on approach through field.
Intervisibility	
Road Access	Must be accessed via farmyard and field.
Parking	Roadside parking may be possible
Public Transport	
Approach Topography	Ground slopes upwards from farmyard
Approach Surface	Pasture, soft ground churned up by cattle
Approach Safety	
Approach Width	
	Approach Gate width >800mm
Gate type	

<i>Site Topography</i>	Entranceway is undulating with steeply sloping ditch and bank of enclosure. Interior is fairly level
<i>Site Paths</i>	None. Cattle have created breaks in encircling bushes in places.
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Uneven ground to reach interior. Cattle present in field. Electric fences around field and along trackway over bank leading to the interior of the enclosure.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Not identifiable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	018-039	Monument	Church
Location/ Townland	Ballinamore	National Grid Ref:	210724 E 267661 N
		RPS Ref	
		National Monument Ref	
Description	Ruins of rectangular, dry-stone wall built church, located centrally within circular enclosure/graveyard (LF018-039001). Partial opening of large window present in gable wall, which is also the most complete wall of the building. Partially overgrown with ivy and brambles.		
Ownership	Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from road, R398.
Intervisibility	Intervisible with castle ruins (LF018-038).
Road Access	In field adjacent to main road, R398, but must cross field to monument.
Parking	No designated parking. Parking may be possible at roadside.
Public Transport	
Approach Topography	Slight slope upwards through field to graveyard
Approach Surface	Uneven grass covered ground
Approach Safety	No footpath at roadside. Cattle may be present in field.
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Undulating ground to access monument, due to encircling ditch and bank. Collapsed walls also make footing difficult.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Unstable ruins. Collapsed rubble present, partially hidden in overgrowth.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Ruinous, unstable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	018-039001	Monument	Graveyard
Location/ Townland	Ballinamore	National Grid Ref:	210727 E 267662 N
		RPS Ref	
		National Monument Ref	
Description	Circular enclosure with low bank and external ditch. Remains of church (LF018-039) are located in the centre of the enclosure. Only one gravestone is apparent and morphology of enclosure suggests an early medieval date. There is a small metal gateway at one side but this is not associated with a fence.		
Ownership	Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#14 Ballinamore, Ballymacormack & Templemichael. Not wheelchair accessible. No pathways present. Access through private land (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from road, R398.
Intervisibility	Intervisible with castle ruins (LF018-038).
Road Access	In field adjacent to main road, R398, but must cross field to monument.
Parking	No designated parking. Parking may be possible at roadside.
Public Transport	
Approach Topography	Slight slope upwards through field to graveyard
Approach Surface	Uneven grass covered ground
Approach Safety	No footpath at roadside. Cattle may be present in field.
Approach Width	
	Approach Gate width >800mm

<i>Gate type</i>	Field gate
<i>Site Topography</i>	Undulating ground to access monument, due to encircling ditch and bank. Collapsed walls also make footing difficult.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Unstable ruins in graveyard. Collapsed rubble present, partially hidden in overgrowth.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	overgrown.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	018-039002	Monument	Children's Burial Ground
Location/ Townland	Ballinamore	National Grid Ref:	210723 E 267657 N
		RPS Ref	
		National Monument Ref	
Description	Not apparent on site. Probably within overall graveyard.		
Ownership	Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	In field adjacent to main road, R398, but must cross field to monument.
Parking	No designated parking. Parking may be possible at roadside.
Public Transport	
Approach Topography	Slight slope upwards through field to graveyard
Approach Surface	Uneven grass covered ground
Approach Safety	No footpath at roadside. Cattle may be present in field.
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Undulating ground to access monument, due to encircling ditch and bank. Collapsed walls also make footing difficult.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Unstable ruins in graveyard. Collapsed rubble present, partially hidden in overgrowth.
<i>Maintenance</i>	
<i>Condition of Monument</i>	Not identifiable
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	018-039003	Monument	Memorial Stone
Location/ Townland	Ballinamore	National Grid Ref:	210724 E 267661 N
		RPS Ref	
		National Monument Ref	
Description	Memorial stone erected in the side wall of the church, which reads 'Here liet the corps of Sir Rich Brown Baronet and his La. Mary Plunket'. Of 17th century date.		
Ownership	Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	In field adjacent to main road, R398, but must cross field to monument.
Parking	No designated parking. Parking may be possible at roadside.
Public Transport	
Approach Topography	Slight slope upwards through field to graveyard
Approach Surface	Uneven grass covered ground
Approach Safety	No footpath at roadside. Cattle may be present in field.
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Undulating ground to access monument, due to encircling ditch and bank. Collapsed walls also make footing difficult.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Unstable ruins in graveyard. Collapsed rubble present, partially hidden in overgrowth.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Weathered and being encroached upon by ivy
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	018-058001	Monument	Enclosure possible
Location/ Townland	Aghnashingan	National Grid Ref:	211969 E 265755 N
		RPS Ref	
		National Monument Ref	
Description	Circular area enclosed by a very low bank and ditch, which may not be readily identifiable to the general public. Associated with Children's Burial Ground (LF018-058002). Interior of enclosure is featureless, with just two large stone visible.		
Ownership	Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Only visible on approach from farmyard
Intervisibility	
Road Access	Need to cross farmyard and garden.
Parking	No designated parking; roadside parking may be possible. Off R397.
Public Transport	
Approach Topography	Slight slope in garden.
Approach Surface	Grass, soft ground
Approach Safety	Animals (donkeys) grazing in field
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Undulating over bank and ditch of monument. General uneven ground.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Animals present
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Not obviously identifiable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	018-058002	Monument	Children's Burial Ground
Location/ Townland	Aghnashingan	National Grid Ref:	211969 <i>E</i> 265755 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Not apparent. Situated within enclosure (LF018-058001) but no markers present. Two large stones in interior of enclosure may be associated with the burial ground.		
Ownership	Private	Date of Inspection	19/10/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Only visible on approach from farmyard
Intervisibility	
Road Access	Need to cross farmyard and garden.
Parking	No designated parking; roadside parking may be possible (R397).
Public Transport	
Approach Topography	Slight slope in garden.
Approach Surface	Grass, soft ground
Approach Safety	Animals (donkeys) grazing in field
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Undulating over bank and ditch of enclosure. General uneven ground.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Animals present
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Not identifiable within enclosure.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	018-059	Monument	Church
Location/ Townland	Kilmakinlan		National Grid Ref: 210621 <i>E</i> 265333 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Site only. No upstanding remains and exact location of church site is uncertain. Located along the side of the Royal Canal.		
Ownership	Private	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	No remains present. Private ownership (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	No visible signs
Intervisibility	
Road Access	Access across field from the Royal Canal tow-path.
Parking	Possibility of roadside parking near Coolnahinch Bridge, but no designated parking
Public Transport	
Approach Topography	A large, wide ditch at the nearest point to the road blocks access from this direction. Access only through other fields
Approach Surface	Grass (pastureland)
Approach Safety	
Approach Width	Approach Gate width >800mm

<i>Gate type</i>	Field gates
<i>Site Topography</i>	Exact location of RMP unknown
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	No upstanding remains
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	018-064	Monument	Ritual Site - Holy Well
Location/ Townland	Abbeyderg	National Grid Ref:	213325 E 264855 N
		RPS Ref	
		National Monument Ref	
Description	Well encircled by low stone and mortar wall, with some overgrowth of ivy and fern. Area around well is fenced-off from rest of field and accessed via a gate. Locally was associated with curative powers and is still occasionally visited (local source). The well was also used for domestic purposes in the past.		
Ownership	Private	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Access via 2 fields (former laneway, now quite muddy in second field) from end of farm access-lane.
Parking	Parking may be possible in front of farm
Public Transport	
Approach Topography	Uphill slope from farmyard to well
Approach Surface	Grass, soft ground
Approach Safety	A bull grazing on the land presents a serious hazard. Permission is required to access land.
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Fairly level ground in immediate area of well.
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Uneven ground and overgrowth around access point.
<i>Maintenance</i>	Kept clean and mostly free of overgrowth.
<i>Condition of Monument</i>	Good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	018-066001	Monument	Religious House - Augustinian Canons
Location/ Townland	Abbeyderg	National Grid Ref:	214112 <i>E</i> 265378 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Well preserved ruins of church, with one gable fully intact. Remains of other structures, in the form of low sections of wall now overgrown with ivy, exist in the vicinity of the church.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	
Graveyard Survey	Wheelchair accessible. No designated parking spaces. Mass is celebrated annually in July at the stone altar. References to the site can be found in Journals and books held in the Local Studies Section in Longford County Library HQ (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Sign on main road indicating laneway to site.
Site Signs	
Visibility	Visible from main road (Moydow to Kenagh road)
Intervisibility	
Road Access	Accessed via laneway from main road (Moydow to Kenagh road)
Parking	Parking space for 1 or 2 cars only
Public Transport	
Approach Topography	Level gated laneway leads from main road.
Approach Surface	Tarmac
Approach Safety	No visible hazards

Approach Width	c.2m	Approach Gate width	c.2m
Gate type	Double gate, permits access of one car at a time		
Site Topography	Level in area of pathway. Elsewhere uneven.		
Site Paths	Pathway encircles graveyard. No path to church ruins.		
Paths Surfacing	Tarmac		
Paths Width	c.2m		
Hazards	Some overgrowth may hide low walls, gravemarkers or loose stones, presenting trip hazards.		
Maintenance	Well maintained		
Condition of Monument	Ruined but church remains appear stable.		
Child friendly <input checked="" type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	Stepped pedestal of memorial cross does provide some low-level seating. No outdoor lighting.		
Notes			

RMP Ref: LF-	018-066002	Monument	Graveyard		
Location/ Townland	Abbeyderg		National Grid Ref:	214080 <i>E</i>	265370 <i>N</i>
			RPS Ref		
			National Monument Ref		
Description	Graveyard associated with Abbey (LF018-066001). Well maintained sub-circular graveyard. Graves extend to interior of church.				
Ownership	Public	Date of Inspection	21/09/09	Inspected By	SMcG
				Accessibility Rating	B

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891.
Local Sources Directions	
Graveyard Survey	#23 Abbeyderg Graveyard, Carrickedmond & Abbeyshrule. Wheelchair accessible; No designated parking spaces; Mass is celebrated annually in July at the stone altar; References to the site can be found in Journals and books held in the Local Studies Section in Longford County Library HQ (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Sign on main road for Abbey indicating laneway to site.
Site Signs	
Visibility	Visible from main road
Intervisibility	
Road Access	Accessed via laneway from main road
Parking	Parking space for 1 or 2 cars only
Public Transport	
Approach Topography	Level gated laneway leads from main road.
Approach Surface	Tarmac

Approach Safety	No visible hazards	
Approach Width	c.2m	Approach Gate width c.2m
Gate type	Double gate, permits access of one car at a time	
Site Topography	Level in area of pathway. Elsewhere uneven.	
Site Paths	Pathway encircles graveyard. No path to church ruins or central area of graveyard.	
Paths Surfacing	Tarmac	
Paths Width	c.2m	
Hazards	Some overgrowth close to church ruins may hide low walls, gravemarkers or loose stones, presenting trip hazards.	
Maintenance	Well maintained	
Condition of Monument	Good	
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>
	On-site Seating <input type="checkbox"/>	On-site Toilets <input type="checkbox"/>
On-site facilities	Stepped pedestal of memorial cross does provide some low-level seating. No outdoor lighting.	
Notes		

RMP Ref: LF-	018-102	Monument	Water Mill - Unclassified
Location/ Townland	Ballyclare (Moydow By., Moydow ED)		National Grid Ref: <input type="text"/> E <input type="text"/> N
		RPS Ref	<input type="text"/>
		National Monument Ref	<input type="text"/>
Description	Not identifiable - non extant. Not considered an RMP on the www.archaeology.ie website. A substantial ditch to the south of the castle (LF018-005) may have functioned as a millrace. However, this may equally represent the original course of the Fallen River.		
Ownership	Private	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	<input type="text"/>
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	<input type="text"/>
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	<input type="text"/>
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	<input type="text"/>
Visibility	<input type="text"/>
Intervisibility	<input type="text"/>
Road Access	<input type="text"/>
Parking	<input type="text"/>
Public Transport	<input type="text"/>
Approach Topography	<input type="text"/>
Approach Surface	<input type="text"/>
Approach Safety	<input type="text"/>
Approach Width	<input type="text"/>
	Approach Gate width <input type="text"/>
Gate type	<input type="text"/>

Site Topography

Site Paths

Paths Surfacing

Paths Width

Hazards

Maintenance

Condition of Monument

Child friendly *On-site Information* *On-site Staff* *On-site Seating* *On-site Toilets*

On-site facilities

Notes

RMP Ref: LF-	019-005001	Monument	Bawn		
Location/ Townland	Bawn (Moydow By.)		National Grid Ref:	215358	E
				269723	N
			RPS Ref		
			National Monument Ref		
Description	Long stretch of wall with adjoining tower within large moated enclosure (LF019-005003). No return is evident on wall.				
Ownership	Private	Date of Inspection	18/09/09	Inspected By	SMcG
				Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	Intervisible with other associated monuments (LF019-005002, LF019-005003, and LF019-005004)
Road Access	Accessed via private driveway to Bawn House and then through field.
Parking	No public parking.
Public Transport	
Approach Topography	Level driveway
Approach Surface	Gravel
Approach Safety	No visible hazards
Approach Width	>1.8m / single-lane
	Approach Gate width >800mm
Gate type	

<i>Site Topography</i>	Very undulating due to presence of moat and ditch enclosing the site.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Heavily overgrown in parts making footing uncertain. Upstanding remains may not be stable
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Ruined
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None. No lighting.
<i>Notes</i>	

RMP Ref: LF-	019-005002	Monument	Castle - Unclassified
Location/ Townland	Bawn (Moydow By.)	National Grid Ref:	215348 E 269685 N
		RPS Ref	
		National Monument Ref	
Description	May refer to ruins of circular tower adjoining the bawn wall (LF019-005001). Situated within moated enclosure (LF019-005003).		
Ownership	Private	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	Intervisible with other associated monuments (LF019-005001, LF019-005003, and LF019-005004)
Road Access	Accessed via private driveway to Bawn House and then through field.
Parking	No public parking.
Public Transport	
Approach Topography	Level driveway
Approach Surface	Gravel
Approach Safety	No visible hazards
Approach Width	>1.8m / single-lane
Approach Gate width	>800mm
Gate type	

<i>Site Topography</i>	Very undulating due to presence of moat and ditch enclosing the site.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Heavily overgrown in parts making footing uncertain. Upstanding remains may not be stable
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Ruined
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None. No lighting.
<i>Notes</i>	

RMP Ref: LF-	019-005003	Monument	Moated Site possible		
Location/ Townland	Bawn (Moydow By.)		National Grid Ref:	215358 E	269723 N
			RPS Ref		
			National Monument Ref		
Description	Large moated enclosure, very evident on two sides but more ephemeral on the eastern side. The moat is rock-cut in places, is generally wide and deep. Within the enclosure are the remains of a circular tower (LF019-005002) and bawn wall (LF019-005001) as well as 'Bawn House' and a number of surviving outbuildings, including stables. The moat may have been crossed by bridge (LF019-005004), which is now collapsed.				
Ownership	Private	Date of Inspection	18/09/09	Inspected By	SMcG
				Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	Intervisible with other associated monuments (LF019-005001, LF019-005002, and LF019-005004)
Road Access	Accessed via private driveway to Bawn House and then through field.
Parking	No public parking.
Public Transport	
Approach Topography	Level driveway
Approach Surface	Gravel
Approach Safety	No visible hazards
Approach Width	>1.8m / single-lane
Approach Gate width	>800mm

<i>Gate type</i>	
<i>Site Topography</i>	Very undulating due to presence of moat and ditch enclosing the site.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Heavily overgrown in parts making footing uncertain. Upstanding remains may not be stable
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None. No lighting.
<i>Notes</i>	

RMP Ref: LF-	019-005004	Monument	Bridge
Location/ Townland	Bawn (Moydow By.)	National Grid Ref:	215386 E 269706 N
		RPS Ref	
		National Monument Ref	
Description	Located at the west of the moated enclosure (LF019-005003), now collapsed and not readily identifiable as a bridge.		
Ownership	Private	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	Intervisible with other associated monuments (LF019-005001, LF019-005002, and LF019-005003)
Road Access	Accessed via private driveway to Bawn House and then through field.
Parking	No public parking.
Public Transport	
Approach Topography	Level driveway
Approach Surface	Gravel
Approach Safety	No visible hazards
Approach Width	>1.8m / single-lane
Approach Gate width	>800mm
Gate type	

<i>Site Topography</i>	Very undulating due to presence of moat and ditch enclosing the site.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Heavily overgrown in parts making footing uncertain. Upstanding remains may not be stable
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Collapsed.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None. No lighting.
<i>Notes</i>	

RMP Ref: LF-	019-030	Monument	Church possible
Location/ Townland	Moydow Glebe	National Grid Ref:	214792 E 268736 N
		RPS Ref	103
		National Monument Ref	
Description	Present church remains were built in 1765 - noted on plaque at entrance. There may have been an earlier church on the site as the earliest gravemarkers in the graveyard (LF019-030001) date to the 17th century. The church is now disused and boarded up.		
Ownership	Public	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891. P 213.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13401902
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Small plaque on wall at entrance gates, with some basic historical detail.
Visibility	Clearly visible at side of main road.
Intervisibility	Intervisible with associated sites (LF019-030001, LF019-030002, LF019-030003). An enclosure (LF01
Road Access	Located at side of road. (Longford to Moydow & Kenagh road)
Parking	Parking available at entrance for a number of cars.
Public Transport	
Approach Topography	Small gravel/hardcore parking area in front of entrance. However, starting to become overgrown with vegetation due to disuse.
Approach Surface	Level
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width c.1.8m
Gate type	Single wrought iron gate, difficult to open

<i>Site Topography</i>	Uneven ground, with ground level largely hidden by overgrowth
<i>Site Paths</i>	Gravel path leads from gate to church, and around part of church, but does not extend to graveyard.
<i>Paths Surfacing</i>	Gravel
<i>Paths Width</i>	c.1.5m
<i>Hazards</i>	Uneven ground in area of church. General appearance of church suggests it is unstable.
<i>Maintenance</i>	Not currently maintained
<i>Condition of Monument</i>	Abandoned, falling into disrepair.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	019-030001	Monument	Graveyard
Location/ Townland	Moydow Glebe	National Grid Ref:	214790 <i>E</i> 268725 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Graveyard associated with Church (LF019-030). Earliest gravemarkers date to 1640. Although restored in 1996, it has since become overgrown again with weeds, although otherwise the ground is quite bare.		
Ownership	Public	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891. P 213.
Local Sources Directions	
Graveyard Survey	#13 Moydow (Moydow Glebe) Graveyard, Ardagh. Limited wheelchair access, to church entrance. No designated parking spaces. Private access (Church of Ireland) (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Small plaque on wall at entrance gates, with some basic historical detail.
Visibility	Clearly visible at side of main road.
Intervisibility	Intervisible with associated sites (LF019-030, LF019-030002, LF019-030003). An enclosure (LF019-0
Road Access	Located at side of road.
Parking	Parking available at entrance for a number of cars.
Public Transport	
Approach Topography	Small gravel/hardcore parking area in front of entrance. However, starting to become overgrown with vegetation due to disuse.
Approach Surface	Level
Approach Safety	No visible hazards

Approach Width	>1.8m	Approach Gate width	c.1.8m
Gate type	Single wrought iron gate, difficult to open		
Site Topography	Uneven ground, with ground level partly hidden by overgrowth		
Site Paths	Gravel path leads from gate to church, and around part of church, but does not extend to graveyard.		
Paths Surfacing	Gravel		
Paths Width	c.1.5m		
Hazards	Uneven ground in area of church. General appearance of church suggests it is unstable.		
Maintenance	Not currently maintained		
Condition of Monument	Overgrown by weeds		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	None.		
Notes			

RMP Ref: LF-	019-030002	Monument	Cross (17th century)
Location/ Townland	Moydow Glebe	National Grid Ref:	214786 <i>E</i> 268716 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	The cross was not identifiable at time of survey.		
Ownership	Public	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891. P 213.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Small plaque on wall at entrance gates, with some basic historical detail.
Visibility	Graveyard is clearly visible at side of road.
Intervisibility	
Road Access	Located in graveyard at side of road.
Parking	Parking available at entrance for a number of cars.
Public Transport	
Approach Topography	Small gravel/hardcore parking area in front of entrance. However, starting to become overgrown with vegetation due to disuse.
Approach Surface	Level
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width c.1.8m
Gate type	Single wrought iron gate, difficult to open

<i>Site Topography</i>	Uneven ground, with ground level partly hidden by overgrowth
<i>Site Paths</i>	Gravel path leads from gate to church, and around part of church, but does not extend to graveyard.
<i>Paths Surfacing</i>	Gravel
<i>Paths Width</i>	c.1.5m
<i>Hazards</i>	Uneven ground in area of church. General appearance of church suggests it is unstable.
<i>Maintenance</i>	Not currently maintained
<i>Condition of Monument</i>	Not readily identifiable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	019-030003	Monument	Graveslab (17th century)
Location/ Townland	Moydow Glebe	National Grid Ref:	214776 <i>E</i> 268715 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	The graveslab was not identifiable at time of survey.		
Ownership	Public	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891. P 213.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Small plaque on wall at entrance gates, with some basic historical detail.
Visibility	Graveyard is clearly visible at side of road.
Intervisibility	
Road Access	Located in graveyard at side of road.
Parking	Parking available at entrance for a number of cars.
Public Transport	
Approach Topography	Small gravel/hardcore parking area in front of entrance. However, starting to become overgrown with vegetation due to disuse.
Approach Surface	Level
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width c.1.8m
Gate type	Single wrought iron gate, difficult to open

<i>Site Topography</i>	Uneven ground, with ground level partly hidden by overgrowth
<i>Site Paths</i>	Gravel path leads from gate to church, and around part of church, but does not extend to graveyard.
<i>Paths Surfacing</i>	Gravel
<i>Paths Width</i>	c.1.5m
<i>Hazards</i>	Uneven ground in area of church. General appearance of church suggests it is unstable.
<i>Maintenance</i>	Not currently maintained
<i>Condition of Monument</i>	Not readily identifiable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	019-050001	Monument	Church
Location/ Townland	Ardagh Demesne	National Grid Ref:	220229 E 268746 N
		RPS Ref	
		National Monument Ref	
Description	Upstanding ruined church, largely ivy covered. Interior is gravelled, with some graves and an enclosed burial plot. Associated with graveyard (LF019-05002) and possible church (LF019-05003).		
Ownership	Public	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Included on tourist information board in Ardagh.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from main road
Intervisibility	Intervisible with church LF019-051.
Road Access	A main road runs past the front of the site
Parking	Parking visible on opposite side of road, in the carpark of the community centre.
Public Transport	
Approach Topography	Fairly level. Footpaths at sides of road. However there is a step up from footpath to graveyard.
Approach Surface	Tarmac
Approach Safety	No break in roadside kerb to facilitate road crossing.
Approach Width	c.1.3m Approach Gate width >800mm
Gate type	Single wrought iron gate. Difficult to open.

<i>Site Topography</i>	Gentle slope from the main road to the church.
<i>Site Paths</i>	Gravel path to church, no paths in graveyard
<i>Paths Surfacing</i>	Gravel, but becoming mossy and grassed over.
<i>Paths Width</i>	1 - 1.3m
<i>Hazards</i>	Overgrowth in places may hide low stones and other trip hazards. Church ruins may be unstable. In addition litter, including broken glass bottles, was noted during survey.
<i>Maintenance</i>	Not regularly maintained.
<i>Condition of Monument</i>	Ruined
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	019-050002	Monument	Graveyard
Location/ Townland	Ardagh Demesne	National Grid Ref:	220236 E 268753 N
		RPS Ref	
		National Monument Ref	
Description	Circular graveyard, somewhat overgrown in parts, associated with churches (LF019-05001 and LF019-05003). Circular bank continues to the south outside the graveyard wall, suggesting an early medieval origin for the site.		
Ownership	Public	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Included on tourist information board in Ardagh.
Local Sources Directions	
Graveyard Survey	#08 Ardagh at Church Ruins Graveyard, Ardagh. No wheelchair access. No designated parking available. A small area of path runs between the entrance and the church ruins. Access is private. Reputed to be the burial place of insurgent leader 'Big Pat Farrell', killed at the Battle of Granard in 1798 (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13312037
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from main road
Intervisibility	Intervisible with church LF019-051.
Road Access	A main road runs past the front of the site
Parking	Parking visible on opposite side of road, in the carpark of the community centre.
Public Transport	
Approach Topography	Fairly level. Footpaths at sides of road. However there is a step up from footpath to graveyard.
Approach Surface	Tarmac

Approach Safety	No break in roadside kerb to facilitate road crossing.	
Approach Width	c.1.3m	Approach Gate width >800mm
Gate type	Single wrought iron gate. Difficult to open.	
Site Topography	Gentle slope from the main road to the church.	
Site Paths	Gravel path to church, no paths in graveyard	
Paths Surfacing	Gravel, but becoming mossy and grassed over.	
Paths Width	1 - 1.3m	
Hazards	Overgrowth in places may hide low stones and other trip hazards. Church ruins may be unstable. In addition litter, including broken glass bottles, was noted during survey.	
Maintenance	Not regularly maintained.	
Condition of Monument	Overgrown	
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>
	On-site Seating <input type="checkbox"/>	On-site Toilets <input type="checkbox"/>
On-site facilities	None.	
Notes		

RMP Ref: LF-	019-050003	Monument	Church - possible
Location/ Townland	Ardagh Demesne	National Grid Ref:	220225 E 268759 N
		RPS Ref	
		National Monument Ref	
Description	No upstanding remains. Possible site of medieval church.		
Ownership	Public	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Included on tourist information board in Ardagh.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	A main road runs past the front of the site
Parking	Parking visible on opposite side of road, in the carpark of the community centre.
Public Transport	
Approach Topography	Fairly level. Footpaths at sides of road. However there is a step up from footpath to graveyard.
Approach Surface	Tarmac
Approach Safety	No break in roadside kerb to facilitate road crossing.
Approach Width	c.1.3m Approach Gate width >800mm
Gate type	Single wrought iron gate. Difficult to open.

<i>Site Topography</i>	Gentle slope from the main road to the church.
<i>Site Paths</i>	Gravel path to church, no paths in graveyard
<i>Paths Surfacing</i>	Gravel, but becoming mossy and grassed over.
<i>Paths Width</i>	1 - 1.3m
<i>Hazards</i>	Overgrowth in places may hide low stones and other trip hazards. Church ruins may be unstable. In addition litter, including broken glass bottles, was noted during survey.
<i>Maintenance</i>	
<i>Condition of Monument</i>	Not identifiable
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	019-051001	Monument	Cathedral
Location/ Townland	Ardagh Demesne		National Grid Ref: 220386 <i>E</i> 268614 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	St. Mel's Church. Remains of rectangular stone structure, with cyclopean masonry. Excavated in the 1960s, and of 8th century date. During excavations, an earlier wooden church was also identified.		
Ownership	Public	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Included on tourist information board in Ardagh. Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided. National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13312032
Internet Directions	

Field Survey:

Road Signs	Sign for site from Main St., Ardagh
Site Signs	Information sign at entrance, but this is weathered and difficult to read.
Visibility	Visible from Main St.
Intervisibility	Intervisible with church and graveyard LF019-050
Road Access	Main road through Ardagh runs adjacent to the site.
Parking	Not designated parking. Roadside parking in village and parking space available at the nearby Community Centre and school.
Public Transport	
Approach Topography	Gentle slope upwards to main front entrance, but steps at rear entrance, allowing access to cathedral ruins.

Approach Surface	Tarmac laneway to front, concrete steps to rear.			
Approach Safety	No visible hazards			
Approach Width	c.2m at main entrance, c1.3m at steps	Approach Gate width	c.2m	
Gate type	Lych-gate at main entrance, currently closed due to construction work on the church.			
Site Topography	Level access to present-day church, but steps at door and steps at only access to cathedral remains.			
Site Paths	Gravel pathway around part of exterior of cathedral, with a gravel-covered interior also. A wide path leads from gate to present church. No pathways extend through graveyard.			
Paths Surfacing	Gravel, tarmac.			
Paths Width	Main pathway to modern church is c.2m, the path around the cathedral is >2m, but the entrance to the interior of the cathedral is just 1m (this is an original feature so cannot be altered).			
Hazards	No visible hazards. Church is currently undergoing renovation works, and presence of construction machinery and debris constitutes a temporary hazard.			
Maintenance	Well maintained.			
Condition of Monument	Ruined but stable. Good condition.			
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/>	On-site Toilets <input type="checkbox"/>
On-site facilities	Lighting for church only.			
Notes				

RMP Ref: LF-	019-051002	Monument	Graveyard
Location/ Townland	Ardagh Demesne		National Grid Ref: 220358 <i>E</i> 268633 <i>N</i>
		RPS Ref	97; 98
		National Monument Ref	
Description	Graveyard associated with 19th century church and early medieval remains. Grass-covered area with numerous, largely 19th and 20th century, gravestones surrounding church and cathedral remains. 19th century church and lychgate are Protected Structures		
Ownership	Public	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Included on tourist information board in Ardagh.
Local Sources Directions	
Graveyard Survey	#07 Ardagh Graveyard at Saint Mel's Ruins and present Church of Ireland, Ardagh. Wheelchair access to modern church. No designated parking spaces. Private access (Church of Ireland). Entrances are an 'ornamental Lichfield' from the village green, and steps and a low wrought-iron gate from the Edgeworthstown road (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided. National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13312032
Internet Directions	

Field Survey:

Road Signs	Sign for site from Main St., Ardagh
Site Signs	Information sign at entrance, but this is weathered and difficult to read.
Visibility	Visible from Main St.
Intervisibility	Intervisible with church and graveyard LF019-050
Road Access	Main road through Ardagh runs adjacent to the site.
Parking	Not designated parking. Roadside parking in village and parking space available at the nearby Community Centre and school.
Public Transport	

Approach Topography	Gentle slope upwards to main front entrance, but steps at rear entrance, allowing access to cathedral ruins.
Approach Surface	Tarmac laneway to front, concrete steps to rear.
Approach Safety	No visible hazards
Approach Width	c.2m at main entrance, c1.3m at steps <i>Approach Gate width</i> c.2m
Gate type	Lych-gate at main entrance, currently closed due to construction work on the church.
Site Topography	Level access to present-day church, but steps at door and steps at only access to cathedral remains. Ground in graveyard slightly uneven.
Site Paths	Gravel pathway around part of exterior of cathedral, with a gravel-covered interior also. A wide path leads from gate to present church. No pathways extend through graveyard.
Paths Surfacing	Gravel, tarmac.
Paths Width	Main pathway to modern church is c.2m, the path around the cathedral is >2m, but the entrance to the interior of the cathedral is just 1m (this is an original feature so cannot be altered).
Hazards	No visible hazards. Church is currently undergoing renovation works, and presence of construction machinery and debris constitutes a temporary hazard.
Maintenance	Grass in graveyard overgrown in places and requires further maintenance.
Condition of Monument	Good.
Child friendly <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
On-site facilities	Lighting for church only.
Notes	

RMP Ref: LF-	019-051003	Monument	Church
Location/ Townland	Ardagh Demesne	National Grid Ref:	220386 E 268614 N
		RPS Ref	
		National Monument Ref	
Description	An earlier (pre-8thC A.D.) church was identified during excavations here in the 1960s, and was probably a precursor of the stone-built cathedral. This church is no longer extant.		
Ownership	Public	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Included on tourist information board in Ardagh.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	Sign for site from Main St., Ardagh
Site Signs	Information sign at entrance, but this is weathered and difficult to read.
Visibility	No extant remains
Intervisibility	
Road Access	Main road through Ardagh runs adjacent to the site.
Parking	Not designated parking. Roadside parking in village and parking space available at the nearby Community Centre and school.
Public Transport	
Approach Topography	Gentle slope upwards to main front entrance, but steps at rear entrance, allowing access to cathedral ruins.
Approach Surface	Tarmac laneway to front, concrete steps to rear.
Approach Safety	No visible hazards
Approach Width	c.2m at main entrance, c1.3m at steps
Approach Gate width	c.2m

Gate type	Lych-gate at main entrance, currently closed due to construction work on the church.
Site Topography	Level access to present-day church, but steps at door and steps at only access to cathedral remains. Ground in graveyard slightly uneven.
Site Paths	Gravel pathway around part of exterior of cathedral, with a gravel-covered interior also. A wide path leads from gate to present church. No pathways extend through graveyard.
Paths Surfacing	Gravel, tarmac.
Paths Width	Main pathway to modern church is c.2m, the path around the cathedral is >2m, but the entrance to the interior of the cathedral is just 1m (this is an original feature so cannot be altered).
Hazards	No visible hazards. Church is currently undergoing renovation works, and presence of construction machinery and debris constitutes a temporary hazard.
Maintenance	
Condition of Monument	Non-extant. Site of, only.
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/> On-site Staff <input type="checkbox"/> On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	Outdoor lighting at modern church.
Notes	

RMP Ref: LF-	019-070001	Monument	Castle - Unclassified possible
Location/ Townland	Drumming	National Grid Ref:	219513 E 267544 N
		RPS Ref	
		National Monument Ref	
Description	No upstanding remains.		
Ownership	Private	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

Site Topography

Site Paths

Paths Surfacing

Paths Width

Hazards

Maintenance

Condition of Monument

Child friendly *On-site Information* *On-site Staff* *On-site Seating* *On-site Toilets*

On-site facilities

Notes

RMP Ref: LF-	019-070002	Monument	Font possible
Location/ Townland	Drumming	National Grid Ref:	219128 <i>E</i> 267751 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Not identified on site. Site is currently occupied by the ruins of a large house and farm, in use as a farmyard.		
Ownership	Private	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Not identified on site.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	019-073	Monument	Ritual Site - Holy Well
Location/ Townland	Banghill	National Grid Ref:	220049 E 268022 N
		RPS Ref	
		National Monument Ref	
Description	Circular well of some 2m diameter, stone/concrete lined with more recent crenellated superstructure. Located in wooded area to side of field.		
Ownership	Public/Private	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	B/C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Informal sign at gate, now very faded
Visibility	
Intervisibility	
Road Access	Access through private field.
Parking	
Public Transport	
Approach Topography	Across fields under grazing with a field ditch.
Approach Surface	Grass and wooded area
Approach Safety	Barbed wire and electric fences between fields.
Approach Width	
	Approach Gate width >800m
Gate type	

<i>Site Topography</i>	Slight slope from gate, soft ground.
<i>Site Paths</i>	Informal trackway through wooded area, now largely disused.
<i>Paths Surfacing</i>	Earthen ground
<i>Paths Width</i>	
<i>Hazards</i>	Overgrowth hiding uneven ground - trip hazards present in wooded area. Well is also slightly overgrown, with low surrounding wall.
<i>Maintenance</i>	Not recently maintained
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	019-073001	Monument	Ritual Site - Holy Tree/Bush
Location/ Townland	Banghill	National Grid Ref:	220049 <i>E</i> 268022 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Blackthorn wishing/ prayer tree located beside Holy Well (LLF019-073), with small strips of material and other objects attached to it.		
Ownership	Public/ Private	Date of Inspection	18/09/09
		Inspected By	SMcG
		Accessibility Rating	B/C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Informal sign at gate, now very faded
Visibility	
Intervisibility	
Road Access	Access through private field.
Parking	
Public Transport	
Approach Topography	Across fields under grazing with a field ditch.
Approach Surface	Grass and wooded area
Approach Safety	Barbed wire and electric fences between fields.
Approach Width	
	Approach Gate width >800m
Gate type	

<i>Site Topography</i>	Slight slope from gate, soft ground.
<i>Site Paths</i>	Informal trackway through wooded area, now largely disused.
<i>Paths Surfacing</i>	Earthen ground
<i>Paths Width</i>	
<i>Hazards</i>	Overgrowth hiding uneven ground - trip hazards present in wooded area. Well is also slightly overgrown, with low surrounding wall.
<i>Maintenance</i>	Not recently maintained
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	020-023	Monument	Graveyard
Location/ Townland	Glen	National Grid Ref:	225757 E 268696 N
		RPS Ref	
		National Monument Ref	
Description	Associated with possible church LF020-023001. No visible features belonging to graveyard.		
Ownership	Private.	Date of Inspection	15/09/09
		Inspected By	McG / A
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#11 Glen Graveyard, Ardagh. Not wheelchair accessible. No designated parking spaces. No pathways. Privately owned (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	Motte (LF020-024) is visible from site.
Road Access	Located off small country lane
Parking	No designated parking. Parking may be possible at roadside
Public Transport	
Approach Topography	Level
Approach Surface	
Approach Safety	Overgrowth presents difficulties.

<i>Approach Width</i>	1.8m	<i>Approach Gate width</i>	
<i>Gate type</i>	No gate present.		
<i>Site Topography</i>	Overgrowth makes ground levels difficult to ascertain		
<i>Site Paths</i>	Located in farmyard		
<i>Paths Surfacing</i>			
<i>Paths Width</i>			
<i>Hazards</i>	Farm machinery in vicinity.		
<i>Maintenance</i>	Not maintained		
<i>Condition of Monument</i>	Not visible		
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>	<i>On-site Staff</i> <input type="checkbox"/>	<i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.		
<i>Notes</i>			

RMP Ref: LF-	020-023001	Monument	Church possible
Location/ Townland	Glen	National Grid Ref:	225764 E 268702 N
		RPS Ref	
		National Monument Ref	
Description	Ruins of church walls visible on 3 sides. Associated with graveyard (LF020-023).		
Ownership	Private.	Date of Inspection	15/09/09
		Inspected By	McG / A
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	Motte (LF020-024) is visible from site.
Road Access	Located off small country lane
Parking	No designated parking. Parking may be possible at roadside
Public Transport	
Approach Topography	Level
Approach Surface	
Approach Safety	Overgrowth presents difficulties.
Approach Width	1.8m
	Approach Gate width
Gate type	No gate present.

<i>Site Topography</i>	Overgrowth makes ground levels difficult to ascertain
<i>Site Paths</i>	Located in farmyard
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Farm machinery in vicinity.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Ruined.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	020-033	Monument	Ecclesiastical Enclosure
Location/ Townland	Killeen (Ardagh By.)	National Grid Ref:	225337 E 265641 N
		RPS Ref	
		National Monument Ref	
Description	Raised sub-circular platform enclosure, divided by field boundary. No internal features were visible.		
Ownership	Private	Date of Inspection	15/09/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from approach laneway
Intervisibility	
Road Access	Access via muddy, unsurfaced laneway, with high centre-line.
Parking	
Public Transport	
Approach Topography	Fairly level approach along lane and across field. However, footing is uneven.
Approach Surface	Grass, stony earth
Approach Safety	Barbed wire and electric fences present along approach and in field. Grazing cattle may be present.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Gate is tied, not allowing access

<i>Site Topography</i>	Enclosure itself is steep sided and the interior has uneven ground.
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Presence of grazing animals.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Subdivided by field boundary.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	020-033001	Monument	Children's Burial Ground possible
Location/ Townland	Killeen (Ardagh By.)		National Grid Ref: 225337 <i>E</i> 265641 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Located within enclosure (LF-020-033). No features visible.		
Ownership	Private	Date of Inspection	15/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	Privately owned. 'Inscribed slab removed from site by The Board of Works many years ago' (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Not visible
Intervisibility	
Road Access	Access via muddy, unsurfaced laneway, with high centre-line.
Parking	
Public Transport	
Approach Topography	Fairly level approach along lane and across field. However, footing is uneven.
Approach Surface	Grass, stony earth
Approach Safety	Barbed wire and electric fences present along approach and in field. Grazing cattle may be present.
Approach Width	>1.8m
Approach Gate width	>800mm

<i>Gate type</i>	Gate is tied, not allowing access
<i>Site Topography</i>	Enclosure itself is steep sided and the interior has uneven ground.
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Presence of grazing animals.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Not identifiable - no above ground features.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	020-033002	Monument	Pillar Stone		
Location/ Townland	Killeen (Ardagh By.)		National Grid Ref:	225337	E
				265641	N
			RPS Ref		
			National Monument Ref		
Description	Not identifiable at site.				
Ownership		Date of Inspection		Inspected By	
				Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	By unpaved road, with high central grassy line.
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

Site Topography

Site Paths

Paths Surfacing

Paths Width

Hazards

Maintenance

Condition of Monument

Child friendly *On-site Information* *On-site Staff* *On-site Seating* *On-site Toilets*

On-site facilities

Notes

RMP Ref: LF-	020-033003	Monument	Cross-inscribed Stone (original location)				
Location/ Townland	Killeen (Ardagh By.)		National Grid Ref:	225337	E	265647	N
			RPS Ref				
			National Monument Ref				
Description	Not present at site. Current location unknown.						
Ownership		Date of Inspection		Inspected By		Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

Site Topography

Site Paths

Paths Surfacing

Paths Width

Hazards

Maintenance

Condition of Monument

Child friendly *On-site Information* *On-site Staff* *On-site Seating* *On-site Toilets*

On-site facilities

Notes

RMP Ref: LF-	021-010001	Monument	Bawn possible		
Location/ Townland	Formoyle (Newcomen)		National Grid Ref:	200490	E
				263679	N
			RPS Ref		
			National Monument Ref		
Description	Bawn associated with House remains (LF021-010002), up to 2m height in parts. A projecting curve and window area present at one point, possibly remnants of a mural tower or watch-point.				
Ownership	Private	Date of Inspection	29/09/09	Inspected By	SMcG
				Accessibility Rating	C

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891. Page 86.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from side of road.
Intervisibility	
Road Access	Road runs adjacent to part of site.
Parking	No designated parking. Parking may be possible at roadside and at local school
Public Transport	
Approach Topography	Level
Approach Surface	Tarmac, grass
Approach Safety	No visible hazards.
Approach Width	
	Approach Gate width >800mm
Gate type	

<i>Site Topography</i>	Fairly level
<i>Site Paths</i>	No pathways
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Farm machinery in vicinity.
<i>Maintenance</i>	Generally well maintained. Has been reconstructed in 1 section close to road.
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	021-010002	Monument	House - 16th/17th century
Location/ Townland	Formoyle (Newcomen)		National Grid Ref: 200582 E 263656 N
		RPS Ref	
		National Monument Ref	
Description	Ruins of large stone-built building, comprising largely of a single wall with part of 2 return walls. Partially ivy covered. Possibly unstable.		
Ownership	Private	Date of Inspection	29/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	J.P. Farrell, "History of County Longford". Dollard Printinghouse, Dublin, 1891. Page 86.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from side of road.
Intervisibility	
Road Access	Road runs adjacent to part of site.
Parking	No designated parking. Parking may be possible at roadside and at local school
Public Transport	
Approach Topography	Level
Approach Surface	Tarmac, grass
Approach Safety	No visible hazards.
Approach Width	
	Approach Gate width >800mm
Gate type	

<i>Site Topography</i>	Fairly level
<i>Site Paths</i>	No pathways
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Farm machinery in vicinity, as within working farmyard. Structure may be unstable.
<i>Maintenance</i>	Not maintained.
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	021-010003	Monument	leerpark Boundary 17th century, possibl
Location/ Townland	Formoyle (Newcomen)	National Grid Ref:	199914 E 263245 N
		RPS Ref	
		National Monument Ref	
Description			
Ownership		Date of Inspection	
		Inspected By	
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	021-020	Monument	Ritual Site - Holy Well
Location/ Townland	Formoyle (Farrell)	National Grid Ref:	199702 E 262921 N
		RPS Ref	
		National Monument Ref	
Description	Not identifiable due to inaccessibility of area.		
Ownership		Date of Inspection	29/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	Marshy, overgrown approach - impassable.
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

Site Topography

Site Paths

Paths Surfacing

Paths Width

Hazards

Maintenance

Condition of Monument

Child friendly *On-site Information* *On-site Staff* *On-site Seating* *On-site Toilets*

On-site facilities

Notes

RMP Ref: LF-	021-031	Monument	Ecclesiastical Enclosure possible		
Location/ Townland	Caltragh Beg		National Grid Ref:	204579 E	261825 N
			RPS Ref		
			National Monument Ref		
Description	Not readily identifiable. Very little upstanding remains, with the best preservation along a curved hedge boundary with a house to the southwest. There is also a slight suggestion of a low bank in the field to the southeast.				
Ownership	Private	Date of Inspection	30/09/09	Inspected By	SMcG
				Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Located beside a small country lane off the main road.
Parking	No designated parking. Roadside parking may be possible
Public Transport	
Approach Topography	Level
Approach Surface	Grass
Approach Safety	No pedestrian crossing on road
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Fairly level. Monument is divided by a field boundary.
<i>Site Paths</i>	No pathways
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Very little upstanding remains visible. Not readily identifiable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	021-033	Monument	Ecclesiastical Enclosure
Location/ Townland	Cashel	National Grid Ref:	201458 E 260140 N
		RPS Ref	
		National Monument Ref	
Description	Large, originally circular enclosure. Walled where encloses graveyard, but original bank is partially preserved in fields to the east and south. It may also continue on the opposite side of the road, with stone banks apparent in a wooded area beside the road. Associated with church (LF021-033001).		
Ownership	Public / Private	Date of Inspection	29/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	Wheelchair accessible. Gravel pathways. Limited parking space. Fás information sign (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib/her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Roadsigns for Cashel Cemetery
Site Signs	
Visibility	Visible from road
Intervisibility	Intervisible with Inchcleraun Island (LF021-048__).
Road Access	Adjacent to road. Road actually cuts through enclosure.
Parking	Parking available in widened section of road on the opposite side to graveyard.
Public Transport	
Approach Topography	Level
Approach Surface	Tarmac
Approach Safety	No pedestrian crossings, but road is fairly quiet
Approach Width	Public road
	Approach Gate width >800m

<i>Gate type</i>	Single and double gates present, along with stone, stepped stile.
<i>Site Topography</i>	Fairly level. Ground level rise in centre of graveyard, and sloped down to the south.
<i>Site Paths</i>	Steps with railing to central area, also path along wall. Paths throughout the graveyard.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	1.3 - 1.5m
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	Graveyard well maintained. Sections of enclosure on private land, not protected.
<i>Condition of Monument</i>	Variable. Better preservation in area of graveyard.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input checked="" type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Seating present in graveyard.
<i>Notes</i>	

RMP Ref: LF-	021-033001	Monument	Church
Location/ Townland	Cashel	National Grid Ref:	201445 E 260139 N
		RPS Ref	
		National Monument Ref	
Description	Large rectangular stone building, probably originally quite ornate. Located within graveyard and associated with Ecclesiastical Enclosure (LF021-033)		
Ownership	Public	Date of Inspection	29/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Roadsigns for Cashel Cemetery
Site Signs	
Visibility	Visible from road
Intervisibility	Intervisible with Inchcleraun Island (LF021-048__).
Road Access	Adjacent to road. Road actually cuts through enclosure.
Parking	Parking available in widened section of road on the opposite side to graveyard.
Public Transport	
Approach Topography	Level
Approach Surface	Tarmac
Approach Safety	No pedestrian crossings, but road is fairly quiet
Approach Width	Public road <input type="text"/> Approach Gate width >800m
Gate type	Single and double gates present, along with stone, stepped stile.

<i>Site Topography</i>	Fairly level. Ground level rise in centre of graveyard, and sloped down to the south.
<i>Site Paths</i>	Steps with railing to central area, also path along wall. Paths throughout the graveyard.
<i>Paths Surfacing</i>	Concrete, grass in interior of church
<i>Paths Width</i>	1.3 - 1.5m. Doorway in church is only 0.7m wide - as this is an original feature it cannot be altered.
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	Well maintained generally. Overgrowth of grass in interior of church may hide low trip hazards.
<i>Condition of Monument</i>	Ruined but stable. Some ivy growth on wall needs to be kept cut back to prevent destabilisation of walls.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input checked="" type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Seating present in graveyard.
<i>Notes</i>	

RMP Ref: LF-	021-046	Monument	Church
Location/ Townland	Inchleraun	National Grid Ref:	199240 <i>E</i> 259360 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Church located on Inchcleraun Island. Not accessible - would require private boat.		
Ownership	Public	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Island is visible from shore
Intervisibility	
Road Access	Access by boat only.
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Unknown - inaccessible at time of survey.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	021-048001	Monument	Ecclesiastical Enclosure
Location/ Townland	Inchleraun	National Grid Ref:	199583 E 259158 N
		RPS Ref	
		National Monument Ref	091
Description	Early medieval monastery on Inchcleraun Island. One of the most important site in the county. However, at the time of the survey no means of accessing the island was available.		
Ownership	Public	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Island is visible from shore
Intervisibility	
Road Access	Access by boat only.
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Unknown - inaccessible at time of survey.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	021-048002	Monument	Church
Location/ Townland	Inchcleraun	National Grid Ref:	199625 E 259116 N
		RPS Ref	
		National Monument Ref	091
Description	Associated with Early Medieval Monastery on Inchcleraun Island.		
Ownership	Public	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Island is visible from shore
Intervisibility	
Road Access	Access by boat only.
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Unknown - inaccessible at time of survey.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	021-048003	Monument	Church
Location/ Townland	Inchcleraun	National Grid Ref:	199576 E 259162 N
		RPS Ref	
		National Monument Ref	091
Description	Associated with Early Medieval Monastery on Inchcleraun Island.		
Ownership	Public	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Island is visible from shore
Intervisibility	
Road Access	Access by boat only.
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Unknown - inaccessible at time of survey.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	021-048004	Monument	Religious House - Augustinian Canons		
Location/ Townland	Inchcleraun		National Grid Ref:	199626	E
				259127	N
			RPS Ref		
			National Monument Ref	091	
Description	Associated with Early Medieval Monastery on Inchcleraun Island.				
Ownership	Public	Date of Inspection	14/10/09	Inspected By	SMcG
				Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Island is visible from shore
Intervisibility	
Road Access	Access by boat only.
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Unknown - inaccessible at time of survey.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	021-048005	Monument	Cross-Slab (original location)		
Location/ Townland	Inchcleraun		National Grid Ref:	199630	E
				259120	N
			RPS Ref		
			National Monument Ref	091	
Description	Associated with Early Medieval Monastery on Inchcleraun Island.				
Ownership	Public	Date of Inspection	14/10/09	Inspected By	SMcG
				Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Island is visible from shore
Intervisibility	
Road Access	Access by boat only.
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Present location unknown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	021-048006	Monument	Church
Location/ Townland	Inchcleraun	National Grid Ref:	199603 E 259152 N
		RPS Ref	
		National Monument Ref	091
Description	Associated with Early Medieval Monastery on Inchcleraun Island.		
Ownership	Public	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Island is visible from shore
Intervisibility	
Road Access	Access by boat only.
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Unknown - inaccessible at time of survey.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	021-048007	Monument	Church
Location/ Townland	Inchcleraun	National Grid Ref:	199554 E 259036 N
		RPS Ref	
		National Monument Ref	091
Description	Associated with Early Medieval Monastery on Inchcleraun Island.		
Ownership	Public	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Island is visible from shore
Intervisibility	
Road Access	Access by boat only.
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Unknown - inaccessible at time of survey.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	021-048009	Monument	Cross-Slab (original location)
Location/ Townland	Inchcleraun	National Grid Ref:	199630 E 259120 N
		RPS Ref	
		National Monument Ref	091
Description	Associated with Early Medieval Monastery on Inchcleraun Island.		
Ownership	Public	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Island is visible from shore
Intervisibility	
Road Access	Access by boat only.
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Present location unknown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	021-048010	Monument	Cross-Slab (original location)
Location/ Townland	Inchcleraun	National Grid Ref:	199630 E 259120 N
		RPS Ref	
		National Monument Ref	091
Description	Associated with Early Medieval Monastery on Inchcleraun Island.		
Ownership	Public	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Island is visible from shore
Intervisibility	
Road Access	Access by boat only.
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Present location unknown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	021-048011	Monument	Cross-Slab (original location)
Location/ Townland	Inchcleraun	National Grid Ref:	199630 E 259120 N
		RPS Ref	
		National Monument Ref	091
Description	Associated with Early Medieval Monastery on Inchcleraun Island.		
Ownership	Public	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Island is visible from shore
Intervisibility	
Road Access	Access by boat only.
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Present location unknown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	021-048012	Monument	Cross-Slab (original location)
Location/ Townland	Inchcleraun	National Grid Ref:	<input type="text"/> E <input type="text"/> N
		RPS Ref	<input type="text"/>
		National Monument Ref	091
Description	Associated with Early Medieval Monastery on Inchcleraun Island. Not considered an RMP site on www.archaeology.ie website.		
Ownership	Public	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Island is visible from shore
Intervisibility	
Road Access	Access by boat only.
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	<input type="text"/> Approach Gate width <input type="text"/>

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Present location unknown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	021-048013	Monument	Cross-Slab (original location)
Location/ Townland	Inchcleraun	National Grid Ref:	<input type="text"/> E <input type="text"/> N
		RPS Ref	<input type="text"/>
		National Monument Ref	091
Description	Associated with Early Medieval Monastery on Inchcleraun Island. Not considered an RMP site on www.archaeology.ie website.		
Ownership	Public	Date of Inspection	14/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Island is visible from shore
Intervisibility	
Road Access	Access by boat only.
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	<input type="text"/> Approach Gate width <input type="text"/>

<i>Gate type</i>	
<i>Site Topography</i>	
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	
<i>Condition of Monument</i>	Present location unknown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	022-028001	Monument	Ringfort - Rath
Location/ Townland	Cormaglava, Cornaguillagh	National Grid Ref:	206018 E 260110 N
		RPS Ref	
		National Monument Ref	
Description	Sub-circular enclosure - not very obvious. Ringfort is truncated/cut through by road. A ring of trees runs along the bank of the ringfort, while the ditch is generally overgrown.		
Ownership	Private	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from road
Intervisibility	
Road Access	Road runs alongside the ringfort (or through part of it)
Parking	No designated parking.
Public Transport	
Approach Topography	Level - road
Approach Surface	Tarmac
Approach Safety	No footpath along roadside, no pedestrian crossing. Electric fence on inner side of entrance gate.
Approach Width	>1.8m Approach Gate width >800mm
Gate type	Field gate - however, rusted, broken and with electric fence on inside.

<i>Site Topography</i>	Undulating ground, uneven - partly due to grazing animals. Tracks through bank and ditch created by animals.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Grazing cattle in field. Electric fence nearby.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Bank and ditch overgrown. Some damage from animals and partly cut/truncated by road.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	022-028002	Monument	Enclosure
Location/ Townland	Cormaglava, Cornaguillagh		National Grid Ref: 206048 <i>E</i> 260074 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Attached to ringfort (LF028-001).		
Ownership	Private	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from road
Intervisibility	
Road Access	Road runs alongside the ringfort (or through part of it)
Parking	No designated parking.
Public Transport	
Approach Topography	Level - road
Approach Surface	Tarmac
Approach Safety	No footpath along roadside, no pedestrian crossing. Electric fence on inner side of entrance gate.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Field gate - however, rusted, broken and with electric fence on inside.

<i>Site Topography</i>	Undulating ground, uneven - partly due to grazing animals.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Grazing cattle in field. Electric fence nearby.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Bank and ditch overgrown. Some damage from animals and partly cut/truncated by road.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	022-028003	Monument	Souterrain possible
Location/ Townland	Cormaglava, Cornaguillagh	National Grid Ref:	206039 <i>E</i> 260092 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Not identifiable. A raised linear feature within ringfort (LF022-028001) may be related to the souterrain.		
Ownership	Private	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Road runs alongside the ringfort (or through part of it)
Parking	No designated parking.
Public Transport	
Approach Topography	Level - road
Approach Surface	Tarmac
Approach Safety	No footpath along roadside, no pedestrian crossing. Electric fence on inner side of entrance gate.
Approach Width	>1.8m Approach Gate width >800mm
Gate type	Field gate - however, rusted, broken and with electric fence on inside.

<i>Site Topography</i>	Undulating ground, uneven - partly due to grazing animals.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Grazing cattle in field. Electric fence nearby.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Not identifiable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	022-032	Monument	Church
Location/ Townland	Kilcommock Glebe		National Grid Ref: 212408 <i>E</i> 261331 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Ruins of large stone built church. Walls present to full height.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13402211
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign for 'Kilcommock Graveyard', but no historical information present
Visibility	Visible from road
Intervisibility	Intervisible with Holy Well LF022-050
Road Access	Located at side of main road
Parking	Parking space present for 2 - 3 cars
Public Transport	
Approach Topography	Fairly level approach from parking area
Approach Surface	Gravel
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width c.1.2m
Gate type	Easily opened.

<i>Site Topography</i>	Change in ground level in graveyard.
<i>Site Paths</i>	Paths throughout graveyard.
<i>Paths Surfacing</i>	Concrete paths - handrails on sloped paths between levels of graveyard. Rough grass and graves in interior of church.
<i>Paths Width</i>	1.3m
<i>Hazards</i>	Signs warning of 'Dangerous church building and headstones' and 'Slippery Steps' at stile. However, in generally ruins appear relatively stable.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Very good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No on-site lighting.
<i>Notes</i>	

RMP Ref: LF-	022-032001	Monument	Graveyard
Location/ Townland	Kilcommock Glebe	National Grid Ref:	212410 <i>E</i> 261321 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Graveyard associated with church LF022-023. Laid out over two levels. A pathway extends around inner perimeter.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#67 Kilcommock Graveyard, Kilcommock. Mostly wheelchair accessible. No designated parking spaces. Public access (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13402211
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign for 'Kilcommock Graveyard', but no historical information present
Visibility	Visible from road
Intervisibility	Intervisible with Holy Well LF022-050
Road Access	Located at side of main road
Parking	Parking space present for 2 - 3 cars
Public Transport	
Approach Topography	Fairly level approach from parking area
Approach Surface	Gravel
Approach Safety	No visible hazards
Approach Width	>1.8m
Approach Gate width	c.1.2m

<i>Gate type</i>	Easily opened. Stone stile also present.
<i>Site Topography</i>	Change in ground level in graveyard.
<i>Site Paths</i>	Paths throughout and around graveyard.
<i>Paths Surfacing</i>	Concrete paths - handrails on sloped paths between levels of graveyard. Rough grass and graves in interior of church.
<i>Paths Width</i>	1.3m
<i>Hazards</i>	Signs warning of 'Dangerous church building and headstones' and 'Slippery Steps' at stile. However, in generally ruins appear relatively stable.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Very good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No on-site lighting.
<i>Notes</i>	

RMP Ref: LF-	022-032002	Monument	Memorial Stone (17th century)
Location/ Townland	Kilcommock Glebe	National Grid Ref:	212445 <i>E</i> 261326 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Set into wall at gated entrance to graveyard (LF022-032001)		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13402211
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign for 'Kilcommock Graveyard', but no historical information present
Visibility	Visible from road
Intervisibility	Intervisible with Holy Well LF022-050
Road Access	Located at side of main road
Parking	Parking space present for 2 - 3 cars
Public Transport	
Approach Topography	Fairly level approach from parking area
Approach Surface	Gravel
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width c.1.2m
Gate type	Easily opened. Stone stile also present.

<i>Site Topography</i>	Change in ground level in graveyard.
<i>Site Paths</i>	Paths throughout and around graveyard.
<i>Paths Surfacing</i>	Concrete paths - handrails on sloped paths between levels of graveyard. Rough grass and graves in interior of church.
<i>Paths Width</i>	1.3m
<i>Hazards</i>	No hazards at monument
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good. Located at entrance so easily accessed.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No on-site lighting.
<i>Notes</i>	

RMP Ref: LF-	022-032003	Monument	Memorial Stone (17th century)
Location/ Townland	Kilcommock Glebe	National Grid Ref:	212445 <i>E</i> 261326 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Set into wall at gated entrance to graveyard (LF022-032001)		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign for 'Kilcommock Graveyard', but no historical information present
Visibility	Visible from road
Intervisibility	Intervisible with Holy Well LF022-050
Road Access	Located at side of main road
Parking	Parking space present for 2 - 3 cars
Public Transport	
Approach Topography	Fairly level approach from parking area
Approach Surface	Gravel
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width c.1.2m
Gate type	Easily opened. Stone stile also present.

<i>Site Topography</i>	Change in ground level in graveyard.
<i>Site Paths</i>	Paths throughout and around graveyard.
<i>Paths Surfacing</i>	Concrete paths - handrails on sloped paths between levels of graveyard. Rough grass and graves in interior of church.
<i>Paths Width</i>	1.3m
<i>Hazards</i>	No hazards at monument
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good. Located at entrance so easily accessed.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No on-site lighting.
<i>Notes</i>	

RMP Ref: LF-	022-045	Monument	Ritual Site - Holy Well
Location/ Townland	Tirlickeen	National Grid Ref:	213313 <i>E</i> 259309 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Tober Patrick. Not readily identifiable. Very overgrown and inaccessible due to fence. No masonry present and well appears more as spring.		
Ownership	Private	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Access through fields only
Parking	No designated parking.
Public Transport	
Approach Topography	Slightly undulating ground in fields.
Approach Surface	Grass
Approach Safety	
Approach Width	
	Approach Gate width >800mm
Gate type	Field gates

<i>Site Topography</i>	Uneven ground
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Cattle may be present in fields. Uneven ground
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Not readily identifiable. Overgrown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	022-050	Monument	Ritual Site - Holy Well
Location/ Townland	Kilcommock Glebe	National Grid Ref:	212297 E 261322 N
		RPS Ref	
		National Monument Ref	
Description	Partially stone-lined shallow spring well, located in field to rear of graveyard (LF022-032001). A shallow stream runs out from well. Well is cordoned off by sheep-wire and wooden fence so not directly accessible but protected.		
Ownership	Private	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	Intervisible with Church (LF022-032) and graveyard (LF-022-032001).
Road Access	Accessed through graveyard and field
Parking	Parking available at graveyard
Public Transport	
Approach Topography	Uneven, undulating ground in field
Approach Surface	Rough pasture
Approach Safety	Possible trip hazards in field. Grazing animals may be present.
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Uneven ground. Ground is soft and saturated close to well
<i>Site Paths</i>	Informal grassy path worn between gate and well - indicates well is still visited locally.
<i>Paths Surfacing</i>	Grass
<i>Paths Width</i>	
<i>Hazards</i>	Uneven, wet ground.
<i>Maintenance</i>	Well maintained - well is protected from animals and kept clear of vegetation.
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	022-051	Monument	Standing Stone
Location/ Townland	Cartonbrack	National Grid Ref:	214450 E 262320 N
		RPS Ref	
		National Monument Ref	
Description	Upright stone beside tree in field.		
Ownership	Private	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Clearly visible from roadside
Intervisibility	
Road Access	Access through field from road
Parking	Roadside parking may be possible
Public Transport	
Approach Topography	Ground slopes gently down from gate to stone.
Approach Surface	Grass
Approach Safety	No visible hazards
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Fairly level in immediate vicinity of stone
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Grazing animals may be present. Nettles growing at base of stone.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	022-057040	Monument	Road - Togher (Tertiary)
Location/ Townland	Cloonbreany	National Grid Ref:	209970 E 262630 N
		RPS Ref	
		National Monument Ref	
Description	Tertiary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Mentioned in 'Lakelands & Inland Waterways: Ireland' (Failte Ireland / Waterways Ireland booklet). Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet Guide (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09). Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre from roadway leading from Kenagh village to R392 (Lanesboro to Ballymahon r
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	022-058001	Monument	Road - Togher (Primary)
Location/ Townland	Cloonbreany, Corlea	National Grid Ref:	209952 E 262652 N
		RPS Ref	
		National Monument Ref	677
Description	Primary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Mentioned in 'Lakelands & Inland Waterways: Ireland' (Failte Ireland / Waterways Ireland booklet). Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09) Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre from roadway leading from Kenagh village to R392 (Lanesboro to Ballymahon r
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	022-058002	Monument	Road - Togher (Secondary)
Location/ Townland	Cloonbreany	National Grid Ref:	210041 E 262611 N
		RPS Ref	
		National Monument Ref	677
Description	Secondary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Mentioned in 'Lakelands & Inland Waterways: Ireland' (Failte Ireland / Waterways Ireland booklet). Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09) Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	022-058003	Monument	Road - Togher (Secondary)
Location/ Townland	Cloonbreany	National Grid Ref:	209935 E 262650 N
		RPS Ref	
		National Monument Ref	677
Description	Secondary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Mentioned in 'Lakelands & Inland Waterways: Ireland' (Failte Ireland / Waterways Ireland booklet). Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09) Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre from roadway leading from Kenagh village to R392 (Lanesboro to Ballymahon r
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	022-058004	Monument	Road - Togher (Secondary)
Location/ Townland	Cloonbreany	National Grid Ref:	209943 <i>E</i> 262653 <i>N</i>
		RPS Ref	
		National Monument Ref	677
Description	Secondary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Mentioned in 'Lakelands & Inland Waterways: Ireland' (Failte Ireland / Waterways Ireland booklet). Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09) Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	022-058007	Monument	Road - Togher (Tertiary)
Location/ Townland	Cloonbreany	National Grid Ref:	209970 E 262630 N
		RPS Ref	
		National Monument Ref	677
Description	Tertiary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Mentioned in 'Lakelands & Inland Waterways: Ireland' (Failte Ireland / Waterways Ireland booklet). Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09) Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre from roadway leading from Kenagh village to R392 (Lanesboro to Ballymahon r
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	022-058008	Monument	Road - Togher (Tertiary)
Location/ Townland	Cloonbreany	National Grid Ref:	209990 E 262670 N
		RPS Ref	
		National Monument Ref	677
Description	Tertiary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Mentioned in 'Lakelands & Inland Waterways: Ireland' (Failte Ireland / Waterways Ireland booklet). Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09) Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	022-058009	Monument	Road - Togher (Tertiary)
Location/ Townland	Cloonbreany	National Grid Ref:	209970 E 262680 N
		RPS Ref	
		National Monument Ref	677
Description	Tertiary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Mentioned in 'Lakelands & Inland Waterways: Ireland' (Failte Ireland / Waterways Ireland booklet). Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09) Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre from roadway leading from Kenagh village to R392 (Lanesboro to Ballymahon r
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	022-058010	Monument	Road - Togher (Secondary)
Location/ Townland	Cloonbreany	National Grid Ref:	210033 E 262668 N
		RPS Ref	
		National Monument Ref	677
Description	Secondary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Mentioned in 'Lakelands & Inland Waterways: Ireland' (Failte Ireland / Waterways Ireland booklet). Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09) Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre from roadway leading from Kenagh village to R392 (Lanesboro to Ballymahon r
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	022-058011	Monument	Road - Togher (Tertiary)
Location/ Townland	Cloonbreany	National Grid Ref:	210030 <i>E</i> 262665 <i>N</i>
		RPS Ref	
		National Monument Ref	677
Description	Tertiary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Mentioned in 'Lakelands & Inland Waterways: Ireland' (Failte Ireland / Waterways Ireland booklet). Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09) Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre from roadway leading from Kenagh village to R392 (Lanesboro to Ballymahon r
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	022-058012	Monument	Road - Togher (Tertiary)
Location/ Townland	Cloonbreany	National Grid Ref:	210050 E 262665 N
		RPS Ref	
		National Monument Ref	677
Description	Tertiary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Mentioned in 'Lakelands & Inland Waterways: Ireland' (Failte Ireland / Waterways Ireland booklet). Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09) Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre from roadway leading from Kenagh village to R392 (Lanesboro to Ballymahon r
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	022-058013	Monument	Road - Togher (Tertiary)
Location/ Townland	Cloonbreany	National Grid Ref:	210125 E 262650 N
		RPS Ref	
		National Monument Ref	677
Description	Tertiary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Mentioned in 'Lakelands & Inland Waterways: Ireland' (Failte Ireland / Waterways Ireland booklet). Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09) Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre from roadway leading from Kenagh village to R392 (Lanesboro to Ballymahon r
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	022-058014	Monument	Road - Togher (Tertiary)
Location/ Townland	Cloonbreany	National Grid Ref:	210020 <i>E</i> 262635 <i>N</i>
		RPS Ref	
		National Monument Ref	677
Description	Tertiary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09) Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre from roadway leading from Kenagh village to R392 (Lanesboro to Ballymahon r
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	022-058015	Monument	Road - Togher (Tertiary)
Location/ Townland	Cloonbreany	National Grid Ref:	210000 E 262645 N
		RPS Ref	
		National Monument Ref	677
Description	Tertiary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Mentioned in 'Lakelands & Inland Waterways: Ireland' (Failte Ireland / Waterways Ireland booklet). Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09) Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre from roadway leading from Kenagh village to R392 (Lanesboro to Ballymahon r
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	022-058016	Monument	Road - Togher (Tertiary)
Location/ Townland	Cloonbreany	National Grid Ref:	209908 E 262614 N
		RPS Ref	
		National Monument Ref	677
Description	Tertiary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Mentioned in 'Lakelands & Inland Waterways: Ireland' (Failte Ireland / Waterways Ireland booklet). Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09) Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre from roadway leading from Kenagh village to R392 (Lanesboro to Ballymahon r
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	022-058017	Monument	Road - Togher (Tertiary)
Location/ Townland	Cloonbreany	National Grid Ref:	209859 E 262600 N
		RPS Ref	
		National Monument Ref	677
Description	Tertiary togher section of Iron Age togher complex extending across bog. Excavated in the 1980s and currently presented at an O.P.W. run Interpretative Centre. One section of the togher is preserved within the centre with a second section visible outside at rear of centre. All other sections are not visible, but preserved in-situ. However interpretative access is good.		
Ownership	Public	Date of Inspection	21/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Information about site included in Moore, S. (2007) Archaeological Monuments in County Longford. All information regarding the Corlea togher is provided at the Corlea Bog Interpretative Centre. Mentioned in 'Walking Tour of Longford Town' leaflet (Longford Community Resources Ltd.)
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	Information about the 'Corlea Trackway' included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09. Mentioned in 'Lakelands & Inland Waterways: Ireland' (Failte Ireland / Waterways Ireland booklet). Included in 'Things to do: Ireland East, on Dublin's Doorstep' (Failte Ireland Booklet). Included in 'Heritage Sites of Ireland' (No. 67; OPW leaflet)
National Sources Directions	
International Guidebooks	Lonely Planet (2006 ed.) p.474. Short entry on Corlea Trackway Visitor Centre: 'well worth an afternoon's excursion'. General directions given, from Longford. Rough Guide (2006 ed) p.197. 1/2 page paragraph on Corlea Trackway Visitor Centre, with some background information on the trackway. Guided tours described as 'excellent'. Directions given, but described as 'tricky to get to'.
Internet Information	Listed as one of the 'Top Attractions' in Co. Longford on www.irishtourist.com. However, a link provided failed to open. (accessed 16/10/09). A working link to the Corlea Trackway Visitor Centre site was available from www.heritageireland.ie (accessed 16/10/09) Corlea Trackway Visitor Centre is included under Heritage Centres at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Road signs for centre at junctions on main roads
Site Signs	Signs and information at centre
Visibility	Monument itself not visible, but centre visible from approach road
Intervisibility	
Road Access	Road access to centre from roadway leading from Kenagh village to R392 (Lanesboro to Ballymahon r
Parking	Available parking for cars and bikes. No designated disabled parking spaces.
Public Transport	
Approach Topography	Level to centre

Approach Surface	Gravel in carpark	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width
Gate type	No gate	
Site Topography		
Site Paths	Wooden walkway outside centre giving access to section of togher.	
Paths Surfacing	Wood	
Paths Width	>1.5m	
Hazards	No visible hazards	
Maintenance	Centre is very well maintained	
Condition of Monument	Good	
Child friendly <input checked="" type="checkbox"/>	On-site Information <input checked="" type="checkbox"/>	On-site Staff <input checked="" type="checkbox"/>
	On-site Seating <input checked="" type="checkbox"/>	On-site Toilets <input checked="" type="checkbox"/>
On-site facilities	Centre is close between October and April. Disabled toilets available. Tea-room present in centre.	
Notes		

RMP Ref: LF-	023-009001	Monument	Castle - Tower House
Location/ Townland	Mornin	National Grid Ref:	217289 E 263339 N
		RPS Ref	
		National Monument Ref	
Description	Ruins of tower house with three walls largely upstanding. The fourth wall and the interior is in a state of collapse and appears very unstable. Located on a slight rise in a field. Contains some original features but considerably unsafe.		
Ownership	Private	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Good visibility from roadside
Intervisibility	
Road Access	A short lane leads to the castle, which is fenced off from the rest of the field
Parking	No designated parking
Public Transport	
Approach Topography	Slope upwards to castle remains. Uneven ground
Approach Surface	Gravel laneway, grass
Approach Safety	Loose masonry strewn around on slope. Uneven ground. Some farm machinery present.
Approach Width	>1.8m
	Approach Gate width
Gate type	No gate

<i>Site Topography</i>	Very uneven ground
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Masonry and rubbles strewn on ground. Towerhouse appears very unstable and unsafe. Suggest not accessible.
<i>Maintenance</i>	Not maintained.
<i>Condition of Monument</i>	Ruined, unstable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	023-009002	Monument	House - Indeterminate Date possible		
Location/ Townland	Mornin	National Grid Ref:	217290	E	263345
		RPS Ref			
		National Monument Ref			
Description	Uncertain of identification. Ruined/abandoned house near Tower House (LF023-009001) but appears too modern to be considered archaeological.				
Ownership	Private	Date of Inspection	01/10/09	Inspected By	SMcG
		Accessibility Rating	D		

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

Site Topography

Site Paths

Paths Surfacing

Paths Width

Hazards

Maintenance

Condition of Monument

Child friendly *On-site Information* *On-site Staff* *On-site Seating* *On-site Toilets*

On-site facilities

Notes

RMP Ref: LF-	023-032001	Monument	Church
Location/ Townland	Glebe (Ardagh By., Foxhall ED)		National Grid Ref: 223019 <i>E</i> 264740 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Not readily identifiable. No structural remains visible in graveyard.		
Ownership	Public	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Signpost for Kilglass on the main road but no sign for graveyard.
Site Signs	No sign. Cross over gateway indicates a graveyard.
Visibility	Only visible from main road if looking down access lane
Intervisibility	Intervisible with Motte and Bailey (LF023-033)
Road Access	Lane leading from local road to graveyard
Parking	No designated parking. May be possible to park at side of access lane, but not very wide.
Public Transport	
Approach Topography	Fairly level lane
Approach Surface	compact gravel laneway with raised, grassy centre-strip
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width >1.8m
Gate type	Low double iron railed gates, easily opened. There is also a stone, stepped stile to one side of the

	gate.
<i>Site Topography</i>	Some undulating, uneven ground in graveyard, particularly where there is a circular enclosure surrounded by a low bank and ditch.
<i>Site Paths</i>	Pathway around the perimeter of the graveyard, but doesn't extend into centre of graveyard.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.1.3m
<i>Hazards</i>	Possibility of trip hazards in more overgrown sections of graveyard
<i>Maintenance</i>	Generally well maintained graveyard.
<i>Condition of Monument</i>	Not identifiable
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	023-032002	Monument	Graveyard				
Location/ Townland	Glebe (Ardagh By., Foxhall ED)		National Grid Ref:	223019	E	264740	N
			RPS Ref				
			National Monument Ref				
Description	Rectangular graveyard with inner circular enclosure, with low bank and shallow ditch apparent, located off-centre within graveyard. Some stone facing visible in exterior of circular enclosure with a raised area within the interior.						
Ownership	Public	Date of Inspection	01/10/09	Inspected By	SMcG	Accessibility Rating	B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Signpost for Kilglass on the main road but no sign for graveyard.	
Site Signs	No sign. Cross over gateway indicates a graveyard.	
Visibility	Only visible from main road if looking down access lane	
Intervisibility	Intervisible with Motte and Bailey (LF023-033)	
Road Access	Lane leading from local road to graveyard	
Parking	No designated parking. May be possible to park at side of access lane, but not very wide.	
Public Transport		
Approach Topography	Fairly level lane	
Approach Surface	Compact gravel laneway with raised, grassy centre-strip	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width >1.8m
Gate type	Low double iron railed gates, easily opened. There is also a stone, stepped stile to one side of the	

	gate.
<i>Site Topography</i>	Some undulating, uneven ground in graveyard, particularly where there is a circular enclosure surrounded by a low bank and ditch.
<i>Site Paths</i>	Pathway around the perimeter of the graveyard, but doesn't extend into centre of graveyard.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.1.3m
<i>Hazards</i>	Possibility of trip hazards in more overgrown sections of graveyard
<i>Maintenance</i>	Generally well maintained graveyard.
<i>Condition of Monument</i>	Not identifiable
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	023-032003	Monument	Architectural Fragment
Location/ Townland	Glebe (Ardagh By., Foxhall ED)		National Grid Ref: 223018 <i>E</i> 264778 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Pedestal or column base, situated at gateway of graveyard (LF023-032002).		
Ownership	Public	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Signpost for Kilglass on the main road but no sign for graveyard.
Site Signs	No sign. Cross over gateway indicates a graveyard.
Visibility	Only visible from main road if looking down access lane
Intervisibility	Intervisible with Motte and Bailey (LF023-033)
Road Access	Lane leading from local road to graveyard
Parking	No designated parking. May be possible to park at side of access lane, but not very wide.
Public Transport	
Approach Topography	Fairly level lane
Approach Surface	Compact gravel laneway with raised, grassy centre-strip
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width >1.8m
Gate type	Low double iron railed gates, easily opened. There is also a stone, stepped stile to one side of the

	gate.
<i>Site Topography</i>	Some undulating, uneven ground in graveyard, particularly where there is a circular enclosure surrounded by a low bank and ditch.
<i>Site Paths</i>	Pathway around the perimeter of the graveyard, but doesn't extend into centre of graveyard.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.1.3m
<i>Hazards</i>	Possibility of trip hazards in more overgrown sections of graveyard
<i>Maintenance</i>	Generally well maintained graveyard.
<i>Condition of Monument</i>	Not identifiable
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	023-032004	Monument	Cross
Location/ Townland	Glebe (Ardagh By., Foxhall ED)		National Grid Ref: 223018 <i>E</i> 264778 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Not identifiable within graveyard.		
Ownership	Public	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Signpost for Kilglass on the main road but no sign for graveyard.
Site Signs	No sign. Cross over gateway indicates a graveyard.
Visibility	Only visible from main road if looking down access lane
Intervisibility	Intervisible with Motte and Bailey (LF023-033)
Road Access	Lane leading from local road to graveyard
Parking	No designated parking. May be possible to park at side of access lane, but not very wide.
Public Transport	
Approach Topography	Fairly level lane
Approach Surface	Compact gravel laneway with raised, grassy centre-strip
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width >1.8m
Gate type	Low double iron railed gates, easily opened. There is also a stone, stepped stile to one side of the

	gate.
<i>Site Topography</i>	Some undulating, uneven ground in graveyard, particularly where there is a circular enclosure surrounded by a low bank and ditch.
<i>Site Paths</i>	Pathway around the perimeter of the graveyard, but doesn't extend into centre of graveyard.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.1.3m
<i>Hazards</i>	Possibility of trip hazards in more overgrown sections of graveyard
<i>Maintenance</i>	Generally well maintained graveyard.
<i>Condition of Monument</i>	Not identifiable
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	023-040	Monument	Ritual Site - Holy Well
Location/ Townland	Legan	National Grid Ref:	223560 <i>E</i> 263780 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	'Lady Well' . Shallow spring well with rectangular masonry & concrete low superstructure. Steps at one side of superstructure leads down to well. A small stream runs off from well, and this must be crossed to access well. An outdoor church with seating and altar has been set up on the side of former church LF023-039.		
Ownership	Public	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Wooden signpost for 'Legan Rock Lady Well' at junction with main road.
Site Signs	No sign, but gate is surmounted with a white cross, indicating an ecclesiastical site.
Visibility	Hidden from road
Intervisibility	
Road Access	Access pathway from minor road
Parking	No designated parking. Parking may be possible at roadside.
Public Transport	
Approach Topography	Pathway slopes down to site with steps at one point.
Approach Surface	Gravel pathway with stone steps
Approach Safety	No visible hazards. Wire fence along paths maybe could be surmounted with handrail
Approach Width	c.1.5m Approach Gate width >800m
Gate type	Single iron railed gate.

<i>Site Topography</i>	Slopes down to well. Need to cross stream to access steps down to well.
<i>Site Paths</i>	Path extends to stream.
<i>Paths Surfacing</i>	Gravel
<i>Paths Width</i>	c.1.5m
<i>Hazards</i>	No obvious hazards. Some stones stick up from well superstructure.
<i>Maintenance</i>	Well maintained and well presented.
<i>Condition of Monument</i>	Good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input checked="" type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No outdoor lighting.
<i>Notes</i>	

RMP Ref: LF-	023-048001	Monument	Ritual Site - Holy Well
Location/ Townland	Doory	National Grid Ref:	216502 E 262467 N
		RPS Ref	
		National Monument Ref	
Description	Stone-lined circular well, with low encircling wall. Located in fenced-off area in field. Water surface is completely covered with pond vegetation. Overgrown uneven area of hardcore in immediate surrounds of well. Associated with Holy Tree/Bush LF023-048002.		
Ownership	Private / Public	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Accessed via field lane
Parking	No designated parking.
Public Transport	
Approach Topography	Access lane is quite muddy - involves fording a stream and crossing a field fence.
Approach Surface	Muddy laneway, grass, some marshy areas
Approach Safety	Hazards include the necessity of crossing stream and fence, and marshy area.
Approach Width	>1.8m
Gate type	Field gate to well surrounds. This is tied with string so may not be easily opened.

<i>Site Topography</i>	Uneven ground around well
<i>Site Paths</i>	No pathways. Some attempt at hardcoring area between gate and well but this has become overgrown
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Surrounding wall of well is quite low. Well water would need to be cleaned due to plant/algal growth.
<i>Maintenance</i>	Renovated in recent years but not maintained.
<i>Condition of Monument</i>	Fair
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	023-048002	Monument	Ritual Site - Holy Tree/Bush
Location/ Townland	Doory	National Grid Ref:	216502 E 262467 N
		RPS Ref	
		National Monument Ref	
Description	Hawthorn wishing/prayer tree immediately beside Holy Well (LF023-048001) with rags tied to it.		
Ownership	Private / Public	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	Accessed via field lane
Parking	No designated parking.
Public Transport	
Approach Topography	Access lane is quite muddy - involves fording a stream and crossing a field fence.
Approach Surface	Muddy laneway, grass, some marshy areas
Approach Safety	Hazards include the necessity of crossing stream and fence, and marshy area.
Approach Width	>1.8m Approach Gate width
Gate type	Field gate to well surrounds. This is tied with string so may not be easily opened.

<i>Site Topography</i>	Uneven ground around well
<i>Site Paths</i>	No pathways. Some attempt at hardcoring area between gate and well but this has become overgrown
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Surrounding wall of well is quite low. Well water would need to be cleaned due to plant/algal growth. Overgrowth in area of tree.
<i>Maintenance</i>	Area appears to have been renovated in recent years but not maintained.
<i>Condition of Monument</i>	Fair
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	023-050	Monument	Burial Ground possible
Location/ Townland	Lislea (Moydow By.)	National Grid Ref:	214830 E 262110 N
		RPS Ref	
		National Monument Ref	
Description	Low raised area in marshy land, with some evidence of stone facing around exterior and ringed with trees. An oblong low, loose cairn of stones near one end is said to mark a famine grave (local source). Difficult to access since road layout was changed - nearest road is no longer present and access is now via private land.		
Ownership	Private	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Only visible on approach to site.
Intervisibility	
Road Access	Accessed through fields
Parking	No designated parking.
Public Transport	
Approach Topography	Slopes down gently on approach to site.
Approach Surface	Pasture, then marshy
Approach Safety	Animals grazing in field. Footing uncertain in marshy area
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Fairly steep rise up to raised area. Monument itself is fairly level with only a slight rise.
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Animals grazing in area. Surrounded by marshy ground.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Not readily identifiable as a burial ground. Only above-ground feature is cairn and its significance is not obvious.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	023-057001	Monument	Church
Location/ Townland	Taghsheenod Glebe	National Grid Ref:	218867 E 262523 N
		RPS Ref	
		National Monument Ref	
Description	Ruins of stone-built church in graveyard (LF023-057002). Heavily overgrown with ivy, while the interior is also very overgrown and uneven ground due to burrowing animals. Burials extend into the interior of the church.		
Ownership	Public	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	B/C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	No sign, but a white cross on the gate signifies an ecclesiastical site.
Visibility	Only visible from access lane
Intervisibility	
Road Access	Access via laneway from road
Parking	No designated parking
Public Transport	
Approach Topography	Fairly level
Approach Surface	Gravel and earth lane, with small area of gravel near gateway.
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width c.1.5m
Gate type	Single iron railed gate.

<i>Site Topography</i>	Ground is undulating and uneven in graveyard, due to presence of older graves and circular bank and ditch. Interior of church is very uneven.
<i>Site Paths</i>	A pathway extends around perimeter of graveyard but not to central part, where the majority of the graves are. An informal grass path/trackway leads to the church and this crosses over the bank and ditch.
<i>Paths Surfacing</i>	Concrete, grass
<i>Paths Width</i>	1 - 1.2m
<i>Hazards</i>	Some overgrowth - may mask trip hazards or uneven ground. Church ruins may be unstable.
<i>Maintenance</i>	Not maintained. Ivy should be cut back to prevent further destabilisation of walls.
<i>Condition of Monument</i>	Ruined, overgrown.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	023-057002	Monument	Graveyard
Location/ Townland	Taghsheenod Glebe	National Grid Ref:	218860 <i>E</i> 262530 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Sub-rectangular graveyard with internal circular enclosure with low bank and ditch. A raised central area lies within this inner enclosure, on which the church ruins (LF023-057001) area situated. Visible grave markers are mostly located within the circular enclosure and on the bank, and date to the 18th - 20th century.		
Ownership	Public	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	B/C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#26 Taghsheenod Graveyard, Carrickedmond & Abbeyshrule. Wheelchair access to entrance area only. No designated parking space. Public access (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	No sign, but a white cross on the gate signifies an ecclesiastical site.
Visibility	Only visible from access lane
Intervisibility	
Road Access	Access via laneway from road
Parking	No designated parking
Public Transport	
Approach Topography	Fairly level
Approach Surface	Gravel and earth lane, with small area of gravel near gateway.
Approach Safety	No visible hazards

Approach Width	>1.8m	Approach Gate width	c.1.5m
Gate type	Single iron railed gate.		
Site Topography	Ground is undulating and uneven in graveyard, due to presence of older graves and circular bank and ditch. Interior of church is very uneven.		
Site Paths	A pathway extends around perimeter of graveyard but not to central part, where the majority of the graves are. An informal grass path/trackway leads to the church and this crosses over the bank and ditch.		
Paths Surfacing	Concrete, grass		
Paths Width	1 - 1.2m		
Hazards	Some overgrowth - may mask trip hazards or uneven ground. Church ruins may be unstable.		
Maintenance	Not maintained. Ivy should be cut back to prevent further destabilisation of walls.		
Condition of Monument	Ruined, overgrown.		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	None		
Notes			

RMP Ref: LF-	023-076	Monument	Castle - Anglo-Norman Masonry Castle				
Location/ Townland	Barry (Shrule By., Ballymahon ED)		National Grid Ref:	215917	E	260798	N
			RPS Ref				
			National Monument Ref				
Description	'Barry Castle'. Located at the edge of Barry village. Extensive remains of Earthwork Motte and Bailey with some remains of stone building on the motte. The site consists of a large sub-square earthen enclosure with a square mound in its northeast corner. The enclosure has a large ditch and possible bank on the exterior. Part of the monument appears to have been damaged by the presence of ESB poles. The setting of the monument is imposing as it is raised above the surrounding ground.						
Ownership	Private	Date of Inspection	01/10/09	Inspected By	SMcG	Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Banks and ditches visible from roadside, although their significance may not be readily identifiable
Intervisibility	
Road Access	Located in field beside main road
Parking	No designated parking at site, but parking available in Barry village
Public Transport	
Approach Topography	No access from road at present - wall must be crossed. Ground rises up to monument.
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width

<i>Gate type</i>	
<i>Site Topography</i>	Very undulating and steeply uphill due to nature of monument.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Extensive earthworks - partly damaged by ESB poles.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	023-097	Monument	Church
Location/ Townland	Taghshinny	National Grid Ref:	220006 E 260314 N
		RPS Ref	
		National Monument Ref	
Description	No visible upstanding remains of earlier church.		
Ownership	Private	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Sign bearing a plan of the graveyard burials.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13402329
Internet Directions	

Field Survey:

Road Signs	None, but located in village
Site Signs	Sign relating to current church services only
Visibility	Visible from roadside
Intervisibility	
Road Access	Located beside road in village
Parking	Parking available beside graveyard
Public Transport	
Approach Topography	Fairly level approach from road and carpark
Approach Surface	Brick paving pathway from carpark
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width >1.8m
Gate type	Double aluminium gates with stepped stile at one site. Handrail provided for stile, as steps are quite

	steep.
<i>Site Topography</i>	Sloping ground at rear of graveyard, slightly uneven elsewhere.
<i>Site Paths</i>	A pathway extends around sides of present church which allows access to parts of graveyard.
<i>Paths Surfacing</i>	Tarmac
<i>Paths Width</i>	c.1.3m
<i>Hazards</i>	Low gravestones may present trip hazard.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Non-extant / not identifiable
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No outdoor lighting
<i>Notes</i>	

RMP Ref: LF-	023-097001	Monument	Graveyard				
Location/ Townland	Taghshinny		National Grid Ref:	220007	E	260307	N
			RPS Ref				
			National Monument Ref				
Description	Circular graveyard associated with church. Visible gravemarkers date primarily from the 18th - 20th centuries, although some earlier markers are also present.						
Ownership	Private	Date of Inspection	01/10/09	Inspected By	SMcG	Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Sign bearing a plan of graveyard burials.
Local Sources Directions	
Graveyard Survey	#27 Tashinny Graveyard, Carrickedmond & Abbeyshrule Wheelchair access to church only. Limited parking space available. Pathways around church. Private access (Church of Ireland) (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13402329
Internet Directions	

Field Survey:

Road Signs	None, but located in village
Site Signs	Sign relating to current church services only
Visibility	Visible from roadside
Intervisibility	
Road Access	Located beside road in village
Parking	Parking available beside graveyard
Public Transport	
Approach Topography	Fairly level approach from road and carpark
Approach Surface	Brick paving pathway from carpark
Approach Safety	No visible hazards

Approach Width	>1.8m	Approach Gate width	>1.8m
Gate type	Double aluminium gates with stepped stile at one site. Handrail provided for stile, as steps are quite steep.		
Site Topography	Sloping ground at rear of graveyard, slightly uneven elsewhere.		
Site Paths	A pathway extends around sides of present church which allows access to parts of graveyard.		
Paths Surfacing	Tarmac		
Paths Width	c.1.3m		
Hazards	Low gravestones may present trip hazard.		
Maintenance	Well maintained		
Condition of Monument	Good		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	No outdoor lighting		
Notes			

RMP Ref: LF-	023-097002	Monument	Architectural Fragment(s)
Location/ Townland	Taghshinny	National Grid Ref:	219997 E 260335 N
		RPS Ref	
		National Monument Ref	
Description	Decorative masonry fragment set in graveyard, to one side of church.		
Ownership	Private	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Sign bearing a plan of graveyard burials.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13402329
Internet Directions	

Field Survey:

Road Signs	None, but located in village
Site Signs	Sign relating to current church services only
Visibility	
Intervisibility	
Road Access	Located beside road in village
Parking	Parking available beside graveyard
Public Transport	
Approach Topography	Fairly level approach from road and carpark
Approach Surface	Brick paving pathway from carpark
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width >1.8m
Gate type	Double aluminium gates with stepped stile at one site. Handrail provided for stile, as steps are quite

	steep.
<i>Site Topography</i>	Sloping ground at rear of graveyard, slightly uneven elsewhere.
<i>Site Paths</i>	A pathway extends around sides of present church which allows access to parts of graveyard.
<i>Paths Surfacing</i>	Tarmac
<i>Paths Width</i>	c.1.3m
<i>Hazards</i>	Low gravestones may present trip hazard.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No outdoor lighting
<i>Notes</i>	

RMP Ref: LF-	023-097003	Monument	Cross-Slab
Location/ Townland	Taghshinny	National Grid Ref:	220012 <i>E</i> 260318 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Upright stone with inscribed cross, standing in graveyard to rear of church.		
Ownership	Private	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Sign bearing a plan of graveyard burials.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13402329
Internet Directions	

Field Survey:

Road Signs	None, but located in village
Site Signs	Sign relating to current church services only
Visibility	
Intervisibility	
Road Access	Located beside road in village
Parking	Parking available beside graveyard
Public Transport	
Approach Topography	Fairly level approach from road and carpark
Approach Surface	Brick paving pathway from carpark
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width >1.8m
Gate type	Double aluminium gates with stepped stile at one site. Handrail provided for stile, as steps are quite

	steep.
<i>Site Topography</i>	Sloping ground at rear of graveyard, slightly uneven elsewhere.
<i>Site Paths</i>	A pathway extends around sides of present church which allows access to parts of graveyard.
<i>Paths Surfacing</i>	Tarmac
<i>Paths Width</i>	c.1.3m
<i>Hazards</i>	Low gravestones may present trip hazard.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No outdoor lighting
<i>Notes</i>	

RMP Ref: LF-	023-097004	Monument	Cross-Slab
Location/ Townland	Taghshinny	National Grid Ref:	219995 E 260335 N
		RPS Ref	
		National Monument Ref	
Description	Uncertain as to what this refers to. Possibly low stone set in graveyard, with some visible markings.		
Ownership	Private	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Sigh bearing a plan of graveyard burials.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13402329
Internet Directions	

Field Survey:

Road Signs	None, but located in village
Site Signs	Sign relating to current church services only
Visibility	
Intervisibility	
Road Access	Located beside road in village
Parking	Parking available beside graveyard
Public Transport	
Approach Topography	Fairly level approach from road and carpark
Approach Surface	Brick paving pathway from carpark
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width >1.8m
Gate type	Double aluminium gates with stepped stile at one site. Handrail provided for stile, as steps are quite

	steep.
<i>Site Topography</i>	Sloping ground at rear of graveyard, slightly uneven elsewhere.
<i>Site Paths</i>	A pathway extends around sides of present church which allows access to parts of graveyard.
<i>Paths Surfacing</i>	Tarmac
<i>Paths Width</i>	c.1.3m
<i>Hazards</i>	Low gravestones may present trip hazard.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Not readily identifiable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No outdoor lighting
<i>Notes</i>	

RMP Ref: LF-	023-103001	Monument	Ritual Site - Holy Well
Location/ Townland	Ratharney	National Grid Ref:	223280 E 261360 N
		RPS Ref	
		National Monument Ref	
Description	Stone-lined well with steps down to water grown. However, very overgrown so not readily identifiable. Located adjacent to road. Used for domestic purposes (local source).		
Ownership	Public	Date of Inspection	15/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Not readily visible
Intervisibility	
Road Access	Located at side of road
Parking	
Public Transport	
Approach Topography	Fairly level - road
Approach Surface	Tarmac
Approach Safety	No visible hazards
Approach Width	
	Approach Gate width
Gate type	None

<i>Site Topography</i>	Uneven due to overgrowth. Steps down, accessed by small entrance
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Heavily overgrown - hazardous as can mask edges.
<i>Maintenance</i>	Not maintained - would need clearance of overgrowth.
<i>Condition of Monument</i>	Overgrown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	023-103002	Monument	Ritual Site - Holy Well
Location/ Townland	Ratharney	National Grid Ref:	223295 <i>E</i> 261349 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Well with modern concrete superstructure. Steps lead down to well.		
Ownership	Public	Date of Inspection	15/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Partially visible through hedge from side of road
Intervisibility	
Road Access	Accessed via pathway from main road
Parking	No designated parking
Public Transport	
Approach Topography	Ground generally uneven and sloping
Approach Surface	Gravel
Approach Safety	No footpath along road. Uneven ground
Approach Width	<1.8m
Approach Gate width	Stile c.0.4m, pathway c.06.-1m wide
Gate type	Stile only

<i>Site Topography</i>	Sloping to sides, and moderate uphill slope.
<i>Site Paths</i>	Path leading to well
<i>Paths Surfacing</i>	Gravel
<i>Paths Width</i>	0.6-1m
<i>Hazards</i>	Unfenced stream along side of pathway.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Clean.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	023-113	Monument	Religious House - Cistercian Monks
Location/ Townland	Abbeysrule	National Grid Ref:	222694 E 258903 N
		RPS Ref	
		National Monument Ref	
Description	Remains of medieval abbey, including substantial ruins of church.		
Ownership	Public	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Good directions to site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	Partially wheelchair accessible. No designated parking space. Old pre-Norman memorial removed for safe-keeping (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib/her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided.
Internet Directions	

Field Survey:

Road Signs	Roadsigns from town
Site Signs	Signs at site regarding restoration works; plaque on wall with some historical information, erected in 1940.
Visibility	Visible from main road
Intervisibility	
Road Access	Located beside road.
Parking	No designated parking, but parking available at roadside.
Public Transport	
Approach Topography	Level approach
Approach Surface	Gravel, concrete
Approach Safety	No visible hazards

Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	Double gate and adjacent small 'kissing gate' provide access.		
Site Topography	Slightly uneven ground throughout site.		
Site Paths	Path extends around graveyard and around abbey remains, but no path to access central area of graveyard.		
Paths Surfacing	Concrete		
Paths Width	c.1.3 - 1.5m		
Hazards	Currently undergoing restoration works so not fully accessible. Parts of ruins may be unstable.		
Maintenance	Well maintained. Undergoing restoration work.		
Condition of Monument	Ruined but appears stable.		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	No outside lighting.		
Notes			

RMP Ref: LF-	023-113002	Monument	Graveyard		
Location/ Townland	Abbeyshrule		National Grid Ref:	222782 E	258954 N
			RPS Ref		
			National Monument Ref		
Description	Graveyard associated with Cistercian Abbey. Abbey features and architectural fragments throughout the graveyards.				
Ownership	Public	Date of Inspection	01/10/09	Inspected By	SMcG
				Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#24 Abbeyshrule Graveyard, Carrickedmond & Abbeyshrule. Partially wheelchair accessible. No designated parking space. Old pre-Norman memorial removed for safe-keeping (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Roadsigns from town
Site Signs	Signs at site regarding restoration works; plaque on wall with some historical information, erected in 1940.
Visibility	Visible from main road
Intervisibility	
Road Access	Located beside road.
Parking	No designated parking, but parking available at roadside.
Public Transport	
Approach Topography	Level approach
Approach Surface	Gravel, concrete

Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width >800mm
Gate type	Double gate and adjacent small 'kissing gate' provide access.	
Site Topography	Slightly uneven ground throughout site.	
Site Paths	Path extends around graveyard and around abbey remains, but no path to access central area of graveyard.	
Paths Surfacing	Concrete	
Paths Width	c.1.3 - 1.5m	
Hazards	Currently undergoing restoration works so not fully accessible	
Maintenance	Well maintained. Undergoing restoration work.	
Condition of Monument	Good	
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>
	On-site Seating <input type="checkbox"/>	On-site Toilets <input type="checkbox"/>
On-site facilities	No outside lighting.	
Notes		

RMP Ref: LF-	023-113003	Monument	Cross-Slab possible
Location/ Townland	Abbeysrule	National Grid Ref:	222779 E 258945 N
		RPS Ref	
		National Monument Ref	
Description	Late medieval cross-slab in graveyard. Not readily discernible. Associated with Abbey (LF023-113).		
Ownership	Public	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Roadsigns from town
Site Signs	Signs at site regarding restoration works; plaque on wall with some historical information, erected in 1940.
Visibility	Not obvious
Intervisibility	
Road Access	Located beside road.
Parking	No designated parking, but parking available at roadside.
Public Transport	
Approach Topography	Level approach
Approach Surface	Gravel, concrete
Approach Safety	No visible hazards
Approach Width	>1.8m
Approach Gate width	>800mm

<i>Gate type</i>	Double gate and adjacent small 'kissing gate' provide access.
<i>Site Topography</i>	Slightly uneven ground throughout site.
<i>Site Paths</i>	Path extends around graveyard and around abbey remains, but no path to access central area of graveyard.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.1.3 - 1.5m
<i>Hazards</i>	Currently undergoing restoration works so not fully accessible
<i>Maintenance</i>	Well maintained. Undergoing restoration work.
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No outside lighting.
<i>Notes</i>	

RMP Ref: LF-	023-113004	Monument	Pillar Stone
Location/ Townland	Abbeyshrule	National Grid Ref:	222736 E 258929 N
		RPS Ref	
		National Monument Ref	
Description	Architectural fragment in graveyard (LF023-113002).		
Ownership	Public	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Roadsigns from town
Site Signs	Signs at site regarding restoration works; plaque on wall with some historical information, erected in 1940.
Visibility	Not obvious
Intervisibility	
Road Access	Located beside road.
Parking	No designated parking, but parking available at roadside.
Public Transport	
Approach Topography	Level approach
Approach Surface	Gravel, concrete
Approach Safety	No visible hazards
Approach Width	>1.8m
Approach Gate width	>800mm

<i>Gate type</i>	Double gate and adjacent small 'kissing gate' provide access.
<i>Site Topography</i>	Slightly uneven ground throughout site.
<i>Site Paths</i>	Path extends around graveyard and around abbey remains, but no path to access central area of graveyard.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.1.3 - 1.5m
<i>Hazards</i>	Currently undergoing restoration works so not fully accessible
<i>Maintenance</i>	Well maintained. Undergoing restoration work.
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No outside lighting.
<i>Notes</i>	

RMP Ref: LF-	023-113005	Monument	Stone Head		
Location/ Townland	Abbeysrule		National Grid Ref:	222780	E
				258945	N
			RPS Ref		
			National Monument Ref		
Description	Architectural fragment from Abbey with carved stone head, now situated at head of Bishop's grave in graveyard.				
Ownership	Public	Date of Inspection	01/10/09	Inspected By	SMcG
				Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Roadsigns from town	
Site Signs	Signs at site regarding restoration works; plaque on wall with some historical information, erected in 1940.	
Visibility	Not obvious	
Intervisibility		
Road Access	Located beside road.	
Parking	No designated parking, but parking available at roadside.	
Public Transport		
Approach Topography	Level approach	
Approach Surface	Gravel, concrete	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width >800mm

<i>Gate type</i>	Double gate and adjacent small 'kissing gate' provide access.
<i>Site Topography</i>	Slightly uneven ground throughout site.
<i>Site Paths</i>	Path extends around graveyard and around abbey remains, but no path to access central area of graveyard.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.1.3 - 1.5m
<i>Hazards</i>	Currently undergoing restoration works so not fully accessible
<i>Maintenance</i>	Well maintained. Undergoing restoration work.
<i>Condition of Monument</i>	Good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No outside lighting.
<i>Notes</i>	

RMP Ref: LF-	023-113006	Monument	Cross-Slab (original location)
Location/ Townland	Abbeyshrule	National Grid Ref:	222781 E 258945 N
		RPS Ref	
		National Monument Ref	
Description	No longer at site. Moved for safe-keeping.		
Ownership	Public	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	
Intervisibility	
Road Access	
Parking	
Public Transport	
Approach Topography	
Approach Surface	
Approach Safety	
Approach Width	
	Approach Gate width
Gate type	

Site Topography

Site Paths

Paths Surfacing

Paths Width

Hazards

Maintenance

Condition of Monument

Child friendly *On-site Information* *On-site Staff* *On-site Seating* *On-site Toilets*

On-site facilities

Notes

RMP Ref: LF-	023-113007	Monument	Graveslab		
Location/ Townland	Abbeysrule		National Grid Ref:	222780	E
				258945	N
			RPS Ref		
			National Monument Ref		
Description	Uncertain as to which graveslab this refers. There are a number present in the graveyard, including a 17th century slab with the Fitzgerald and O'Farrell family crests.				
Ownership	Public	Date of Inspection	01/10/09	Inspected By	SMcG
				Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Roadsigns from town to Abbey and graveyard.	
Site Signs	Signs at site regarding restoration works; plaque on wall with some historical information, erected in 1940.	
Visibility	Not obvious	
Intervisibility		
Road Access	Located beside road.	
Parking	No designated parking, but parking available at roadside.	
Public Transport		
Approach Topography	Level approach	
Approach Surface	Gravel, concrete	
Approach Safety	No visible hazards	
Approach Width	>1.8m	Approach Gate width >800mm

<i>Gate type</i>	Double gate and adjacent small 'kissing gate' provide access.
<i>Site Topography</i>	Slightly uneven ground throughout site.
<i>Site Paths</i>	Path extends around graveyard and around abbey remains, but no path to access central area of graveyard.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.1.3 - 1.5m
<i>Hazards</i>	Currently undergoing restoration works so not fully accessible
<i>Maintenance</i>	Well maintained. Undergoing restoration work.
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	No outside lighting.
<i>Notes</i>	

RMP Ref: LF-	023-113008	Monument	Bridge (17th century)
Location/ Townland	Abbeyshrule	National Grid Ref:	222751 E 259173 N
		RPS Ref	
		National Monument Ref	
Description	Double-arched masonry bridge with cutwaters, crossing the River Inny. There are two smaller arches on the northwestern side for a millrace which is now filled in. A ramp is present towards the river along one side; now used as a field access.		
Ownership	Public	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	B/C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13402347
Internet Directions	

Field Survey:

Road Signs	Signposted in Abbeyshrule town and on route from town
Site Signs	
Visibility	Located on road
Intervisibility	Intervisible with Abbeyshrule Abbey (LF023-113)
Road Access	Road crosses bridge.
Parking	Parking in village.
Public Transport	
Approach Topography	
Approach Surface	Road
Approach Safety	No footpath over bridge, but can be viewed from grounds of the new R.C. church in Abbeyshrule
Approach Width	
	Approach Gate width
Gate type	

<i>Site Topography</i>	Bridge is arched,
<i>Site Paths</i>	No footpath across bridge
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Lack of footpath.
<i>Maintenance</i>	
<i>Condition of Monument</i>	Good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None. No lighting on bridge.
<i>Notes</i>	

RMP Ref: LF-	023-113009	Monument	Fish-Pond possible
Location/ Townland	Abbeyshrule	National Grid Ref:	222699 E 259026 N
		RPS Ref	
		National Monument Ref	
Description	Visible as a number of earthworks between the Abbey and the river. Associated with the Cistercian foundation (LF023-113).		
Ownership	Public	Date of Inspection	01/10/09
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Roadsigns from town to Abbey and graveyard.
Site Signs	Signs at site regarding restoration works; plaque on wall with some historical information, erected in 1940.
Visibility	May not be readily identifiable
Intervisibility	
Road Access	Located beside road.
Parking	No designated parking, but parking available at roadside.
Public Transport	
Approach Topography	Level approach
Approach Surface	Gravel, concrete
Approach Safety	No visible hazards
Approach Width	>1.8m
Approach Gate width	>800mm

<i>Gate type</i>	Double gate and adjacent small 'kissing gate' provide access.
<i>Site Topography</i>	Slightly uneven ground throughout site.
<i>Site Paths</i>	Path extends around graveyard and around abbey remains, but no path to access central area of graveyard.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.1.3 - 1.5m
<i>Hazards</i>	Restoration works at Abbey.
<i>Maintenance</i>	
<i>Condition of Monument</i>	
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	
<i>Notes</i>	

RMP Ref: LF-	023-123002	Monument	Castle - Unclassified
Location/ Townland	Tennalick		National Grid Ref: 221580 <i>E</i> 258794 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Remains of castle, later converted to mill (LF023-123003). Partial ruins of main building survive, and have been stabilised - at least in part - by iron and concrete supports. Located at one end of yard belonging to White's Trailers and used as storage by the company. Heavily covered with ivy. Uncertain as to how much of upstanding remains are original.		
Ownership	Private	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from road
Intervisibility	
Road Access	Located beside main road
Parking	No designated parking. Parking is possible at roadside.
Public Transport	
Approach Topography	Level approach.
Approach Surface	Tarmac, concrete, gravel
Approach Safety	No footpath on road. No pedestrian crossing on road. Approach is through working trailer yard.
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Wide metal gate, locked outside of business hours.

<i>Site Topography</i>	No access to interior. Yard is level but footing may be uncertain.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Accessed through working trailer business only. Building partly stabilised but uncertain as to what degree the structure is stable.
<i>Maintenance</i>	Not fully maintained
<i>Condition of Monument</i>	Ruined, possibly unstable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	023-123003	Monument	Water Mill - Unclassified		
Location/ Townland	Tennalick		National Grid Ref:	<input type="text"/> E	<input type="text"/> N
			RPS Ref	<input type="text"/>	
			National Monument Ref	<input type="text"/>	
Description	Ruined mill building - converted from castle (LF023-123002). Partial ruins of main building survive, and have been stabilised - at least in part - by iron and concrete supports. Located at one end of yard belonging to White's Trailers and used as storage by the company. Heavily covered with ivy. Uncertain as to how much of upstanding remains are original. Not considered an RMP on www.archaeology.ie website.				
Ownership	Private	Date of Inspection	20/10/09	Inspected By	SMcG
				Accessibility Rating	C/D

Desk-Based Survey

Local Sources Information	<input type="text"/>
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	<input type="text"/>
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	<input type="text"/>
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	<input type="text"/>
Visibility	Visible from road
Intervisibility	<input type="text"/>
Road Access	Located beside main road
Parking	No designated parking. Parking may be possible at roadside.
Public Transport	<input type="text"/>
Approach Topography	Level approach.
Approach Surface	Tarmac, concrete, gravel
Approach Safety	No footpath on road. No pedestrian crossing on road. Approach is through working trailer yard.
Approach Width	>1.8m
Approach Gate width	>800mm

<i>Gate type</i>	Wide metal gate, locked outside of business hours.
<i>Site Topography</i>	No access to interior. Yard is level but footing may be uncertain.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Accessed through working trailer business only. Building partly stabilised but uncertain as to what degree the structure is stable.
<i>Maintenance</i>	Not fully maintained
<i>Condition of Monument</i>	Ruined, possibly unstable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	024-003001	Monument	Church
Location/ Townland	Foxhall Glebe	National Grid Ref:	225445 E 264377 N
		RPS Ref	
		National Monument Ref	
Description			
Ownership	Public	Date of Inspection	15/09/09
		Inspected By	SMcG
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	Wheelchair accessible. No designated parking spaces. Gravel path to church and part of graveyard. Public access (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from the demesne road.
Intervisibility	Intervisible with Demesne House (LF024-004)
Road Access	Located at side of road.
Parking	No designated parking. Parking may be possible at side of road.
Public Transport	
Approach Topography	Level pathway from road to site.
Approach Surface	Concrete
Approach Safety	No visible hazards
Approach Width	>1.8m
Approach Gate width	c.1.1m

<i>Gate type</i>	Single metal railing gate with stepped stile (with handrail) to one side.
<i>Site Topography</i>	Fairly level
<i>Site Paths</i>	Pathway extends through half of graveyard.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.0.9m
<i>Hazards</i>	Church floor is very uneven. Walls appear solid.
<i>Maintenance</i>	Generally well maintained. Overgrowth on church may need to be cut back.
<i>Condition of Monument</i>	Ruined but stable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	024-003002	Monument	Sarcophagus
Location/ Townland	Foxhall Glebe	National Grid Ref:	225448 <i>E</i> 264377 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Located within church (LF024-003002). Stone sarcophagus with effigy, dated 1634. Effigy is broken, otherwise in good condition.		
Ownership	Public	Date of Inspection	15/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Only visible from within church
Intervisibility	
Road Access	Graveyard is located at side of road.
Parking	No designated parking. Parking may be possible at side of road.
Public Transport	
Approach Topography	Pathway church is fairly level
Approach Surface	Concrete
Approach Safety	No visible hazards
Approach Width	c.0.9m
Approach Gate width	
Gate type	Railed metal gate at entrance to graveyard. Arched stone doorway, with iron railed door/gate at

	entrance to church.
<i>Site Topography</i>	Very uneven floor within church.
<i>Site Paths</i>	Stone flag floor in interior of church
<i>Paths Surfacing</i>	Stone flags.
<i>Paths Width</i>	
<i>Hazards</i>	Uneven stone paving is a trip hazard.
<i>Maintenance</i>	Overall well maintained.
<i>Condition of Monument</i>	Effigy broken, otherwise in good condition.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	024-003003	Monument	Graveyard
Location/ Townland	Foxhall Glebe	National Grid Ref:	225448 E 264398 N
		RPS Ref	
		National Monument Ref	
Description	Graveyard associated with Church (LF024-003001)		
Ownership	Public	Date of Inspection	15/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	#78 Foxhall Graveyard, Legan. Still in use; wheelchair access; public ownership (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from the demesne road.
Intervisibility	Intervisible with Demesne House (LF024-004)
Road Access	Located at side of road.
Parking	No designated parking. Parking may be possible at side of road.
Public Transport	
Approach Topography	Level pathway from road to site.
Approach Surface	Concrete
Approach Safety	No visible hazards
Approach Width	>1.8m
Approach Gate width	c.1.1m

<i>Gate type</i>	Single metal railing gate with stepped stile (with handrail) to one side.
<i>Site Topography</i>	Fairly level
<i>Site Paths</i>	Pathway extends through half of graveyard.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.0.9m
<i>Hazards</i>	Church floor is very uneven. Walls appear solid.
<i>Maintenance</i>	Generally well maintained. Overgrowth on church may need to be cut back.
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	024-007001	Monument	Church
Location/ Townland	Agharra	National Grid Ref:	225231 <i>E</i> 260730 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Ruins of small stone built church with two rooms, located within small graveyard. Heavily covered in ivy.		
Ownership	Public	Date of Inspection	15/09/09
		Inspected By	SMcG
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from road.
Intervisibility	
Road Access	Beside road
Parking	No designated parking. Parking may be possible at roadside.
Public Transport	
Approach Topography	Moderate slope from road to graveyard entrance - no handrail present.
Approach Surface	Gravel path. However, there is a pothole where the pathway meets the road.
Approach Safety	No footpath along road - grass verge only.
Approach Width	>1.8m Approach Gate width >800mm
Gate type	Single metal railed gate at graveyard entrance, heavy to open. A stile crosses the stone wall to one

	side of the gate. Second railed gate at church entrance - narrow, low doorway in church.
<i>Site Topography</i>	Fairly level within graveyard. Slight slope down to church.
<i>Site Paths</i>	Path extends through centre of graveyard towards church ruins.
<i>Paths Surfacing</i>	Gravel/hardcore
<i>Paths Width</i>	c.1m
<i>Hazards</i>	Path peters out before church with end of path blocked by a low grave marker.
<i>Maintenance</i>	Graveyard well maintained
<i>Condition of Monument</i>	Heavily overgrown with ivy.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Some seating outside graveyard, opposite entrance.
<i>Notes</i>	

RMP Ref: LF-	024-007002	Monument	Graveyard		
Location/ Townland	Agharra		National Grid Ref:	225212 <i>E</i>	260731 <i>N</i>
			RPS Ref		
			National Monument Ref		
Description	Small graveyard associated with church LF024-007001. Graveyard is still in use.				
Ownership	Public	Date of Inspection	15/09/09	Inspected By	SMcG
				Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#77 Agharra Graveyard, Legan. Limited wheelchair access. Gravel pathway to church ruins. Reference to site in books, Field Notes, held in the Local Studies Section of Longford Library. Reference to memorial to Giolla na Naomh O'Farrell in Field Notes held in Longford Library - this memorial was not visible at the time of the Graveyard Survey (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from road.
Intervisibility	
Road Access	Beside road
Parking	No designated parking. Parking may be possible at roadside.
Public Transport	
Approach Topography	Moderate slope from road to graveyard entrance - no handrail present.
Approach Surface	Gravel path. However, there is a pothole where the pathway meets the road.

Approach Safety	No footpath along road - grass verge only.	
Approach Width	>1.8m	Approach Gate width >800mm
Gate type	Single metal railed gate at graveyard entrance, heavy to open. A stile crosses the stone wall to one side of the gate.	
Site Topography	Fairly level within graveyard. Slight slope down to church.	
Site Paths	Path extends through centre of graveyard towards church ruins.	
Paths Surfacing	Gravel/hardcore	
Paths Width	c.1m	
Hazards	Path peters out before church with end of path blocked by a low grave marker.	
Maintenance	Graveyard well maintained	
Condition of Monument	Heavily overgrown with ivy.	
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>
	On-site Seating <input type="checkbox"/>	On-site Toilets <input type="checkbox"/>
On-site facilities	Some seating outside graveyard, opposite entrance.	
Notes		

RMP Ref: LF-	024-009	Monument	Bridge (17th century)
Location/ Townland	Agharra	National Grid Ref:	225875 E 260289 N
		RPS Ref	
		National Monument Ref	
Description	Ballynacarrow Bridge. Bridge crossing the river Inny, with four arches on the Longford side. Two of the arches are now blocked.		
Ownership	Public	Date of Inspection	15/09/09
		Inspected By	SMcG
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13402406
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Sign for 'Ballycarrow Bridge River Inny' on the side of the bridge, but this is not obvious.
Visibility	Visible as crossed by main road
Intervisibility	Intervisible with Mill (LF024-0010)
Road Access	Road crosses bridge
Parking	
Public Transport	
Approach Topography	Fairly level
Approach Surface	Tarmac
Approach Safety	No footpath - access by car only
Approach Width	>1.8m
	Approach Gate width
Gate type	

<i>Site Topography</i>	Top of bridge level. Ground drops off to either side in fields.
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Ground in fields is uneven and overgrown - unsuitable for visual access to bridge
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	024-010	Monument	Water Mill - Unclassified.
Location/ Townland	Agharra	National Grid Ref:	225822 E 260331 N
		RPS Ref	
		National Monument Ref	
Description	Rectangular foundation to the southwest of bridge LF024-009, which may be the former mill. Not readily identifiable.		
Ownership	Private	Date of Inspection	15/09/09
		Inspected By	S
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Foundations of structure visible but not readily identifiable
Intervisibility	Intervisible with Bridge (LF024-009)
Road Access	Accessed through field from road.
Parking	
Public Transport	
Approach Topography	Fairly level on road, ground slopes down in field.
Approach Surface	Tarmac, grass
Approach Safety	No footpath on road.
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate

<i>Site Topography</i>	Slopes downwards at exterior of possible mill building.
<i>Site Paths</i>	None - site surrounded by rough pasture
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Old farm machinery in vicinity of structure, along with fencing and loose stones. Overgrowth may hide trip hazards
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Foundation level only - significance not obvious
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	025-001001	Monument	Ritual Site - Holy Well
Location/ Townland	Derrydarragh	National Grid Ref:	202839 E 257466 N
		RPS Ref	
		National Monument Ref	
Description	Stone-lined well, with concrete. Steps lead down to water level. A channel carries excess water away to Lough Ree. Associated with Holy Tree (LF025-001003).		
Ownership	Public	Date of Inspection	29/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from approach road, not from main road.
Intervisibility	Intervisible with Holy Tree LF025-001003.
Road Access	Located beside road leading to slipway on Lough Ree
Parking	No designated parking. Parking may be possible on laneway.
Public Transport	
Approach Topography	Fairly level but uneven ground.
Approach Surface	Gravel path, now grassed-over and with some larger stones.
Approach Safety	Lake is nearby with no barriers at lakeside. No other visible hazards.
Approach Width	>1.8m
	Approach Gate width
Gate type	None

<i>Site Topography</i>	Level - may be uneven due to stones and roots.
<i>Site Paths</i>	No paths.
<i>Paths Surfacing</i>	General grass covering.
<i>Paths Width</i>	
<i>Hazards</i>	No visible hazards.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None. No outdoor lighting.
<i>Notes</i>	

RMP Ref: LF-	025-001002	Monument	Penal Mass Station possible
Location/ Townland	Derrydarragh	National Grid Ref:	202859 <i>E</i> 257444 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	Large rectangular stone block, located at a slight angle along the side of a driveway to a private house. Not considered an RMP on the www.archaeology.ie website		
Ownership	Private	Date of Inspection	29/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from driveway only, not from main road.
Intervisibility	
Road Access	Accessed via private driveway to house
Parking	No designated parking
Public Transport	
Approach Topography	Fairly level but uneven ground.
Approach Surface	Gravel
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width
Gate type	Stile over wall only. No gate.

<i>Site Topography</i>	Fairly level
<i>Site Paths</i>	No paths
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	Well maintained.
<i>Condition of Monument</i>	Good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	025-001003	Monument	Ritual Site - Holy Tree/Bush
Location/ Townland	Derrydarragh	National Grid Ref:	202839 E 257466 N
		RPS Ref	
		National Monument Ref	
Description	Two wishing/prayer trees (beech and hawthorn) located beside holy well (LF025-001001), with statues, rags and rosary beads tied to them.		
Ownership	Public	Date of Inspection	29/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from approach road, not from main road.
Intervisibility	Intervisible with Holy Tree LF025-001003.
Road Access	Located beside road leading to slipway on Lough Ree
Parking	No designated parking. Parking may be possible on laneway.
Public Transport	
Approach Topography	Fairly level but uneven ground.
Approach Surface	Gravel path, now grassed-over and with some larger stones.
Approach Safety	Lake is nearby with no barriers at lakeside. No other visible hazards.
Approach Width	>1.8m
	Approach Gate width
Gate type	None

<i>Site Topography</i>	Level - may be uneven due to stones and roots.
<i>Site Paths</i>	No paths.
<i>Paths Surfacing</i>	General grass covering.
<i>Paths Width</i>	
<i>Hazards</i>	No visible hazards.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None. No outdoor lighting.
<i>Notes</i>	

RMP Ref: LF-	025-005001	Monument	Enclosure
Location/ Townland	Portanure	National Grid Ref:	204204 E 256509 N
		RPS Ref	
		National Monument Ref	
Description	Large, sub-circular enclosure with earth and stone banks. Banks are up to 1.2m in height, and there is a slight rise in the interior.		
Ownership	Private	Date of Inspection	29/09/09
		Inspected By	SMcG
		Accessibility Rating	B/C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from road
Intervisibility	Intervisible with castle ruins (LF025-006), located on opposite side of road.
Road Access	Access through field from minor road.
Parking	No designated parking.
Public Transport	
Approach Topography	Fairly level.
Approach Surface	Grass
Approach Safety	No pedestrian crossing on road.
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate, but this is rusted and broken. However had been left open at time of survey.

<i>Site Topography</i>	Undulating due to nature of monument
<i>Site Paths</i>	No paths. Some tracks worn across banks.
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Good, but some damage due to trackways, probably caused by animals.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	025-005002	Monument	Burial Ground
Location/ Townland	Portanure	National Grid Ref:	204208 E 256499 N
		RPS Ref	
		National Monument Ref	
Description	No visible features relating to burial ground. Probably located within enclosure (LF025-005001).		
Ownership	Private	Date of Inspection	29/09/09
		Inspected By	SMcG
		Accessibility Rating	B/C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Enclosure is visible from road. Burial ground itself is not identifiable.
Intervisibility	Intervisible with castle ruins (LF025-006), located on opposite side of road.
Road Access	Access through field from minor road.
Parking	No designated parking.
Public Transport	
Approach Topography	Fairly level.
Approach Surface	Grass
Approach Safety	No pedestrian crossing on road.
Approach Width	
	Approach Gate width >800mm
Gate type	Field gate, but this is rusted and broken. However had been left open at time of survey.

<i>Site Topography</i>	Undulating due to nature of monument
<i>Site Paths</i>	No paths. Some tracks worn across banks.
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	No features visible. Not readily identifiable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	026-016001	Monument	Ecclesiastical Enclosure
Location/ Townland	Saints Island	National Grid Ref:	207077 E 256076 N
		RPS Ref	
		National Monument Ref	
Description	Large circular enclosure, enclosing monastery (LF026-016002), delimited by a stone wall. An earlier, higher wall survives in two sections.		
Ownership	Public	Date of Inspection	25/09/09
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided. Included in list of place of interest under 'Heritage and Places' in Co. Longford at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Signposts on main road for Saints Island
Site Signs	Plaque on wall at monastery with some historical information.
Visibility	Visible from road.
Intervisibility	Intervisible with other individual RMPs relating to monastery
Road Access	Island is accessed via small road crossing causeway. Road leads around island. Site is accessed via
Parking	No designated parking. Parking possible along roadside.
Public Transport	
Approach Topography	Some gentle slopes
Approach Surface	Tarmac, Gravel
Approach Safety	No visible hazards
Approach Width	>1.8m
Approach Gate width	>800mm

<i>Gate type</i>	Metal railed gate, with stone stepped stile to one side of the gate.
<i>Site Topography</i>	Slope on one side. No handrail present.
<i>Site Paths</i>	Path extends around perimeter of graveyard. Path does not extend to monastic structures.
<i>Paths Surfacing</i>	Gravel
<i>Paths Width</i>	c.1.3m
<i>Hazards</i>	Care should be taken around structural remains. The main buildings appear stable, but some sections of walls appear unstable.
<i>Maintenance</i>	Well maintained.
<i>Condition of Monument</i>	Good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input checked="" type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	One bench within precinct of monastery for seating.
<i>Notes</i>	

RMP Ref: LF-	026-016002	Monument	Religious House - Augustinian Canons				
Location/ Townland	Saints Island		National Grid Ref:	207060	E	256071	N
			RPS Ref				
			National Monument Ref				
Description	Upstanding ruined remains of medieval monastic settlement. Church remains are substantial, while remains of other buildings are more ruinous and their functions are not readily identifiable.						
Ownership	Public	Date of Inspection	25/09/09	Inspected By	SMcG	Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided. Included in list of place of interest under 'Heritage and Places' in Co. Longford at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Signposts on main road for Saints Island
Site Signs	Plaque on wall at monastery with some historical information.
Visibility	Visible from road.
Intervisibility	Intervisible with other individual RMPs relating to monastery
Road Access	Island is accessed via small road crossing causeway. Road leads around island. Site is accessed via
Parking	No designated parking. Parking possible along roadside.
Public Transport	
Approach Topography	Some gentle slopes
Approach Surface	Tarmac, Gravel
Approach Safety	No visible hazards
Approach Width	>1.8m
Approach Gate width	>800mm

<i>Gate type</i>	Metal railed gate, with stone stepped stile to one side of the gate.
<i>Site Topography</i>	Some sloping and uneven ground in vicinity of structural remains.
<i>Site Paths</i>	Path extends around perimeter of graveyard. Path does not extend to monastic structures.
<i>Paths Surfacing</i>	Gravel
<i>Paths Width</i>	c.1.3m
<i>Hazards</i>	Care should be taken around structural remains. The main buildings appear stable, but some sections of walls appear unstable.
<i>Maintenance</i>	Well maintained.
<i>Condition of Monument</i>	Good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input checked="" type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	One bench within precinct of monastery for seating.
<i>Notes</i>	

RMP Ref: LF-	026-016003	Monument	Graveyard
Location/ Townland	Saints Island	National Grid Ref:	207076 E 256071 N
		RPS Ref	
		National Monument Ref	
Description	Graveyard associated with monastery (LF026-016002) and Ecclesiastical Enclosure (LF-026-016001). Visible gravemarkers are located to the east of the church remains.		
Ownership	Public	Date of Inspection	25/09/09
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	#29 Saint's Island Graveyard, Cashel. Wheelchair access to graveyard. No designated parking. Public access (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib/her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided. Included in list of place of interest under 'Heritage and Places' in Co. Longford at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Signposts on main road for Saints Island
Site Signs	Plaque on wall at monastery with some historical information.
Visibility	Visible from road.
Intervisibility	Intervisible with other individual RMPs relating to monastery
Road Access	Island is accessed via small road crossing causeway. Road leads around island. Site is accessed via
Parking	No designated parking. Parking possible along roadside.
Public Transport	
Approach Topography	Some gentle slopes
Approach Surface	Tarmac, Gravel
Approach Safety	No visible hazards

Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	No visible hazards		
Site Topography	Some sloping ground in graveyard and from pathway towards centre of graveyard.		
Site Paths	Path extends around perimeter of graveyard. Path does not extend to monastic structures.		
Paths Surfacing	Gravel		
Paths Width	c.1.3m		
Hazards	Care should be taken around structural remains. The main buildings appear stable, but some sections of walls appear unstable.		
Maintenance	Well maintained.		
Condition of Monument	Good.		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input checked="" type="checkbox"/>
On-site facilities	One bench within precinct of monastery for seating.		
Notes			

RMP Ref: LF-	026-016004	Monument	Building
Location/ Townland	Saints Island	National Grid Ref:	207100 E 256084 N
		RPS Ref	
		National Monument Ref	
Description	Uncertain as to which of a number of remains of buildings this refers. Associated with Monastery (LF026-016002).		
Ownership	Public	Date of Inspection	25/09/09
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided. Included in list of place of interest under 'Heritage and Places' in Co. Longford at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Signposts on main road for Saints Island
Site Signs	Plaque on wall at monastery with some historical information.
Visibility	Visible from road.
Intervisibility	Intervisible with other individual RMPs relating to monastery
Road Access	Island is accessed via small road crossing causeway. Road leads around island. Site is accessed via
Parking	No designated parking. Parking possible along roadside.
Public Transport	
Approach Topography	Some gentle slopes
Approach Surface	Tarmac, Gravel
Approach Safety	No visible hazards
Approach Width	>1.8m
Approach Gate width	>800mm

<i>Gate type</i>	No visible hazards
<i>Site Topography</i>	Some sloping ground in graveyard and from pathway towards centre of graveyard.
<i>Site Paths</i>	Path extends around perimeter of graveyard. Path does not extend to monastic structures.
<i>Paths Surfacing</i>	Gravel
<i>Paths Width</i>	c.1.3m
<i>Hazards</i>	Care should be taken around structural remains. The main buildings appear stable, but some sections of walls appear unstable.
<i>Maintenance</i>	Well maintained.
<i>Condition of Monument</i>	Good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input checked="" type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	One bench within precinct of monastery for seating.
<i>Notes</i>	

RMP Ref: LF-	026-016005	Monument	Graveslab
Location/ Townland	Saints Island	National Grid Ref:	207059 E 256071 N
		RPS Ref	
		National Monument Ref	
Description	One of two graveslabs located against the wall of the monastery, below the information plaque. Possibly of 17th century date. Inscription difficult to read.		
Ownership	Public	Date of Inspection	25/09/09
		Inspected By	SMcG
		Accessibility Rating	A/B

Desk-Based Survey

Local Sources Information	Information about the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Local Sources Directions	Directions to the site included in Moore, S. (2007) Archaeological Monuments in County Longford.
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided. Included in list of place of interest under 'Heritage and Places' in Co. Longford at http://www.longfordtourism.ie
Internet Directions	

Field Survey:

Road Signs	Signposts on main road for Saints Island
Site Signs	Plaque on wall at monastery with some historical information.
Visibility	Visible within graveyard.
Intervisibility	Intervisible with other individual RMPs relating to monastery
Road Access	Island is accessed via small road crossing causeway. Road leads around island. Site is accessed via
Parking	No designated parking. Parking possible along roadside.
Public Transport	
Approach Topography	Some gentle slopes
Approach Surface	Tarmac, Gravel
Approach Safety	No visible hazards
Approach Width	>1.8m
Approach Gate width	>800mm

<i>Gate type</i>	No visible hazards
<i>Site Topography</i>	Some sloping ground in graveyard and from pathway towards centre of graveyard.
<i>Site Paths</i>	Path extends around perimeter of graveyard. Path does not extend to monastic structures.
<i>Paths Surfacing</i>	Gravel
<i>Paths Width</i>	c.1.3m
<i>Hazards</i>	Care should be taken around structural remains. The main buildings appear stable, but some sections of walls appear unstable.
<i>Maintenance</i>	Well maintained.
<i>Condition of Monument</i>	Good, but inscription weathered.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input checked="" type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	One bench within precinct of monastery for seating.
<i>Notes</i>	

RMP Ref: LF-	026-019001	Monument	Church possible
Location/ Townland	Glebe (Rathcline By.) (Detached portion)		National Grid Ref: 213470 E 256100 N
		RPS Ref	
		National Monument Ref	
Description	No upstanding structure visible. A raised sub-rectangular area at the highest point in the graveyard (LF026-019002) may represent foundational remains of the church. A small octagonal stone font is also present, on one of the burial plots.		
Ownership	Public	Date of Inspection	25/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	Graveyard is referred to on plaque at Shrule Bridge.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Sign for "'Leo" Parents Grave' on road (reference to local poet).
Site Signs	
Visibility	Visible from main road
Intervisibility	
Road Access	Accessed via laneway from main road
Parking	Parking is available at the new graveyard, fronting onto the main road.
Public Transport	
Approach Topography	Fairly level laneway from main road.
Approach Surface	Gravel laneway with grassed over central line.
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width >800mm
Gate type	Modern metal gate and adjacent 'kissing gate' along lane; older single metal gate with stepped stile to

	one side to access graveyard. No handrail on steps but warning sign for 'Slippery Steps'.
<i>Site Topography</i>	Generally uneven ground, particularly in area of possible church remains.
<i>Site Paths</i>	Pathway extends around edges of graveyard.
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.1.5m
<i>Hazards</i>	Uneven ground.
<i>Maintenance</i>	Well maintained.
<i>Condition of Monument</i>	Not readily identifiable.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input checked="" type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Two benches at gravesides. No outdoor lighting present.
<i>Notes</i>	

RMP Ref: LF-	026-019002	Monument	Graveyard				
Location/ Townland	Glebe (Rathcline By.) (Detached portion)		National Grid Ref:	213470	E	256100	N
			RPS Ref				
			National Monument Ref				
Description	Circular graveyard with raised area in centre. One side of the graveyard has been straightened slightly with evidence of the original enclosure continuing outside the wall. Visible gravestones date to the 18th to 21st centuries (graveyard still in use).						
Ownership	Public	Date of Inspection	25/09/09	Inspected By	SMcG	Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Graveyard is referred to on plaque at Shrule Bridge.
Local Sources Directions	
Graveyard Survey	#93 Shrule (Old) Graveyard, Shrule. Limited wheelchair access. Gravel path from entrance and along wall. Parking spaces at new graveyard. Public access (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	Sign for "'Leo" Parents Grave' on road (reference to local poet).
Site Signs	
Visibility	Visible from main road
Intervisibility	
Road Access	Accessed via laneway from main road
Parking	Parking is available at the new graveyard, fronting onto the main road.
Public Transport	
Approach Topography	Fairly level laneway from main road.
Approach Surface	Gravel laneway with grassed over central line.
Approach Safety	No visible hazards

Approach Width	>1.8m	Approach Gate width	>800mm
Gate type	Modern metal gate and adjacent 'kissing gate' along lane; older single metal gate with stepped stile to one side to access graveyard. No handrail on steps but warning sign for 'Slippery Steps'.		
Site Topography	Generally uneven ground, particularly in area of possible church remains.		
Site Paths	Pathway extends around edges of graveyard.		
Paths Surfacing	Concrete		
Paths Width	c.1.5m		
Hazards	Uneven ground.		
Maintenance	Well maintained.		
Condition of Monument	Not readily identifiable.		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input checked="" type="checkbox"/>
On-site facilities	Two benches at gravesides. No outdoor lighting present.		
Notes			

RMP Ref: LF-	026-030001	Monument	Bridge
Location/ Townland	Shrulle	National Grid Ref:	<input type="text"/> E <input type="text"/> N
		RPS Ref	<input type="text"/>
		National Monument Ref	<input type="text"/>
Description	Shrulle Bridge. Original 17th century bridge is no longer extant. Replaced by modern bridge crossing the river Inny. Present bridge has plaques dedicated to local 19th century poet John Keegan Casey, aka 'Leo'. Bridge is not considered an RMP on the official www.archaeology.ie website.		
Ownership	Public	Date of Inspection	25/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	<input type="text"/>
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	<input type="text"/>
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	<input type="text"/>
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	Plaques commemorating local poet and writer John Keegan Casey.
Visibility	Modern bridge only present
Intervisibility	<input type="text"/>
Road Access	<input type="text"/>
Parking	<input type="text"/>
Public Transport	<input type="text"/>
Approach Topography	<input type="text"/>
Approach Surface	<input type="text"/>
Approach Safety	<input type="text"/>
Approach Width	<input type="text"/>
	Approach Gate width <input type="text"/>
Gate type	<input type="text"/>

Site Topography

Site Paths

Paths Surfacing

Paths Width

Hazards

Maintenance

Condition of Monument

Child friendly *On-site Information* *On-site Staff* *On-site Seating* *On-site Toilets*

On-site facilities

Notes

RMP Ref: LF-	027-003001	Monument	Church possible
Location/ Townland	Ballymahon	National Grid Ref:	215784 E 256970 N
		RPS Ref	
		National Monument Ref	
Description	No visible remains. 19th century church may have been constructed on site of earlier church. Access to church grounds by appointment only.		
Ownership	Private	Date of Inspection	29/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	Located within the grounds of St. Catherine's Church of Ireland.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13316019
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Only relating to modern church.
Visibility	No visible remains. Modern church visible from Main Street.
Intervisibility	
Road Access	Access from Main Street in Ballymahon
Parking	Street parking available in town
Public Transport	Public transport to town centre.
Approach Topography	Level approach
Approach Surface	pavement.
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width >800m
Gate type	Double gate.

<i>Site Topography</i>	Slight slope on one side of graveyard.
<i>Site Paths</i>	Pathway to church from gate, but step up to path at gateway. Path extends around church.
<i>Paths Surfacing</i>	Concrete, gravel
<i>Paths Width</i>	>1.8m
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	Well maintained.
<i>Condition of Monument</i>	Non-extant
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	027-003002	Monument	Graveyard		
Location/ Townland	Ballymahon		National Grid Ref:	215794 <i>E</i>	256974 <i>N</i>
			RPS Ref		
			National Monument Ref		
Description	Graveyard associated with church (LF027-003001). Curved boundary on two sides, while the remaining two sides are bounded by roads.				
Ownership	Private	Date of Inspection	29/09/09	Inspected By	SMcG
				Accessibility Rating	D

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#90 Ballymahon (C of I) Graveyard, Shrule. Not wheelchair accessible; No designated parking space; Gravel pathways to church; Private access (Church of Ireland); Information panels present (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13316019
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Only relating to modern church.
Visibility	Visible from main street
Intervisibility	
Road Access	Access from Main Street in Ballymahon
Parking	Street parking available in town
Public Transport	Public transport to town centre.
Approach Topography	Level approach
Approach Surface	pavement.
Approach Safety	No visible hazards

Approach Width	>1.8m	Approach Gate width	>800m
Gate type	Double gate.		
Site Topography	Slight slope on one side of graveyard.		
Site Paths	Pathway to church from gate, but step up to path at gateway. Path extends around church.		
Paths Surfacing	Concrete, gravel		
Paths Width	>1.8m		
Hazards	No visible hazards		
Maintenance	Well maintained.		
Condition of Monument	Good		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>	On-site Seating <input type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	None.		
Notes			

RMP Ref: LF-	027-003003	Monument	Bridge (17th century)
Location/ Townland	Ballymahon	National Grid Ref:	215818 E 256882 N
		RPS Ref	
		National Monument Ref	
Description	Treble-arched bridge over the river Inny, located at the southeastern end of Ballymahon, with cutwaters on both sides. Heavily modified in modern times, with older stone arches visible at underside of arches.		
Ownership	Public	Date of Inspection	25/09/09
		Inspected By	SMcG
		Accessibility Rating	

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13316030
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible from Main Street in town
Intervisibility	Intervisible with Graveyard (LF027-003002), Historic town (LF027-003006) and Mill (LF027-003005)
Road Access	Main road crosses over bridge.
Parking	Street parking available in town
Public Transport	Public transport to town centre.
Approach Topography	Level road over bridge. Steps lead down to Mill Park from where earlier structural features of bridge can be viewed, with wheelchair access from mill apartment complex side.
Approach Surface	Pavement, concrete, tarmac
Approach Safety	Pedestrian crossing on Main St., but not on any of minor streets. No barrier at riverside.
Approach Width	pathways c.1m wide.
	Approach Gate width
Gate type	

<i>Site Topography</i>	Bridge itself level.
<i>Site Paths</i>	
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	open riverside at Mill Park from where bridge can be viewed. This is only accessed via steps or combination of pathway/steps.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Modified.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Seating in town and in Mill Park
<i>Notes</i>	

RMP Ref: LF-	027-003005	Monument	Mill - Unclassified
Location/ Townland	Ballymahon	National Grid Ref:	<input type="text"/> E <input type="text"/> N
		RPS Ref	126
		National Monument Ref	<input type="text"/>
Description	Surviving mill structure has been converted into apartments. No evidence of millrace. Not considered an RMP on the www.archaeology.ie website.		
Ownership	Private	Date of Inspection	25/09/09
		Inspected By	SMcG
		Accessibility Rating	<input type="text"/>

Desk-Based Survey

Local Sources Information	Longford Library Local History Reading Room: An industrial archaeological survey of the Ballymahon mills complex, County Longford: Colin Rynne, for Frank Kelly Construction Ltd., 1999.
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	<input type="text"/>
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	Excavations.ie report on archaeological excavations: http://www.excavations.ie/Pages/Details.php?Year=&County=Longford&id=538
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	<input type="text"/>
Visibility	Visible from Main Street in town
Intervisibility	Intervisible with Graveyard (LF027-003002), Historic town (LF027-003006) and Bridge (LF027-003004)
Road Access	Accessed from Main St in Ballymahon
Parking	Street parking available in town.
Public Transport	Public transport to town centre
Approach Topography	Steps lead down to Mill Park from where exterior of renovated mill building can be viewed, with wheelchair access from mill apartment complex side.
Approach Surface	Pavement, concrete, tarmac
Approach Safety	Pedestrian crossing on Main St., but not on any of minor streets. No barrier at riverside.
Approach Width	pathways c.1m wide. Approach Gate width <input type="text"/>

<i>Gate type</i>	
<i>Site Topography</i>	No access to mill complex as private grounds.
<i>Site Paths</i>	Paths in the Mill Park
<i>Paths Surfacing</i>	Concrete
<i>Paths Width</i>	c.1m
<i>Hazards</i>	No barrier at riverside in Mill Park.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Renovated
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input checked="" type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Seating in Mill Park.
<i>Notes</i>	

RMP Ref: LF-	027-003006	Monument	Historic Town		
Location/ Townland	Ballymahon		National Grid Ref:	215752	E
				256964	N
			RPS Ref		
			National Monument Ref		
Description	19th century town of Ballymahon.				
Ownership	Public	Date of Inspection	25/09/09	Inspected By	SMcG
				Accessibility Rating	A

Desk-Based Survey

Local Sources Information	Paddy Whelan (edited by Jimmy Casey), "Ballymahon and its people":published posthumously by his executors, Longford 2001.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?county=LF&name=&town=ballymahon&townland=&type=quick&page=1 http://www.buildingsofireland.ie/niah/search.jsp?county=LF&name=&town=ballymahon&townland=&type=quick&page=2 http://www.buildingsofireland.ie/niah/search.jsp?county=LF&name=&town=ballymahon&townland=&type=quick&page=3
Internet Directions	

Field Survey:

Road Signs	Roadsigns for Ballymahon town
Site Signs	Large Tourist Information Board
Visibility	
Intervisibility	Intervisible with Graveyard (LF027-003002), Bridge (LF027-003004) and Mill (LF027-003005)
Road Access	Main road extends through town.
Parking	Street parking available in town.
Public Transport	Public transport to town centre
Approach Topography	Fairly level
Approach Surface	Tarmac

Approach Safety	
Approach Width	>1.8m
Gate type	
Approach Gate width	
Site Topography	Fairly level in town centre
Site Paths	Footpaths along road throughout town
Paths Surfacing	Concrete paving
Paths Width	>800mm
Hazards	Pedestrian crossing on Main Street but not at minor road junctions.
Maintenance	Well maintained
Condition of Monument	Good. Positioning of Information Board may not be optimal, as partially blocked at present.
Child friendly <input type="checkbox"/>	On-site Information <input checked="" type="checkbox"/> On-site Staff <input type="checkbox"/> On-site Seating <input checked="" type="checkbox"/> On-site Toilets <input type="checkbox"/>
On-site facilities	Seating located in town centre and in Mill Park.
Notes	

RMP Ref: LF-	027-036	Monument	Ritual Site - Holy Well
Location/ Townland	Forgney	National Grid Ref:	219640 <i>E</i> 254717 <i>N</i>
		RPS Ref	
		National Monument Ref	
Description	St. Patrick's Well. Natural spring well, now overgrown, with a field ditch running off from one side. No stone facing. Located in a small triangular field.		
Ownership	Private	Date of Inspection	25/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Not very visible.
Intervisibility	
Road Access	Accessed via small laneway at end of farm access lane
Parking	
Public Transport	
Approach Topography	Uneven levels on laneways, very uneven, marshy ground in field
Approach Surface	Earth/stone and grass.
Approach Safety	Uneven, marshy ground creates uncertain footing.
Approach Width	>1.8m
	Approach Gate width
Gate type	Double field gate at access point to small laneway

<i>Site Topography</i>	Marshy ground and field ditch in immediate vicinity of well.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Overgrowth, uneven and marshy ground.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Overgrown - not readily identifiable as a holy well.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	027-037001	Monument	Church
Location/ Townland	Forgney	National Grid Ref:	219945 E 254601 N
		RPS Ref	
		National Monument Ref	
Description	No visible upstanding remains. Vicinity of monument is very heavily overgrown.		
Ownership	Public	Date of Inspection	25/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Circular, tree-ringed enclosure visible on approach through field. Church not visible.
Intervisibility	
Road Access	Accessed via right-of-way through field from laneway.
Parking	No designated parking
Public Transport	
Approach Topography	Ground slopes downhill and is generally slightly uneven in field
Approach Surface	Grass
Approach Safety	Cattle grazing in field. Right-of-way not fenced off.
Approach Width	
	Approach Gate width >800mm
Gate type	Gate is rusting and partially blocked by metal shed. A stile crosses the stone wall to one side of the

	gate.
<i>Site Topography</i>	Ground is generally uneven and heavily overgrown.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Overgrowth makes footing uncertain and hides trip hazards.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Not visible.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	027-037002	Monument	Graveyard
Location/ Townland	Forgney	National Grid Ref:	219940 E 254600 N
		RPS Ref	
		National Monument Ref	
Description	Situated in large circular enclosure, with external ditch and encircled by trees. Central area of enclosure is raised and it is here all but one of the visible gravestones are located. Most gravestones appear unstable due to uneven ground. The most recent identifiable gravestone is apart from the others and is date 1898. Area of graveyard heavily overgrown.		
Ownership	Public	Date of Inspection	25/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	#57 Forgney (Old) Graveyard, Forgney. Not wheelchair accessible. No designated parking. Private access (through farmland) (Lennon 2005). Longford Graveyard Survey is available on-line at http://www.longfordlibrary.ie/lib_her_inside.aspx?id=16836 .
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Circular, tree-ringed enclosure visible on approach through field.
Intervisibility	
Road Access	Accessed via right-of-way through field from laneway.
Parking	No designated parking
Public Transport	
Approach Topography	Ground slopes downhill and is generally slightly uneven in field
Approach Surface	Grass
Approach Safety	Cattle grazing in field. Right-of-way not fenced off.
Approach Width	
	Approach Gate width >800mm

<i>Gate type</i>	Gate is rusting and partially blocked by metal shed. A stile crosses the stone wall to one side of the gate.
<i>Site Topography</i>	Ground is generally uneven and heavily overgrown.
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Overgrowth makes footing uncertain and hides trip hazards.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Heavily overgrown
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None
<i>Notes</i>	

RMP Ref: LF-	027-045	Monument	Bridge (17th century)
Location/ Townland	Newcastle	National Grid Ref:	218214 E 256899 N
		RPS Ref	
		National Monument Ref	
Description	Masonry bridge crossing the river Inny at Newcastle Demesne. Three main arches on the bridge cross the Inny, with a smaller arch over a former millrace at one end. Some renovation work obvious on bridge. Steps lead down to water at one side of bridge.		
Ownership	Public	Date of Inspection	25/09/09
		Inspected By	SMcG
		Accessibility Rating	A

Desk-Based Survey

Local Sources Information	
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13402707
Internet Directions	

Field Survey:

Road Signs	
Site Signs	
Visibility	Visible along road
Intervisibility	Intervisible with Newcastle House (LF027-008)
Road Access	Located along public road
Parking	Adjacent public carpark of Newcastle Wood, which is designated wheelchair accessible. Bridge can be viewed from wood nature walk.
Public Transport	
Approach Topography	Carpark area is level
Approach Surface	Tarmac, gravel
Approach Safety	No footpath along road over bridge.
Approach Width	>1.8m
Approach Gate width	

<i>Gate type</i>	
<i>Site Topography</i>	Slope on bridge itself. Level ground in carpark.
<i>Site Paths</i>	Road extends over bridge
<i>Paths Surfacing</i>	Tarmac, gravel (carpark, woodland)
<i>Paths Width</i>	>1.8m
<i>Hazards</i>	No footpath on bridge. Steps down to unfenced riverside.
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input checked="" type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	Seating present in carpark. No lighting present.
<i>Notes</i>	

RMP Ref: LF-	LIHS-009-025	Monument	Smithy
Location/ Townland	Clooncoose (Granard By.)		National Grid Ref: 224023 <i>E</i> 280747 <i>N</i>
		RPS Ref	145
		National Monument Ref	
Description	MacEoin's Forge. Not an RMP, but included as important in local and industrial heritage. Exterior access only. Interior of forge with features preserved but cannot be accessed.		
Ownership	Public	Date of Inspection	22/09/09
		Inspected By	SMcG
		Accessibility Rating	B

Desk-Based Survey

Local Sources Information	Included on Tourist Information Board in Ballinalee.
Local Sources Directions	
Graveyard Survey	
National Sources Information	
National Sources Directions	
International Guidebooks	
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13400905
Internet Directions	

Field Survey:

Road Signs	
Site Signs	Small plaque on building and on remains of house adjacent to the forge
Visibility	Visible from road
Intervisibility	
Road Access	Located at roadside
Parking	No designated parking. Roadside parking is possible
Public Transport	Local bus routes between Longford town and Granard pass by.
Approach Topography	Level approach from road
Approach Surface	Tarmac, gravel
Approach Safety	No footpath on road
Approach Width	
	Approach Gate width >800mm
Gate type	Open gateways in wall surrounding house

<i>Site Topography</i>	Fairly level.
<i>Site Paths</i>	Level pathway around building and garden to rear. Gravel also extends to remains of nearby house.
<i>Paths Surfacing</i>	Gravel, with grass in garden.
<i>Paths Width</i>	>1.8m
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	Well maintained
<i>Condition of Monument</i>	Very good
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	LIHS-011-00701	Monument	Ballywillin Train Station
Location/ Townland	Ballywillin	National Grid Ref:	<input type="text"/> E <input type="text"/> N
		RPS Ref	170 - 172
		National Monument Ref	<input type="text"/>
Description	Former railway station, with railway platforms still in-situ. Railway line has been removed. Now in private ownership. Also present are an outbuilding, a former goods shed, a water tower and a railway signal box.		
Ownership	Private	Date of Inspection	17/09/09
		Inspected By	SMcG
		Accessibility Rating	D

Desk-Based Survey

Local Sources Information	<input type="text"/>
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	<input type="text"/>
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?county=LF&name=&town=&townland=0138&type=quick&page=1
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	Original station signs still present
Visibility	Only visible from approach lane
Intervisibility	<input type="text"/>
Road Access	No through road. Private access road only
Parking	No designated parking
Public Transport	<input type="text"/>
Approach Topography	Level
Approach Surface	Grass, gravel
Approach Safety	No visible hazards
Approach Width	>1.8m
	Approach Gate width <input type="text"/>
Gate type	No gate

<i>Site Topography</i>	Generally level, but with slope down from Goods Shed to former tracks - no railing present
<i>Site Paths</i>	
<i>Paths Surfacing</i>	Grass, gravel surface; platforms are paved.
<i>Paths Width</i>	>1.8m
<i>Hazards</i>	No visible hazards
<i>Maintenance</i>	Well maintained as private house
<i>Condition of Monument</i>	Good.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	LIHS-013-002	Monument	Canal Complex
Location/ Townland	Cloondara (aka Clondra)	National Grid Ref:	<input type="text"/> E <input type="text"/> N
		RPS Ref	186, 187
		National Monument Ref	<input type="text"/>
Description	Canal Complex at Clondra/Cloondara - recently refurbished.		
Ownership	<input type="text"/>	Date of Inspection	<input type="text"/>
		Inspected By	<input type="text"/>
		Accessibility Rating	<input type="text"/>

Desk-Based Survey

Local Sources Information	Links the Royal Canal harbour at Clondra to Lough Ree, via the Camlin River.
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	Information about 'Shannon Harbour' at Clondra included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09.
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided. National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13307006 and http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13307007
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	<input type="text"/>
Visibility	Visible from Clondra to Termonbarry road.
Intervisibility	<input type="text"/>
Road Access	<input type="text"/>
Parking	<input type="text"/>
Public Transport	Accessible by boat from Royal Canal and River Inny.
Approach Topography	<input type="text"/>
Approach Surface	<input type="text"/>

<i>Approach Safety</i>		
<i>Approach Width</i>		<i>Approach Gate width</i>
<i>Gate type</i>		
<i>Site Topography</i>		
<i>Site Paths</i>		
<i>Paths Surfacing</i>		
<i>Paths Width</i>		
<i>Hazards</i>		
<i>Maintenance</i>		
<i>Condition of Monument</i>		
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>		
<i>Notes</i>		

RMP Ref: LF-	LIHS-013-003__	Monument	Various - Clondra
Location/ Townland	Cloondara (aka Clondra), Glebe		National Grid Ref: <input type="text"/> E <input type="text"/> N
		RPS Ref	<input type="text"/>
		National Monument Ref	<input type="text"/>
Description	Structures associated with the canal in Clondra, currently undergoing renovation. Including a mill, currently being converted into apartments; harbour lock; dry dock; smithy (in ruins); possible mill building (ruined); post-box and Lock-keeper's house. Mill is a protected structure ; Lock-keeper's house is a protected structure		
Ownership	<input type="text"/>	Date of Inspection	<input type="text"/>
		Inspected By	<input type="text"/>
		Accessibility Rating	<input type="text"/>

Desk-Based Survey

Local Sources Information	<input type="text"/>
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	Information about 'Shannon Harbour' at Clondra included in 'Ireland's Lakelands', Irish Times supplement, 30/09/09.
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	Included in short list of places of interest on http://www.countylongford.com/longford_heritage_museum.htm , with links to connected entry in http://www.goireland.com . A short description is given with some historical information. No information regarding accessibility is provided. National Inventory of Architectural Heritage: Lock-keeper's cottage, Lock 46: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13307016 Richmond Harbour: http://www.buildingsofireland.ie/niah/search.jsp?county=LF&name=richmond+harbour&town=&townland=&type=quick&page=1 Former Shannon Navigation Office (Cloondara/Camlin Canal): http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13307004 Richmond Mill: www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13307009 ; www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13307010 ; www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13307011 ; www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13307012
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	Signs erected in 2011 by Waterways Ireland.
Visibility	<input type="text"/>
Intervisibility	<input type="text"/>
Road Access	From Clondra (Cloondara) village.

Parking	Parking at Richmond Harbour.	
Public Transport		
Approach Topography		
Approach Surface		
Approach Safety		
Approach Width		Approach Gate width
Gate type		
Site Topography		
Site Paths		
Paths Surfacing		
Paths Width		
Hazards		
Maintenance		
Condition of Monument		
Child friendly <input type="checkbox"/>	On-site Information <input type="checkbox"/>	On-site Staff <input type="checkbox"/>
	On-site Seating <input type="checkbox"/>	On-site Toilets <input type="checkbox"/>
On-site facilities		
Notes		

RMP Ref: LF-	LIHS-018-003	Monument	Water Mill - Corn
Location/ Townland	Grillagh	National Grid Ref:	<input type="text"/> E <input type="text"/> N
		RPS Ref	<input type="text"/>
		National Monument Ref	<input type="text"/>
Description	19th Century mill - continued in use until 1950s. Still contains much of inner workings of mill, including mill wheel, millstones, sorting/sifting trays etc. Building is roofed but stability of interior is uncertain. 2 kilns are located in an adjacent building, with furnaces intact and most of kiln tile floors. Mill race is also identifiable.		
Ownership	Private	Date of Inspection	20/10/09
		Inspected By	SMcG
		Accessibility Rating	B/C

Desk-Based Survey

Local Sources Information	Included on Tourist Information Board in Killashee.
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	<input type="text"/>
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	National Inventory of Architectural Heritage: http://www.buildingsofireland.ie/niah/search.jsp?type=record&county=LF&regno=13401810
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	<input type="text"/>
Visibility	Visible at side of minor road
Intervisibility	<input type="text"/>
Road Access	Located beside local road
Parking	No designated parking, but there is widened space for 1-2 cars on opposite side of road.
Public Transport	<input type="text"/>
Approach Topography	Fairly level
Approach Surface	Grassed over laneway
Approach Safety	No pedestrian crossing on road or no footpath. Some farm machinery present.
Approach Width	>1.8m
	Approach Gate width <input type="text"/>
Gate type	No gate.

<i>Site Topography</i>	Building has narrow wooden stairs and narrow doorways
<i>Site Paths</i>	Wooden floorboards in interior - uncertain how stable floors are
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Presence of farm machinery. Narrow doorways and stairs present.
<i>Maintenance</i>	Uncertain
<i>Condition of Monument</i>	Currently in use as farm outbuildings. Original features still present in interior.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/> <i>On-site Staff</i> <input type="checkbox"/> <i>On-site Seating</i> <input type="checkbox"/> <i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	

RMP Ref: LF-	LIHS-027-008	Monument	Woollen Factory
Location/ Townland	Ballymulvey	National Grid Ref:	<input type="text"/> E <input type="text"/> N
		RPS Ref	<input type="text"/>
		National Monument Ref	<input type="text"/>
Description	Buildings set inside area enclosed by a large brick wall. The associated millrace is impressive with wheel pit evident and fixture relating to the wheel, although not the wheel itself. The roof is absent from half of the main building, while the other half extends to 1st floor level. There is a bridge between buildings over the millrace but this is partially collapsed. Sometimes used as farm buildings.		
Ownership	Private	Date of Inspection	25/09/09
		Inspected By	SMcG
		Accessibility Rating	C

Desk-Based Survey

Local Sources Information	<input type="text"/>
Local Sources Directions	<input type="text"/>
Graveyard Survey	<input type="text"/>
National Sources Information	<input type="text"/>
National Sources Directions	<input type="text"/>
International Guidebooks	<input type="text"/>
Internet Information	<input type="text"/>
Internet Directions	<input type="text"/>

Field Survey:

Road Signs	<input type="text"/>
Site Signs	<input type="text"/>
Visibility	Clearly visible at side of road
Intervisibility	<input type="text"/>
Road Access	Beside road.
Parking	Parking may be possible at widened area at roadside, opposite factory complex
Public Transport	<input type="text"/>
Approach Topography	Level laneway from main road to buildings
Approach Surface	Grassed-over laneway
Approach Safety	No pedestrian crossings. Cattle grazing in field.
Approach Width	>1.8m
Approach Gate width	>800mm

<i>Gate type</i>	Double gate
<i>Site Topography</i>	Generally uneven ground
<i>Site Paths</i>	None
<i>Paths Surfacing</i>	
<i>Paths Width</i>	
<i>Hazards</i>	Building may not be stable. Bridge over millrace appears unstable.
<i>Maintenance</i>	Not maintained
<i>Condition of Monument</i>	Ruined, overgrown.
<i>Child friendly</i> <input type="checkbox"/>	<i>On-site Information</i> <input type="checkbox"/>
	<i>On-site Staff</i> <input type="checkbox"/>
	<i>On-site Seating</i> <input type="checkbox"/>
	<i>On-site Toilets</i> <input type="checkbox"/>
<i>On-site facilities</i>	None.
<i>Notes</i>	